
















NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID4\_N/A  
\_30\_1000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID4\_N/A  
\_1000\_3000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID4\_N/A  
\_3000\_12000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID4\_N/A  
\_12000\_20000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID5\_N/A  
\_0.009\_0.15\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID5\_N/A  
\_0.15\_30\_#1





NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID6\_N/A  
\_0.009\_0.15\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID6\_N/A  
\_0.15\_30\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID6\_N/A  
\_30\_1000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID6\_N/A  
\_1000\_3000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID6\_N/A  
\_3000\_12000\_#1NTNV\_N78-3450-3550\_PC2\_30\_60\_H\_TID6\_N/A  
\_12000\_20000\_#1

















NTNV\_N78-3450-3550\_PC2\_30\_80\_L\_TID6\_N/A  
\_0.009\_0.15\_#1

NTNV\_N78-3450-3550\_PC2\_30\_80\_L\_TID6\_N/A  
\_0.15\_30\_#1

NTNV\_N78-3450-3550\_PC2\_30\_80\_L\_TID6\_N/A  
\_30\_1000\_#1

NTNV\_N78-3450-3550\_PC2\_30\_80\_L\_TID6\_N/A  
\_1000\_3000\_#1

