



11AC20SISO-Ant1-5260



11AC20SISO-Ant1-5300

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5320




11AC20SISO-Ant1-5500

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5580



11AC20SISO-Ant1-5700


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5745



11AC20SISO-Ant1-5785

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5825



11AC40SISO-Ant1-5190

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5230



11AC40SISO-Ant1-5270

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5310



11AC40SISO-Ant1-5510

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5550



11AC40SISO-Ant1-5670

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5755



11AC40SISO-Ant1-5795

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC80SISO-Ant1-5210




11AC80SISO-Ant1-5290

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC80SISO-Ant1-5530



11AC80SISO-Ant1-5775

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix A2: 99% Occupied Bandwidth

Test Result

Test Mode	Antenna	Frequency[MHz]	OCB [MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
11A	Ant1	5180	16.963	5171.5467	5188.5097	---	---
11A	Ant1	5220	16.933	5211.5298	5228.4628	---	---
11A	Ant1	5240	16.938	5231.5037	5248.4417	---	---
11A	Ant1	5260	16.982	5251.4855	5268.4675	---	---
11A	Ant1	5300	16.923	5291.5352	5308.4582	---	---
11A	Ant1	5320	16.878	5311.5619	5328.4399	---	---
11A	Ant1	5500	16.916	5491.5603	5508.4763	---	---
11A	Ant1	5580	16.923	5571.5467	5588.4697	---	---
11A	Ant1	5700	16.910	5691.5522	5708.4622	---	---
11A	Ant1	5745	16.949	5736.4887	5753.4377	---	---
11A	Ant1	5785	16.941	5776.5194	5793.4604	---	---
11A	Ant1	5825	16.862	5816.5752	5833.4372	---	---
11N20SISO	Ant1	5180	17.816	5171.1001	5188.9161	---	---
11N20SISO	Ant1	5220	17.806	5211.0919	5228.8979	---	---
11N20SISO	Ant1	5240	17.817	5231.0909	5248.9079	---	---
11N20SISO	Ant1	5260	17.854	5251.0582	5268.9122	---	---
11N20SISO	Ant1	5300	17.850	5291.0920	5308.9420	---	---
11N20SISO	Ant1	5320	17.855	5311.0939	5328.9489	---	---
11N20SISO	Ant1	5500	17.842	5491.1157	5508.9577	---	---
11N20SISO	Ant1	5580	17.837	5571.1056	5588.9426	---	---
11N20SISO	Ant1	5700	17.827	5691.1032	5708.9302	---	---
11N20SISO	Ant1	5745	17.806	5736.0514	5753.8574	---	---
11N20SISO	Ant1	5785	17.810	5776.1074	5793.9174	---	---
11N20SISO	Ant1	5825	17.827	5816.1236	5833.9506	---	---
11N40SISO	Ant1	5190	36.371	5171.8734	5208.2444	---	---
11N40SISO	Ant1	5230	36.312	5211.8399	5248.1519	---	---
11N40SISO	Ant1	5270	36.334	5251.7658	5288.0998	---	---
11N40SISO	Ant1	5310	36.344	5291.8427	5328.1867	---	---
11N40SISO	Ant1	5510	36.297	5491.8833	5528.1803	---	---
11N40SISO	Ant1	5550	36.351	5531.8096	5568.1606	---	---
11N40SISO	Ant1	5670	36.402	5651.8476	5688.2496	---	---
11N40SISO	Ant1	5755	36.332	5736.7289	5773.0609	---	---
11N40SISO	Ant1	5795	36.391	5776.8666	5813.2576	---	---
11AC20SISO	Ant1	5180	17.808	5171.1126	5188.9206	---	---
11AC20SISO	Ant1	5220	17.838	5211.0840	5228.9220	---	---
11AC20SISO	Ant1	5240	17.853	5231.0775	5248.9305	---	---
11AC20SISO	Ant1	5260	17.829	5251.0764	5268.9054	---	---


11AC20SISO	Ant1	5300	17.828	5291.0922	5308.9202	---	---
11AC20SISO	Ant1	5320	17.849	5311.0895	5328.9385	---	---
11AC20SISO	Ant1	5500	17.827	5491.1044	5508.9314	---	---
11AC20SISO	Ant1	5580	17.817	5571.1284	5588.9454	---	---
11AC20SISO	Ant1	5700	17.835	5691.1021	5708.9371	---	---
11AC20SISO	Ant1	5745	17.845	5736.0589	5753.9039	---	---
11AC20SISO	Ant1	5785	17.850	5776.0606	5793.9106	---	---
11AC20SISO	Ant1	5825	17.867	5816.1218	5833.9888	---	---
11AC40SISO	Ant1	5190	36.378	5171.8927	5208.2707	---	---
11AC40SISO	Ant1	5230	36.331	5211.8286	5248.1596	---	---
11AC40SISO	Ant1	5270	36.378	5251.7849	5288.1629	---	---
11AC40SISO	Ant1	5310	36.557	5291.6716	5328.2286	---	---
11AC40SISO	Ant1	5510	36.318	5491.8611	5528.1791	---	---
11AC40SISO	Ant1	5550	36.434	5531.7792	5568.2132	---	---
11AC40SISO	Ant1	5670	36.404	5651.8590	5688.2630	---	---
11AC40SISO	Ant1	5755	36.374	5736.7449	5773.1189	---	---
11AC40SISO	Ant1	5795	36.326	5776.8405	5813.1665	---	---
11AC80SISO	Ant1	5210	76.014	5171.9643	5247.9783	---	---
11AC80SISO	Ant1	5290	76.347	5251.7515	5328.0985	---	---
11AC80SISO	Ant1	5530	76.144	5492.0126	5568.1566	---	---
11AC80SISO	Ant1	5775	76.302	5736.7400	5813.0420	---	---

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Test Graphs



11A-Ant1-5180




11A-Ant1-5220


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5240





11A-Ant1-5260

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





11A-Ant1-5500




11A-Ant1-5580


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5700




11A-Ant1-5745


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5785




11A-Ant1-5825

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20SISO-Ant1-5180




11N20SISO-Ant1-5220

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20SISO-Ant1-5240




11N20SISO-Ant1-5260

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20SISO-Ant1-5300



11N20SISO-Ant1-5320

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com