

Nov. 30, 2022

Attestation for signal booster: FCC ID: 2A9A8-FB20221001

Each Signal Booster certificated under FCC ID: 2A9A8-FB20221001 is manufactured and

individually tested to ensure FCC compliance:

(1) Licensee consent for Fixed consumer booster has been obtained (consent be made available upon FCC/TCB request)

(2) NPS and other compliance/safeguard features have been implemented

(3) NPS and other compliance/safeguard features are defaulted to "ON" configuration (in operation)

(4) NPS and other compliance/safeguard features cannot be field reconfigured, disabled or removed

(5) This Consumer booster is not user programmable, does not need fine tuning or adjustment, does not require professional installation.

(6) Future software upgrade will not cause non-compliance.

Yours sincerely,

Heng Zhang

Signature: 