






11AC80SISO_Ant1_5610





11AC80SISO_Ant1_5690






99% Bandwidth







11A Ant0 5280



11A Ant0 5320




11A Ant0 5500




Date: 3 FEB 2023 17:16:12

11A Ant0 5580




Date: 3 FEB 2023 17:19:00

11A Ant0 5700




Date: 3 FEB 2023 17:21:05

11A Ant0 5720




Date: 3 FEB 2023 17:24:21

11A Ant0 5745




Date: 3 FEB 2023 17:27:08

11A Ant0 5785




Date: 3 FEB 2023 17:29:21

11A Ant0 5825




Date: 3.FEB.2023 17:32:12

11N20SISO_Ant0_5180




Date: 3.FEB.2023 17:34:37

11N20SISO_Ant0_5200




Date: 3.FEB.2023 17:36:27

11N20SISO_Ant0_5240




Date: 3.FEB.2023 17:38:38

11N20SISO_Ant0_5260




Date: 3.FEB.2023 17:40:27

11N20SISO_Ant0_5280




Date: 3.FEB.2023 17:43:43

11N20SISO_Ant0_5320




Date: 3 FEB 2023 17:46:32

11N20SISO_Ant0_5500




Date: 3 FEB 2023 17:48:34

11N20SISO_Ant0_5580




Date: 3 FEB 2023 17:51:09

11N20SISO_Ant0_5700




Date: 3 FEB 2023 17:52:49

11N20SISO_Ant0_5720




Date: 4 FEB 2023 09:31:41

11N20SISO_Ant0_5745




Date: 4 FEB 2023 09:34:30

11N20SISO_Ant0_5785




Date: 4 FEB 2023 09:36:48

11N20SISO_Ant0_5825




Date: 4 FEB 2023 09:38:47

11N40SISO_Ant0_5190




Date: 4 FEB 2023 09:41:00

11N40SISO_Ant0_5230




Date: 4 FEB 2023 09:43:06

11N40SISO_Ant0_5270



Date: 4 FEB 2023 09:44:46

11N40SISO_Ant0_5310



Date: 4 FEB 2023 09:46:28

11N40SISO_Ant0_5510



Date: 4 FEB 2023 09:48:20

11N40SISO_Ant0_5550



Date: 4 FEB 2023 09:50:20

11N40SISO_Ant0_5670




Date: 4 FEB 2023 09:52:02

11N40SISO_Ant0_5710




Date: 4 FEB 2023 09:59:26

11N40SISO Ant0 5755




Date: 4 FEB 2023 09:56:45

11N40SISO Ant0 5795




Date: 4 FEB 2023 10:02:27

11AC20SISO Ant0 5180




Date: 4 FEB 2023 10:05:57

11AC20SISO_Ant0_5200




Date: 4 FEB 2023 10:07:48

11AC20SISO_Ant0_5240




Date: 4 FEB 2023 10:09:25


11AC20SISO_Ant0_5260




11AC20SISO_Ant0_5280



11AC20SISO_Ant0_5320




11AC20SISO_Ant0_5500




Date: 4 FEB 2023 10:16:18

11AC20SISO_Ant0_5580




Date: 4 FEB 2023 10:18:24

11AC20SISO_Ant0_5700




Date: 4 FEB 2023 10:20:03

11AC20SISO_Ant0_5720




Date: 4 FEB 2023 10:21:54

11AC20SISO_Ant0_5745




Date: 4 FEB 2023 10:24:39

11AC20SISO_Ant0_5785




Date: 4 FEB 2023 10:27:03

11AC20SISO_Ant0_5825




Date: 4 FEB 2023 10:29:12

11AC40SISO_Ant0_5190



Date: 4 FEB 2023 10:31:40

11AC40SISO_Ant0_5230




Date: 4 FEB 2023 10:33:30

11AC40SISO_Ant0_5270



11AC40SISO_Ant0_5310



11AC40SISO_Ant0_5510



11AC40SISO_Ant0_5550



Date: 4 FEB 2023 10:40:36

11AC40SISO_Ant0_5670




Date: 4 FEB 2023 10:42:18

11AC40SISO_Ant0_5710




Date: 4 FEB 2023 10:44:14


11AC40SISO_Ant0_5755



11AC40SISO Ant0 5795




11AC80SISO Ant0 5210




11AC80SISO Ant0 5290




11AC80SISO Ant0 5530



11AC80SISO Ant0 5610




11AC80SISO Ant0 5690




Date: 4 FEB 2023 10:59:01

11AC80SISO Ant0 5775




Date: 4 FEB 2023 11:01:42

11A Ant1 5180




Date: 4 FEB 2023 11:52:48

11A Ant1 5200




Date: 4 FEB 2023 11:54:45

11A Ant1 5240




Date: 4 FEB 2023 11:57:34

11A Ant1 5260




Date: 4 FEB 2023 11:59:17


11A Ant1 5280




11A Ant1 5320



11A Ant1 5500




11A Ant1 5580




Date: 4 FEB 2023 12:06:50

11A Ant1 5700




Date: 4 FEB 2023 12:08:34

11A Ant1 5720




Date: 4 FEB 2023 12:10:26

11A Ant1 5745




Date: 4 FEB 2023 12:12:51

11A Ant1 5785




Date: 4 FEB 2023 12:37:21

11A Ant1 5825




Date: 4 FEB 2023 12:47:28

11N20SISO Ant1 5180




Date: 4 FEB 2023 12:55:24

11N20SISO_Ant1_5200




Date: 4 FEB 2023 12:57:15

11N20SISO_Ant1_5240




Date: 4 FEB 2023 12:58:55

11N20SISO_Ant1_5260




Date: 4 FEB 2023 13:01:54

11N20SISO_Ant1_5280




Date: 4 FEB 2023 13:04:59

11N20SISO_Ant1_5320




Date: 4 FEB 2023 13:15:48

11N20SISO_Ant1_5500




Date: 4 FEB 2023 13:17:57

11N20SISO_Ant1_5580




Date: 4 FEB 2023 13:19:52

11N20SISO_Ant1_5700




Date: 4 FEB 2023 13:23:09

11N20SISO_Ant1_5720




Date: 4 FEB 2023 13:25:01

11N20SISO_Ant1_5745




Date: 4 FEB 2023 13:27:23

11N20SISO_Ant1_5785




Date: 4 FEB 2023 13:36:49

11N20SISO_Ant1_5825




Date: 4 FEB 2023 13:38:43

11N40SISO_Ant1_5190



Date: 4 FEB 2023 13:40:44

11N40SISO_Ant1_5230



Date: 4 FEB 2023 13:42:38

11N40SISO_Ant1_5270




Date: 4 FEB 2023 13:44:30

11N40SISO_Ant1_5310




Date: 4 FEB 2023 13:46:11

11N40SISO_Ant1_5510




Date: 4 FEB 2023 13:48:02

11N40SISO_Ant1_5550




Date: 4 FEB 2023 13:49:53

11N40SISO Ant1 5670




Date: 4 FEB 2023 13:51:55

11N40SISO Ant1 5710




Date: 4 FEB 2023 13:53:56

11N40SISO Ant1 5755




Date: 4 FEB 2023 13:56:39

11N40SISO Ant1 5795




Date: 4 FEB 2023 13:58:51

11AC20SISO Ant1 5180




Date: 4 FEB 2023 14:01:00

11AC20SISO Ant1 5200




Date: 4 FEB 2023 14:03:20

11AC20SISO_Ant1_5240




Date: 4 FEB 2023 14:05:02

11AC20SISO_Ant1_5260




Date: 4 FEB 2023 14:06:36

11AC20SISO_Ant1_5280




Date: 4 FEB 2023 14:08:13

11AC20SISO_Ant1_5320




Date: 4 FEB 2023 14:09:49

11AC20SISO_Ant1_5500




Date: 4 FEB 2023 14:11:39

11AC20SISO_Ant1_5580




Date: 4 FEB 2023 14:13:34

11AC20SISO_Ant1_5700




Date: 4 FEB 2023 14:15:14

11AC20SISO_Ant1_5720




Date: 4 FEB 2023 14:17:05


11AC20SISO_Ant1_5745




11AC20SISO_Ant1_5785




11AC20SISO_Ant1_5825




11AC40SISO_Ant1_5190




11AC40SISO_Ant1_5230




11AC40SISO_Ant1_5270




11AC40SISO_Ant1_5310




11AC40SISO_Ant1_5510



11AC40SISO_Ant1_5550




11AC40SISO_Ant1_5670




Date: 4 FEB 2023 14:37:24

11AC40SISO_Ant1_5710




Date: 4 FEB 2023 14:39:57

11AC40SISO_Ant1_5755




Date: 4 FEB 2023 14:42:41

11AC40SISO_Ant1_5795




Date: 4 FEB 2023 14:45:12

11AC80SISO_Ant1_5210




Date: 4 FEB 2023 14:47:50

11AC80SISO_Ant1_5290




Date: 4 FEB 2023 14:49:45

11AC80SISO_Ant1_5530




Date: 4 FEB 2023 14:52:29

11AC80SISO_Ant1_5610




Date: 4 FEB 2023 14:54:21

11AC80SISO_Ant1_5690



Date: 4 FEB 2023 14:56:15


11AC80SISO_Ant1_5775



Date: 4 FEB 2023 14:58:58


6dB Bandwidth:

11A Ant0 5745




Date: 3 FEB 2023 17:26:56

11A Ant0 5785




Date: 3 FEB 2023 17:29:09


11A Ant0 5825




11N20SISO_Ant0_5745




11N20SISO_Ant0_5785




11N20SISO_Ant0_5825




11N40SISO_Ant0_5755




11N40SISO_Ant0_5795




11AC20SISO_Ant0_5745




11AC20SISO Ant0 5785




11AC20SISO Ant0 5825




11AC40SISO Ant0 5755




11AC40SISO Ant0 5795




11AC80SISO Ant0 5775




11A Ant1 5745



11A_Ant1_5785



11A_Ant1_5825



11N20SISO_Ant1_5745