


TEST GRAPHS





BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 1M Ant1 2440 0~Reference




BLE 1M Ant1 2440 30~1000




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 1M Ant1 2440 1000~26500



BLE 1M Ant1 2480 0~Reference




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 1M Ant1 2480 30~1000




BLE 1M Ant1 2480 1000~26500



BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 2M Ant1 2404 0~Reference




BLE 2M Ant1 2404 30~1000




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 2M Ant1 2404 1000~26500



BLE 2M Ant1 2440 0~Reference




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 2M Ant1 2440 30~1000



BLE 2M Ant1 2440 1000~26500



Reference No.: PSU-QSU2509050111RF02



BLE 2M Ant1 2478 0~Reference




BLE 2M Ant1 2478 30~1000




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 2M Ant1 2478 1000~26500




BLE 125K Ant1 2402 0~Reference



Reference No.: PSU-QSU2509050111RF02



BLE 125K Ant1 2402 30~1000



BLE 125K Ant1 2402 1000~26500



Reference No.: PSU-QSU2509050111RF02



BLE 125K Ant1 2440 0~Reference




BLE 125K Ant1 2440 30~1000




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE_125K_Ant1_2440_1000~26500




BLE_125K_Ant1_2480_0~Reference



Reference No.: PSU-QSU2509050111RF02



BLE 125K Ant1 2480 30~1000




BLE 125K Ant1 2480 1000~26500



BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE_500K_Ant1_2402_0~Reference




BLE_500K_Ant1_2402_30~1000




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE_500K_Ant1_2402_1000~26500




BLE_500K_Ant1_2440_0~Reference



Reference No.: PSU-QSU2509050111RF02



BLE_500K_Ant1_2440_30~1000




BLE_500K_Ant1_2440_1000~26500



BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE_500K_Ant1_2480_0~Reference




BLE_500K_Ant1_2480_30~1000




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 500K Ant1 2480 1000~26500



DUTY CYCLE TEST RESULT

TestMode	Antenna	Frequency[MHz]	ON Time [ms]	Period [ms]	Duty Cycle [%]	Duty Cycle Factor[dB]
BLE_1M	Ant1	2402	2.13	2.50	85.20	0.70
		2440	2.13	2.50	85.20	0.70
		2480	2.13	2.50	85.20	0.70
BLE_2M	Ant1	2404	1.08	1.88	57.45	2.41
		2440	1.08	1.88	57.45	2.41
		2478	1.08	1.88	57.45	2.41
BLE_125K	Ant1	2402	17.05	17.50	97.43	0.11
		2440	17.05	17.50	97.43	0.11
		2480	17.05	17.50	97.43	0.11
BLE_500K	Ant1	2402	4.56	5.01	91.02	0.41
		2440	4.56	5.01	91.02	0.41
		2480	4.56	5.01	91.02	0.41


TEST GRAPHS






BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 2M Ant1 2404




BLE 2M Ant1 2440




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 125K_Ant1_2440




BLE 125K_Ant1_2480




BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



BLE 500K_Ant1_2402




BLE 500K_Ant1_2440



BUREAU
VERITAS

Reference No.: PSU-QSU2509050111RF02



--END--