

CaDA

OPERATING FREQUENCY

2402MHz~2480 MHz

EIRP(MAX.)

-0.90dBm




Hereby, [DOUBLEEAGLE INDUSTRY (CHINA) LIMITED], declares that this [BUILDING BLOCK SERIES] is in compliance with the essential requirements and other relevant provisions of Directive 2014/53/EU.

The full test of the EU declaration of conformity is available at the following internet address: www.doubleeagle-group.com


C51306

RC
EAGLE
2.4G



**DUAL
MODE
CONTROL**

1




2








A1






A2








A3




A4








A5




A6







A7



A8




A8





A9



A10






A11



A12



A11



A10



A13



1



2



3




4

1:1




A14



A15







A16






A17







A18



A19







A20




A21



A 22




A23








A24



A25




A26



A27




A26



A22



A28






A29



1




2




3



A30




A31






A33




A34






A35







A36




A37



A38





A39






A40







A41



A42






A43






A44






A45





A46






A47







A48






A49





A50



1



2



3







A51



A52





A53







A54




A55








A56



A57




A58









A59




A60




A61






A62








A63







A64







A65







A66



A67






A68




A69



A70






A71



A72




A73



A74



A75




1:1

A76






A77







A78








A79







A80







A81







A82















A84











Hereby, DOUBLEEAGLE INDUSTRY (CHINA)LIMITED,
declares that this Building block series is in compliance with the
essential requirements and other relevant provisions of
Directive 2014/53/EU.

The full test of the EU declaration of conformity is available at the
following internet address: www.doubleeagle-group.com



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications.

However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.