

CaDA[®]

GT Sport Car

OPERATING FREQUENCY

2426MHz ~ 2474MHz

EIRP (MAX.)

-1.18dBm




Hereby, [DOUBLEEAGLE INDUSTRY (CHINA)LIMITED], declares that this [REMOTE CONTROL CAR SERIES] is in compliance with the essential requirements and other relevant provisions of Directive 2014/53/EU..


The full test of the EU declaration of conformity is available at the following internet address:www.doublele-group.com

C51307 | 427PCS


1




2







1




2









A1







A2





1




2




A3






A4







A5




1







2








A6










A7






A8







A9








A10







A11








A12








A13









A14






A15




A16











A18





A19







A20







A21





A22











A24







A25









A26





A27









A28






A29








A30





A31






A32







A33




1



2




3







A34





1





2




3





A35







A36




1



2




3









A37



1








2








A38










A40





A41







A42







A43







A44







A45




A46







A47




1



2






3






A48








A49





A50







A51








A52






A53







A54






A55




A56



1




2







A57






1





2




A58




A59






A60







A61







A62





A63







A64





A65








A66






A67







A68







A69







A70







A71





A72





A73








A74





1




2








3






A75







A76




1






2




3



A77






A78









A79









A80









A81















 x1
 JA10050006

 x2
 JA10100003

 x2
 JA10110001

 x1
 JA10660001

 x4
 JA30320005

 x2
 JA30330004

 x4
 JA30380005

 x3
 JA30410008

 x4
 JA30690007

 x2
 JB40150003

 x2
 JC00080003

 x1
 JC00100002


 x1
 JC00110002

 x2
 JF00330002

 x5
 JF10890001

 x4
 JF80720002

 x1
 JH00040001

 x1
 JH00070001

 x1
 JH00090001

 x4
 JH00110001

 x4
 JH00630001

 x4
 JH10180001

 x2
 JH10790001

 x8
 JH10790016

 x4
 JH20140001

 x30
 JH20150001

 x32
 JH20160001


 x72
 JH20250001

 x11
 JH21030001

 x3
 JH30210002

 x4
 JH40220009

 x2
 JH40230001

 x2
 JH40230002

 x11
 JH50010001

 x2
 JH50200002

 x2
 JH50260001

 x4
 JH50260007

 x19
 JH50320001

 x2
 JH50410001

 x4
 JH50440001

 x6
 JH50860001


 x3
 JH50860002

 x3
 JH60350001

 x2
 JH60390001

 x1
 JH60480003

 x4
 JH60850002

 x4
 JH90730004

 x2
 JJ40290001

 x1
 JJ40730002

 x2
 JJ50710008

 x5
 JJ60040001

 x5
 JJ60040007

 x2
 JJ60050007

 x2
 JJ60060001


 x2
 JJ60060007

 x3
 JJ60070001

 x2
 JJ60080002

 x2
 JJ60090002

 x2
 JJ60180004

 x1
 JJ60330001

 x2
 JJ60330008

 x2
 JJ60340001

 x5
 JJ60340006

 x3
 JJ60350004

 x4
 JJ60350005

x5
JJ60360003

x2
JJ60380006

x1
JJ60390001

x1
JJ60510003

x4
JJ60590002

x4
JJ70110002

x4
JJ70110007

x2
JJ70120002

x7
JJ70740003

x2
JM90420002

x1
JR30090001


x1
JR30110001

x2
JR30120003

x2
JR30250006

x2
JV3027

x1
JV8001



x1
JV9004

x1
JX10440002

x3
JX40350007

x3
JX40350008

x6
JX40350009

x2
JX40450001

x1
JX40450009

x2
JX40740001

x1
JX40930005

x8
JX41120003

x2
JX41680008

x5
JX41790002

x6
JX40350010

x2
JX40450002

x1
JX40450010

x1
JX40940005

x2
JX41690008

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.⁴⁾

Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.⁴⁾

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:⁴⁾

- Reorient or relocate the receiving antenna.⁴⁾
- Increase the separation between the equipment and receiver.⁴⁾
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.⁴⁾
- Consult the dealer or an experienced radio/TV technician for help.⁴⁾

Caution: Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.⁴⁾

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.⁴⁾

C51055



C51301



C51306

