


8*50MM

FCC ID: 2AAFASY-E562-003-05



Stuck on the top surface of the remote controller