



INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs


Model: Z-255-BTPFU5W

(Internal)



Report No.: 15071375HKG-001

Model: Z-255-BTPFU5W




INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15071375HKG-001

Equipment Photographs

Model: Z-255-BTPFU5W

(Internal)

