


INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15010579HKG-001

Equipment Photographs

Model: 88012RC

(Internal)

