



Freq. Stability 20C 2.81V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:11:16

Freq. Stability 20C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:12:07

Freq. Stability 20C 3.80V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:11:31

Freq. Stability -20C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:11:38

Freq. Stability -10C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:11:45

Freq. Stability 0C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:11:53

Freq. Stability 10C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:12:00

Freq. Stability 30C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:12:15

Freq. Stability 40C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:12:22

Freq. Stability 50C 3.3V ac20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 01:12:29


Freq. Stability 20C 2.81V ac20 5745MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V ac20 5745MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:15:19

Freq. Stability -20C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:15:26

Freq. Stability -10C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:15:34

Freq. Stability 0C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:15:41

Freq. Stability 10C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:15:48

Freq. Stability 30C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:16:03

Freq. Stability 40C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:16:10

Freq. Stability 50C 3.3V ac20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 01:16:18

Freq. Stability 20C 2.81V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:08

Freq. Stability 20C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:59

Freq. Stability 20C 3.80V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:22

Freq. Stability -20C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:30

Freq. Stability -10C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:37

Freq. Stability 0C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:44

Freq. Stability 10C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:19:32

Freq. Stability 30C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:20:06

Freq. Stability 40C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:20:13

Freq. Stability 50C 3.3V ac20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 01:20:21

Freq. Stability 20C 2.81V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:23:09

Freq. Stability 20C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:24:01


Freq. Stability 20C 3.80V ac20 5825MHz Ant1 0 Minutes



Freq. Stability -20C 3.3V ac20 5825MHz Ant1 0 Minutes




Freq. Stability -10C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:23:39

Freq. Stability 0C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:23:46

Freq. Stability 10C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:23:33

Freq. Stability 30C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:24:08

Freq. Stability 40C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:24:15

Freq. Stability 50C 3.3V ac20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 01:24:22

Freq. Stability 20C 2.81V ac20 5180MHz Ant2 0 Minutes




Date: 22.09.2023 20:57:44

Freq. Stability 20C 3.3V ac20 5180MHz Ant2 0 Minutes




Date: 22.09.2023 20:58:35

Freq. Stability 20C 3.80V ac20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 20:57:39

Freq. Stability -20C 3.3V ac20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 20:58:06

Freq. Stability -10C 3.3V ac20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 20:58:14

Freq. Stability 0C 3.3V ac20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 20:58:21

Freq. Stability 10C 3.3V ac20 5180MHz Ant2 0 Minutes




Date: 22.09.2023 20:58:28

Freq. Stability 30C 3.3V ac20 5180MHz Ant2 0 Minutes




Date: 22.09.2023 20:58:43


Freq. Stability 40C 3.3V ac20 5180MHz Ant2 0 Minutes



Freq. Stability 50C 3.3V ac20 5180MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V ac20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 21:01:53

Freq. Stability 20C 3.3V ac20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 21:02:44

Freq. Stability 20C 3.80V ac20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 21:02:08

Freq. Stability -20C 3.3V ac20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 21:02:15


Freq. Stability -10C 3.3V ac20 5200MHz Ant2 0 Minutes



Freq. Stability 0C 3.3V ac20 5200MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V ac20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 21:02:37

Freq. Stability 30C 3.3V ac20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 21:02:52

Freq. Stability 40C 3.3V ac20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 21:02:59

Freq. Stability 50C 3.3V ac20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 21:03:06

Freq. Stability 20C 2.81V ac20 5240MHz Ant2 0 Minutes




Date: 22.09.2023 21:05:42

Freq. Stability 20C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.09.2023 21:06:33

Freq. Stability 20C 3.80V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:05:37

Freq. Stability -20C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:04

Freq. Stability -10C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:11

Freq. Stability 0C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:19

Freq. Stability 10C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:26

Freq. Stability 30C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:40

Freq. Stability 40C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:48

Freq. Stability 50C 3.3V ac20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 21:06:55

Freq. Stability 20C 2.81V ac20 5260MHz Ant2 0 Minutes




Date: 22.9.2023 21:09:24

Freq. Stability 20C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.9.2023 21:10:15

Freq. Stability 20C 3.80V ac20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 21:09:39

Freq. Stability -20C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 21:09:46

Freq. Stability -10C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.9.2023 21:09:33

Freq. Stability 0C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.9.2023 21:10:01

Freq. Stability 10C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 21:10:08

Freq. Stability 30C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 21:10:23

Freq. Stability 40C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 21:10:30

Freq. Stability 50C 3.3V ac20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 21:10:37

Freq. Stability 20C 2.81V ac20 5300MHz Ant2 0 Minutes




Date: 22.09.2023 21:13:49

Freq. Stability 20C 3.3V ac20 5300MHz Ant2 0 Minutes




Date: 22.09.2023 21:14:40

Freq. Stability 20C 3.80V ac20 5300MHz Ant2 0 Minutes



Date: 22.09.2023 21:14:03

Freq. Stability -20C 3.3V ac20 5300MHz Ant2 0 Minutes



Date: 22.09.2023 21:14:11

Freq. Stability -10C 3.3V ac20 5300MHz Ant2 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.92 dB RBW 10 kHz
 Att 30 dB SWT 40 ms VBW 30 kHz Mode Sweep
 SGL Count 20/20

• 1Pk Max

CF 5.3 GHz 1001 pts Span 40.0 MHz

Marker	Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1			1	5.29998 GHz	-26.81 dBm		
M2			1	5.29108 GHz	-20.27 dBm		
M3			1	5.30888 GHz	-20.41 dBm		

22.09.2023 21:14:18

Freq. Stability OC 3.3V ac20 5300MHz Ant2 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.92 dB RBW 10 kHz
 Att 30 dB SWT 40 ms VBW 30 kHz Mode Sweep
 SGL Count 20/20


1Pk Max

M1[1] -27.11 dBm
 5.2999600 GHz
 M2[1] -20.49 dBm
 5.2910800 GHz

CF 5.3 GHz 1001 pts Span 40.0 MHz


Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1		1	5.29996 GHz	-27.11 dBm		
M2		1	5.29108 GHz	-20.49 dBm		
M3		1	5.30884 GHz	-21.14 dBm		

Freq. Stability 10C 3.3V ac20 5300MHz Ant2 0 Minutes




Date: 22.09.2023 21:14:33

Freq. Stability 30C 3.3V ac20 5300MHz Ant2 0 Minutes




Date: 22.09.2023 21:14:47

Freq. Stability 40C 3.3V ac20 5300MHz Ant2 0 Minutes




Date: 22.09.2023 21:14:35

Freq. Stability 50C 3.3V ac20 5300MHz Ant2 0 Minutes




Date: 22.09.2023 21:15:02

Freq. Stability 20C 2.81V ac20 5320MHz Ant2 0 Minutes




Date: 22.9.2023 21:21:42

Freq. Stability 20C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.9.2023 21:22:33


Freq. Stability 20C 3.80V ac20 5320MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V ac20 5320MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.09.2023 21:22:11

Freq. Stability 0C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.09.2023 21:22:18

Freq. Stability 10C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.09.2023 21:22:25

Freq. Stability 30C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.09.2023 21:22:40

Freq. Stability 40C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.09.2023 21:22:47

Freq. Stability 50C 3.3V ac20 5320MHz Ant2 0 Minutes




Date: 22.09.2023 21:22:54

Freq. Stability 20C 2.81V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:26:29

Freq. Stability 20C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:27:20

Freq. Stability 20C 3.80V ac20 5500MHz Ant2 0 Minutes




Date: 22.9.2023 21:26:44

Freq. Stability -20C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.9.2023 21:26:51

Freq. Stability -10C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:26:58

Freq. Stability 0C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:27:06

Freq. Stability 10C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:27:13

Freq. Stability 30C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:27:28

Freq. Stability 40C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:27:35

Freq. Stability 50C 3.3V ac20 5500MHz Ant2 0 Minutes




Date: 22.09.2023 21:27:42

Freq. Stability 20C 2.81V ac20 5600MHz Ant2 0 Minutes




Date: 22.09.2023 21:37:07

Freq. Stability 20C 3.3V ac20 5600MHz Ant2 0 Minutes




Date: 22.09.2023 21:37:58

Freq. Stability 20C 3.80V ac20 5600MHz Ant2 0 Minutes




Date: 22.09.2023 21:37:21

Freq. Stability -20C 3.3V ac20 5600MHz Ant2 0 Minutes




Date: 22.09.2023 21:37:29

Freq. Stability -10C 3.3V ac20 5600MHz Ant2 0 Minutes




Date: 22.9.2023 21:37:36

Freq. Stability 0C 3.3V ac20 5600MHz Ant2 0 Minutes




Date: 22.9.2023 21:37:43

Freq. Stability 10C 3.3V ac20 5600MHz Ant2 0 Minutes




Date: 22.09.2023 21:37:51

Freq. Stability 30C 3.3V ac20 5600MHz Ant2 0 Minutes




Date: 22.09.2023 21:38:05

Freq. Stability 40C 3.3V ac20 5600MHz Ant2 0 Minutes



Date: 22.09.2023 21:38:13

Freq. Stability 50C 3.3V ac20 5600MHz Ant2 0 Minutes



Date: 22.09.2023 21:38:20