



Freq. Stability 20C 2.81V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:18:44

Freq. Stability 20C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:20:16

Freq. Stability 20C 3.80V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:19:11

Freq. Stability -20C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:19:24

Freq. Stability -10C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:19:37

Freq. Stability 0C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:19:50

Freq. Stability 10C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:20:03

Freq. Stability 30C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:20:30

Freq. Stability 40C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:20:43

Freq. Stability 50C 3.3V ac40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 04:20:56


Freq. Stability 20C 2.81V ac40 5190MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V ac40 5190MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ac40 5190MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V ac40 5190MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V ac40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 23:43:22

Freq. Stability 0C 3.3V ac40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 23:43:35

Freq. Stability 10C 3.3V ac40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 23:43:48

Freq. Stability 30C 3.3V ac40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 23:46:15

Freq. Stability 40C 3.3V ac40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 23:46:28

Freq. Stability 50C 3.3V ac40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 23:46:41


Freq. Stability 20C 2.81V ac40 5230MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ac40 5230MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ac40 5230MHz Ant2 0 Minutes




Date: 22.09.2023 23:49:45

Freq. Stability -20C 3.3V ac40 5230MHz Ant2 0 Minutes




Date: 22.09.2023 23:49:58


Freq. Stability -10C 3.3V ac40 5230MHz Ant2 0 Minutes



Freq. Stability 0C 3.3V ac40 5230MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V ac40 5230MHz Ant2 0 Minutes




Date: 22.09.2023 23:50:38

Freq. Stability 30C 3.3V ac40 5230MHz Ant2 0 Minutes




Date: 22.09.2023 23:51:04

Freq. Stability 40C 3.3V ac40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 23:51:17

Freq. Stability 50C 3.3V ac40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 23:51:30


Freq. Stability 20C 2.81V ac40 5270MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ac40 5270MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:56:06

Freq. Stability -20C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:56:19

Freq. Stability -10C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:56:32

Freq. Stability 0C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:56:45

Freq. Stability 10C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:56:38

Freq. Stability 30C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:57:25

Freq. Stability 40C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:57:38

Freq. Stability 50C 3.3V ac40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:57:51


Freq. Stability 20C 2.81V ac40 5310MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ac40 5310MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ac40 5310MHz Ant2 0 Minutes




Date: 23.09.2023 00:01:10

Freq. Stability -20C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.09.2023 00:01:23

Freq. Stability -10C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.09.2023 00:01:36

Freq. Stability 0C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.09.2023 00:01:49

Freq. Stability 10C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.09.2023 00:02:02

Freq. Stability 30C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.09.2023 00:02:28

Freq. Stability 40C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.9.2023 00:02:41

Freq. Stability 50C 3.3V ac40 5310MHz Ant2 0 Minutes




Date: 23.9.2023 00:02:54

Freq. Stability 20C 2.81V ac40 5510MHz Ant2 0 Minutes




Date: 23.09.2023 00:05:29

Freq. Stability 20C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.09.2023 00:07:00

Freq. Stability 20C 3.80V ac40 5510MHz Ant2 0 Minutes




Date: 23.9.2023 00:05:35

Freq. Stability -20C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.9.2023 00:06:08

Freq. Stability -10C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.9.2023 00:06:21

Freq. Stability 0C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.9.2023 00:06:34

Freq. Stability 10C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.9.2023 00:06:47

Freq. Stability 30C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.9.2023 00:07:13

Freq. Stability 40C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.09.2023 00:07:26

Freq. Stability 50C 3.3V ac40 5510MHz Ant2 0 Minutes




Date: 23.09.2023 00:07:40

Freq. Stability 20C 2.81V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:10:17

Freq. Stability 20C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:11:49

Freq. Stability 20C 3.80V ac40 5590MHz Ant2 0 Minutes




Date: 23.9.2023 00:10:43

Freq. Stability -20C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.9.2023 00:10:56

Freq. Stability -10C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:11:09

Freq. Stability 0C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:11:22

Freq. Stability 10C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:11:35

Freq. Stability 30C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:12:02

Freq. Stability 40C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:12:15

Freq. Stability 50C 3.3V ac40 5590MHz Ant2 0 Minutes




Date: 23.09.2023 00:12:28

Freq. Stability 20C 2.81V ac40 5670MHz Ant2 0 Minutes




Date: 23.09.2023 00:16:01

Freq. Stability 20C 3.3V ac40 5670MHz Ant2 0 Minutes




Date: 23.09.2023 00:17:32

Freq. Stability 20C 3.80V ac40 5670MHz Ant2 0 Minutes




Date: 23.9.2023 00:16:27

Freq. Stability -20C 3.3V ac40 5670MHz Ant2 0 Minutes




Date: 23.9.2023 00:16:40


Freq. Stability -10C 3.3V ac40 5670MHz Ant2 0 Minutes



Freq. Stability 0C 3.3V ac40 5670MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V ac40 5670MHz Ant2 0 Minutes




Date: 23.09.2023 00:17:19

Freq. Stability 30C 3.3V ac40 5670MHz Ant2 0 Minutes




Date: 23.09.2023 00:17:46

Freq. Stability 40C 3.3V ac40 5670MHz Ant2 0 Minutes




Date: 23.09.2023 00:17:59

Freq. Stability 50C 3.3V ac40 5670MHz Ant2 0 Minutes




Date: 23.09.2023 00:18:12


Freq. Stability 20C 2.81V ac40 5755MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ac40 5755MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ac40 5755MHz Ant2 0 Minutes




Date: 23.9.2023 00:21:23

Freq. Stability -20C 3.3V ac40 5755MHz Ant2 0 Minutes




Date: 23.9.2023 00:21:36


Freq. Stability -10C 3.3V ac40 5755MHz Ant2 0 Minutes



Freq. Stability 0C 3.3V ac40 5755MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V ac40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 00:22:15

Freq. Stability 30C 3.3V ac40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 00:22:42

Freq. Stability 40C 3.3V ac40 5755MHz Ant2 0 Minutes




Date: 23.9.2023 00:22:55

Freq. Stability 50C 3.3V ac40 5755MHz Ant2 0 Minutes




Date: 23.9.2023 00:23:08


Freq. Stability 20C 2.81V ac40 5795MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ac40 5795MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ac40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 00:26:31

Freq. Stability -20C 3.3V ac40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 00:26:44


Freq. Stability -10C 3.3V ac40 5795MHz Ant2 0 Minutes




Freq. Stability 0C 3.3V ac40 5795MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V ac40 5795MHz Ant2 0 Minutes



Freq. Stability 30C 3.3V ac40 5795MHz Ant2 0 Minutes




Freq. Stability 40C 3.3V ac40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 00:28:04

Freq. Stability 50C 3.3V ac40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 00:28:17

Freq. Stability 20C 2.81V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 04:57:38

Freq. Stability 20C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 05:00:37

Freq. Stability 20C 3.80V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 04:58:44

Freq. Stability -20C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 04:59:06

Freq. Stability -10C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 04:59:29

Freq. Stability 0C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 04:59:31

Freq. Stability 10C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 05:00:14

Freq. Stability 30C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 05:01:00

Freq. Stability 40C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 05:01:22

Freq. Stability 50C 3.3V ac80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 05:01:45


Freq. Stability 20C 2.81V ac80 5290MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V ac80 5290MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V ac80 5290MHz Ant1 0 Minutes




Date: 20.09.2023 05:04:31

Freq. Stability -20C 3.3V ac80 5290MHz Ant1 0 Minutes




Date: 20.09.2023 05:04:33

Freq. Stability -10C 3.3V ac80 5290MHz Ant1 0 Minutes




Date: 20.09.2023 05:05:16

Freq. Stability 0C 3.3V ac80 5290MHz Ant1 0 Minutes




Date: 20.09.2023 05:05:38

Freq. Stability 10C 3.3V ac80 5290MHz Ant1 0 Minutes




Date: 20.09.2023 05:06:01

Freq. Stability 30C 3.3V ac80 5290MHz Ant1 0 Minutes




Date: 20.09.2023 05:06:46

Freq. Stability 40C 3.3V ac80 5290MHz Ant1 0 Minutes



Date: 20.09.2023 05:07:08

Freq. Stability 50C 3.3V ac80 5290MHz Ant1 0 Minutes



Date: 20.09.2023 05:07:31