





1. Material : PC+ABS

2. Colour: BLACK

3. SURFACE FINISH : TEXTURE

- #### 4. Technique requirement:

4. 1: measurement method: 外取最大値,

- 产品长宽中间变形重新定义内控内

- 4.2产 品料头需削平，不可凹凸不平

- 4.3The surface of the product can not shrink, not satisfied,

- silver

- #### 4.4材料要求符合环保

5. CTA= Critical to assemble (00-02)

- CTA need to do CPK control

- CTF= Critical to function (00-00) .

- CITF need to do FAI control[6]. Unspecified tolerance:

[illegible]