

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB522
26-0133
August 24, 2026
SwipeSense, Inc.
HUB522

INTERNAL PHOTOGRAPHS




Figure 1. EUT, Front Cover Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB522
26-0133
August 24, 2026
SwipeSense, Inc.
HUB522



Figure 2. Back of Main PCB

Note: Wire coming off board are for programming and power purposes of testing.

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB522
26-0133
August 24, 2026
SwipeSense, Inc.
HUB522




Figure 3. Front of Main PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB522
26-0133
August 24, 2026
SwipeSense, Inc.
HUB522




Figure 4. BLE Radio- Close up

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB522
26-0133
August 24, 2026
SwipeSense, Inc.
HUB522




Figure 5. 2.4 GHz Thread Radio- Close up

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB522
26-0133
August 24, 2026
SwipeSense, Inc.
HUB522




Figure 6. Enclosure with Main PCB Removed