




16:44:23 24.08.2021

Band5-10MHz-16QAM-20600-50RB#0




16:44:48 24.08.2021

Band7-5MHz-QPSK-20775-1RB#0




08:36:22 25.08.2021

Band7-5MHz-QPSK-20775-25RB#0




08:36:46 25.08.2021

Band7-5MHz-QPSK-21100-1RB#0




08:37:13 25.08.2021

Band7-5MHz-QPSK-21100-25RB#0




08:37:37 25.08.2021

Band7-5MHz-QPSK-21425-1RB#0




08:38:03 25.08.2021

Band7-5MHz-QPSK-21425-25RB#0




08:38:28 25.08.2021

Band7-5MHz-16QAM-20775-1RB#0




08:36:34 25.08.2021

Band7-5MHz-16QAM-20775-25RB#0



08:36:58 25.08.2021

Band7-5MHz-16QAM-21100-1RB#0




08:37:25 25.08.2021

Band7-5MHz-16QAM-21100-25RB#0




08:37:49 25.08.2021

Band7-5MHz-16QAM-21425-1RB#0




08:38:15 25.08.2021

Band7-5MHz-16QAM-21425-25RB#0




08:38:40 25.08.2021

Band7-10MHz-QPSK-20800-1RB#0




09:04:45 25.08.2021

Band7-10MHz-QPSK-20800-50RB#0




09:05:09 25.08.2021

Band7-10MHz-QPSK-21100-1RB#0




09:05:36 25.08.2021

Band7-10MHz-QPSK-21100-50RB#0




09:06:00 25.08.2021

Band7-10MHz-QPSK-21400-1RB#0




09:06:26 25.08.2021

Band7-10MHz-QPSK-21400-50RB#0




09:06:51 25.08.2021

Band7-10MHz-16QAM-20800-1RB#0




09:04:57 25.08.2021

Band7-10MHz-16QAM-20800-50RB#0




09:05:22 25.08.2021

Band7-10MHz-16QAM-21100-1RB#0




09:05:48 25.08.2021

Band7-10MHz-16QAM-21100-50RB#0




09:06:13 25.08.2021

Band7-10MHz-16QAM-21400-1RB#0




09:06:38 25.08.2021

Band7-10MHz-16QAM-21400-50RB#0




09:07:03 25.08.2021

Band7-15MHz-QPSK-20825-1RB#0




09:33:49 25.08.2021

Band7-15MHz-QPSK-20825-75RB#0




09:34:14 25.08.2021

Band7-15MHz-QPSK-21100-1RB#0




09:34:41 25.08.2021

Band7-15MHz-QPSK-21100-75RB#0




09:35:06 25.08.2021

Band7-15MHz-QPSK-21375-1RB#0




09:35:33 25.08.2021

Band7-15MHz-QPSK-21375-75RB#0




09:35:58 25.08.2021

Band7-15MHz-16QAM-20825-1RB#0




09:34:02 25.08.2021

Band7-15MHz-16QAM-20825-75RB#0



09:34:27 25.08.2021

Band7-15MHz-16QAM-21100-1RB#0




09:34:54 25.08.2021

Band7-15MHz-16QAM-21100-75RB#0




09:35:19 25.08.2021

Band7-15MHz-16QAM-21375-1RB#0




09:35:45 25.08.2021

Band7-15MHz-16QAM-21375-75RB#0



09:36:11 25.08.2021

Band7-20MHz-QPSK-20850-1RB#0




10:02:57 25.08.2021

Band7-20MHz-QPSK-20850-100RB#0




10:03:22 25.08.2021

Band7-20MHz-QPSK-21100-1RB#0




10:03:49 25.08.2021

Band7-20MHz-QPSK-21100-100RB#0



10:04:14 25.08.2021

Band7-20MHz-QPSK-21350-1RB#0



10:04:40 25.08.2021

Band7-20MHz-QPSK-21350-100RB#0



10:05:06 25.08.2021

Band7-20MHz-16QAM-20850-1RB#0




10:03:10 25.08.2021

Band7-20MHz-16QAM-20850-100RB#0



10:03:35 25.08.2021

Band7-20MHz-16QAM-21100-1RB#0




10:04:01 25.08.2021

Band7-20MHz-16QAM-21100-100RB#0



10:04:27 25.08.2021

Band7-20MHz-16QAM-21350-1RB#0




10:04:53 25.08.2021

Band7-20MHz-16QAM-21350-100RB#0




10:05:18 25.08.2021

Band12-1.4MHz-QPSK-23017-1RB#0




10:25:13 25.08.2021

Band12-1.4MHz-QPSK-23017-6RB#0




10:25:37 25.08.2021

Band12-1.4MHz-QPSK-23095-1RB#0




10:26:03 25.08.2021

Band12-1.4MHz-QPSK-23095-6RB#0



10:26:27 25.08.2021

Band12-1.4MHz-QPSK-23173-1RB#0




10:26:52 25.08.2021

Band12-1.4MHz-QPSK-23173-6RB#0




10:27:16 25.08.2021

Band12-1.4MHz-16QAM-23017-1RB#0




10:25:25 25.08.2021

Band12-1.4MHz-16QAM-23017-6RB#0




10:25:50 25.08.2021

Band12-1.4MHz-16QAM-23095-1RB#0




10:26:15 25.08.2021

Band12-1.4MHz-16QAM-23095-6RB#0



10:26:39 25.08.2021

Band12-1.4MHz-16QAM-23173-1RB#0




10:27:04 25.08.2021

Band12-1.4MHz-16QAM-23173-6RB#0




10:27:29 25.08.2021

Band12-3MHz-QPSK-23025-1RB#0




10:52:26 25.08.2021

Band12-3MHz-QPSK-23025-15RB#0




10:52:50 25.08.2021

Band12-3MHz-QPSK-23095-1RB#0




10:53:16 25.08.2021

Band12-3MHz-QPSK-23095-15RB#0




10:53:41 25.08.2021

Band12-3MHz-QPSK-23165-1RB#0




10:54:06 25.08.2021

Band12-3MHz-QPSK-23165-15RB#0




10:54:31 25.08.2021

Band12-3MHz-16QAM-23025-1RB#0




10:52:38 25.08.2021

Band12-3MHz-16QAM-23025-15RB#0



10:53:03 25.08.2021

Band12-3MHz-16QAM-23095-1RB#0



10:53:28 25.08.2021

Band12-3MHz-16QAM-23095-15RB#0



10:53:53 25.08.2021

Band12-3MHz-16QAM-23165-1RB#0




10:54:18 25.08.2021

Band12-3MHz-16QAM-23165-15RB#0




10:54:43 25.08.2021

Band12-5MHz-QPSK-23035-1RB#0




11:20:13 25.08.2021

Band12-5MHz-QPSK-23035-25RB#0




11:20:37 25.08.2021

Band12-5MHz-QPSK-23095-1RB#0




11:21:03 25.08.2021

Band12-5MHz-QPSK-23095-25RB#0




11:21:27 25.08.2021

Band12-5MHz-QPSK-23155-1RB#0




11:21:53 25.08.2021

Band12-5MHz-QPSK-23155-25RB#0



11:22:18 25.08.2021

Band12-5MHz-16QAM-23035-1RB#0




11:20:25 25.08.2021

Band12-5MHz-16QAM-23035-25RB#0



11:20:49 25.08.2021

Band12-5MHz-16QAM-23095-1RB#0




11:21:15 25.08.2021

Band12-5MHz-16QAM-23095-25RB#0




11:21:40 25.08.2021

Band12-5MHz-16QAM-23155-1RB#0




11:22:06 25.08.2021

Band12-5MHz-16QAM-23155-25RB#0




11:22:30 25.08.2021

Band12-10MHz-QPSK-23060-1RB#0




11:47:42 25.08.2021

Band12-10MHz-QPSK-23060-50RB#0




11:48:07 25.08.2021

Band12-10MHz-QPSK-23095-1RB#0




11:48:33 25.08.2021

Band12-10MHz-QPSK-23095-50RB#0




11:48:58 25.08.2021

Band12-10MHz-QPSK-23130-1RB#0




11:49:24 25.08.2021

Band12-10MHz-QPSK-23130-50RB#0




11:49:49 25.08.2021

Band12-10MHz-16QAM-23060-1RB#0




11:47:55 25.08.2021

Band12-10MHz-16QAM-23060-50RB#0



11:48:20 25.08.2021

Band12-10MHz-16QAM-23095-1RB#0



11:48:45 25.08.2021

Band12-10MHz-16QAM-23095-50RB#0



11:49:10 25.08.2021

Band12-10MHz-16QAM-23130-1RB#0




11:49:36 25.08.2021

Band12-10MHz-16QAM-23130-50RB#0




11:50:01 25.08.2021

Band13-5MHz-QPSK-23205-1RB#0




12:40:33 25.08.2021

Band13-5MHz-QPSK-23205-25RB#0




12:40:57 25.08.2021

Band13-5MHz-QPSK-23230-1RB#0




12:41:23 25.08.2021

Band13-5MHz-QPSK-23230-25RB#0




12:41:48 25.08.2021

Band13-5MHz-QPSK-23255-1RB#0




12:42:14 25.08.2021

Band13-5MHz-QPSK-23255-25RB#0



12:42:39 25.08.2021

Band13-5MHz-16QAM-23205-1RB#0




12:40:45 25.08.2021

Band13-5MHz-16QAM-23205-25RB#0




12:41:10 25.08.2021

Band13-5MHz-16QAM-23230-1RB#0




12:41:36 25.08.2021

Band13-5MHz-16QAM-23230-25RB#0




12:42:00 25.08.2021

Band13-5MHz-16QAM-23255-1RB#0




12:42:26 25.08.2021

Band13-5MHz-16QAM-23255-25RB#0




12:42:51 25.08.2021

Band13-10MHz-QPSK-23230-1RB#0




13:08:50 25.08.2021

Band13-10MHz-QPSK-23230-50RB#0




13:09:15 25.08.2021

Band13-10MHz-16QAM-23230-1RB#0




13:09:03 25.08.2021

Band13-10MHz-16QAM-23230-50RB#0




13:09:28 25.08.2021

Band17-5MHz-QPSK-23755-1RB#0



15:23:28 25.08.2021

Band17-5MHz-QPSK-23755-25RB#0



15:23:52 25.08.2021

Band17-5MHz-QPSK-23790-1RB#0