






13:27:48 16.11.2021

Band38-10MHz-QPSK-38000-1RB#0




13:28:15 16.11.2021

Band38-10MHz-QPSK-38000-50RB#0




13:28:40 16.11.2021

Band38-10MHz-QPSK-38200-1RB#0




13:29:07 16.11.2021

Band38-10MHz-QPSK-38200-50RB#0




13:29:32 16.11.2021

Band38-10MHz-16QAM-37800-1RB#0




13:27:36 16.11.2021

Band38-10MHz-16QAM-37800-50RB#0




13:28:01 16.11.2021

Band38-10MHz-16QAM-38000-1RB#0




13:28:28 16.11.2021

Band38-10MHz-16QAM-38000-50RB#0




13:28:53 16.11.2021

Band38-10MHz-16QAM-38200-1RB#0




13:29:19 16.11.2021

Band38-10MHz-16QAM-38200-50RB#0




13:29:44 16.11.2021

Band38-15MHz-QPSK-37825-1RB#0



13:56:48 16.11.2021

Band38-15MHz-QPSK-37825-75RB#0




13:57:13 16.11.2021

Band38-15MHz-QPSK-38000-1RB#0




13:57:40 16.11.2021

Band38-15MHz-QPSK-38000-75RB#0




13:58:05 16.11.2021

Band38-15MHz-QPSK-38175-1RB#0




13:58:33 16.11.2021

Band38-15MHz-QPSK-38175-75RB#0




13:58:58 16.11.2021

Band38-15MHz-16QAM-37825-1RB#0




13:57:00 16.11.2021

Band38-15MHz-16QAM-37825-75RB#0




13:57:25 16.11.2021

Band38-15MHz-16QAM-38000-1RB#0




13:57:53 16.11.2021

Band38-15MHz-16QAM-38000-75RB#0




13:58:18 16.11.2021

Band38-15MHz-16QAM-38175-1RB#0




13:58:45 16.11.2021

Band38-15MHz-16QAM-38175-75RB#0




13:59:10 16.11.2021

Band38-20MHz-QPSK-37850-1RB#0




14:30:05 16.11.2021

Band38-20MHz-QPSK-37850-100RB#0




14:30:32 16.11.2021

Band38-20MHz-QPSK-38000-1RB#0




14:31:00 16.11.2021

Band38-20MHz-QPSK-38000-100RB#0




14:31:26 16.11.2021

Band38-20MHz-QPSK-38150-1RB#0




14:31:54 16.11.2021

Band38-20MHz-QPSK-38150-100RB#0




14:32:21 16.11.2021

Band38-20MHz-16QAM-37850-1RB#0




14:30:19 16.11.2021

Band38-20MHz-16QAM-37850-100RB#0




14:30:45 16.11.2021

Band38-20MHz-16QAM-38000-1RB#0




14:31:13 16.11.2021

Band38-20MHz-16QAM-38000-100RB#0



14:31:39 16.11.2021

Band38-20MHz-16QAM-38150-1RB#0





14:32:07 16.11.2021

Band38-20MHz-16QAM-38150-100RB#0




14:32:34 16.11.2021






Band41-5MHz-QPSK-39675-1RB#0




11:35:45 14.01.2022

Band41-5MHz-QPSK-39675-25RB#0




11:36:05 14.01.2022

Band41-5MHz-QPSK-40620-1RB#0




11:36:28 14.01.2022

Band41-5MHz-QPSK-40620-25RB#0




11:36:48 14.01.2022

Band41-5MHz-QPSK-41565-1RB#0




11:37:11 14.01.2022

Band41-5MHz-QPSK-41565-25RB#0




11:37:31 14.01.2022

Band41-5MHz-16QAM-39675-1RB#0




11:35:55 14.01.2022

Band41-5MHz-16QAM-39675-25RB#0




11:36:15 14.01.2022

Band41-5MHz-16QAM-40620-1RB#0




11:36:38 14.01.2022

Band41-5MHz-16QAM-40620-25RB#0




11:36:58 14.01.2022

Band41-5MHz-16QAM-41565-1RB#0




11:37:21 14.01.2022

Band41-5MHz-16QAM-41565-25RB#0




11:37:41 14.01.2022

Band41-10MHz-QPSK-39700-1RB#0




11:39:49 14.01.2022

Band41-10MHz-QPSK-39700-50RB#0




11:40:10 14.01.2022

Band41-10MHz-QPSK-40620-1RB#0




11:40:32 14.01.2022

Band41-10MHz-QPSK-40620-50RB#0




11:40:53 14.01.2022

Band41-10MHz-QPSK-41540-1RB#0




11:41:16 14.01.2022

Band41-10MHz-QPSK-41540-50RB#0




11:41:36 14.01.2022

Band41-10MHz-16QAM-39700-1RB#0




11:40:00 14.01.2022

Band41-10MHz-16QAM-39700-50RB#0




11:40:20 14.01.2022

Band41-10MHz-16QAM-40620-1RB#0




11:40:43 14.01.2022

Band41-10MHz-16QAM-40620-50RB#0




11:41:03 14.01.2022

Band41-10MHz-16QAM-41540-1RB#0




11:41:26 14.01.2022

Band41-10MHz-16QAM-41540-50RB#0




11:41:46 14.01.2022

Band41-15MHz-QPSK-39725-1RB#0




11:43:55 14.01.2022

Band41-15MHz-QPSK-39725-75RB#0




11:44:16 14.01.2022

Band41-15MHz-QPSK-40620-1RB#0




11:44:39 14.01.2022

Band41-15MHz-QPSK-40620-75RB#0




11:44:59 14.01.2022

Band41-15MHz-QPSK-41515-1RB#0




11:45:22 14.01.2022

Band41-15MHz-QPSK-41515-75RB#0




11:45:43 14.01.2022

Band41-15MHz-16QAM-39725-1RB#0




11:44:05 14.01.2022

Band41-15MHz-16QAM-39725-75RB#0




11:44:26 14.01.2022

Band41-15MHz-16QAM-40620-1RB#0




11:44:49 14.01.2022

Band41-15MHz-16QAM-40620-75RB#0




11:45:09 14.01.2022

Band41-15MHz-16QAM-41515-1RB#0




11:45:32 14.01.2022

Band41-15MHz-16QAM-41515-75RB#0




11:45:53 14.01.2022

Band41-20MHz-QPSK-39750-1RB#0




11:48:02 14.01.2022

Band41-20MHz-QPSK-39750-100RB#0




11:48:23 14.01.2022

Band41-20MHz-QPSK-40620-1RB#0




11:48:46 14.01.2022

Band41-20MHz-QPSK-40620-100RB#0




11:49:07 14.01.2022

Band41-20MHz-QPSK-41490-1RB#0




11:49:30 14.01.2022

Band41-20MHz-QPSK-41490-100RB#0




11:49:50 14.01.2022

Band41-20MHz-16QAM-39750-1RB#0




11:48:13 14.01.2022

Band41-20MHz-16QAM-39750-100RB#0




11:48:33 14.01.2022

Band41-20MHz-16QAM-40620-1RB#0




11:48:56 14.01.2022

Band41-20MHz-16QAM-40620-100RB#0




11:49:17 14.01.2022

Band41-20MHz-16QAM-41490-1RB#0




11:49:40 14.01.2022

Band41-20MHz-16QAM-41490-100RB#0




11:50:00 14.01.2022

Band66-1.4MHz-QPSK-131979-1RB#0




14:30:28 26.08.2021

Band66-1.4MHz-QPSK-131979-6RB#0




14:30:52 26.08.2021

Band66-1.4MHz-QPSK-132322-1RB#0




14:31:17 26.08.2021

Band66-1.4MHz-QPSK-132322-6RB#0




14:31:42 26.08.2021

Band66-1.4MHz-QPSK-132665-1RB#0




14:32:07 26.08.2021

Band66-1.4MHz-QPSK-132665-6RB#0



14:32:31 26.08.2021

Band66-1.4MHz-16QAM-131979-1RB#0



14:30:40 26.08.2021

Band66-1.4MHz-16QAM-131979-6RB#0



14:31:04 26.08.2021

Band66-1.4MHz-16QAM-132322-1RB#0




14:31:30 26.08.2021

Band66-1.4MHz-16QAM-132322-6RB#0




14:31:54 26.08.2021

Band66-1.4MHz-16QAM-132665-1RB#0




14:32:19 26.08.2021

Band66-1.4MHz-16QAM-132665-6RB#0




14:32:43 26.08.2021

Band66-3MHz-QPSK-131987-1RB#0




14:56:46 26.08.2021

Band66-3MHz-QPSK-131987-15RB#0




14:57:11 26.08.2021

Band66-3MHz-QPSK-132322-1RB#0




14:57:36 26.08.2021

Band66-3MHz-QPSK-132322-15RB#0




14:58:01 26.08.2021

Band66-3MHz-QPSK-132657-1RB#0




14:58:27 26.08.2021

Band66-3MHz-QPSK-132657-15RB#0




14:58:52 26.08.2021

Band66-3MHz-16QAM-131987-1RB#0




14:56:58 26.08.2021

Band66-3MHz-16QAM-131987-15RB#0



14:57:23 26.08.2021

Band66-3MHz-16QAM-132322-1RB#0



14:57:49 26.08.2021

Band66-3MHz-16QAM-132322-15RB#0




14:58:13 26.08.2021

Band66-3MHz-16QAM-132657-1RB#0




14:58:39 26.08.2021

Band66-3MHz-16QAM-132657-15RB#0




14:59:04 26.08.2021

Band66-5MHz-QPSK-131997-1RB#0




15:23:58 26.08.2021

Band66-5MHz-QPSK-131997-25RB#0




15:24:22 26.08.2021

Band66-5MHz-QPSK-132322-1RB#0



15:24:48 26.08.2021

Band66-5MHz-QPSK-132322-25RB#0



15:25:13 26.08.2021

Band66-5MHz-QPSK-132647-1RB#0