






15:25:39 26.08.2021

Band66-5MHz-QPSK-132647-25RB#0




15:26:04 26.08.2021

Band66-5MHz-16QAM-131997-1RB#0




15:24:10 26.08.2021

Band66-5MHz-16QAM-131997-25RB#0




15:24:35 26.08.2021

Band66-5MHz-16QAM-132322-1RB#0



15:25:01 26.08.2021

Band66-5MHz-16QAM-132322-25RB#0




15:25:25 26.08.2021

Band66-5MHz-16QAM-132647-1RB#0




15:25:52 26.08.2021

Band66-5MHz-16QAM-132647-25RB#0




15:26:16 26.08.2021

Band66-10MHz-QPSK-132022-1RB#0




15:51:01 26.08.2021

Band66-10MHz-QPSK-132022-50RB#0




15:51:26 26.08.2021

Band66-10MHz-QPSK-132322-1RB#0




15:51:52 26.08.2021

Band66-10MHz-QPSK-132322-50RB#0



15:52:17 26.08.2021

Band66-10MHz-QPSK-132622-1RB#0



15:52:43 26.08.2021

Band66-10MHz-QPSK-132622-50RB#0




15:53:08 26.08.2021

Band66-10MHz-16QAM-132022-1RB#0




15:51:14 26.08.2021

Band66-10MHz-16QAM-132022-50RB#0




15:51:39 26.08.2021

Band66-10MHz-16QAM-132322-1RB#0



15:52:05 26.08.2021

Band66-10MHz-16QAM-132322-50RB#0




15:52:30 26.08.2021

Band66-10MHz-16QAM-132622-1RB#0




15:52:56 26.08.2021

Band66-10MHz-16QAM-132622-50RB#0




15:53:21 26.08.2021

Band66-15MHz-QPSK-132047-1RB#0




16:18:48 26.08.2021

Band66-15MHz-QPSK-132047-75RB#0




16:19:13 26.08.2021

Band66-15MHz-QPSK-132322-1RB#0




16:19:40 26.08.2021

Band66-15MHz-QPSK-132322-75RB#0




16:20:05 26.08.2021

Band66-15MHz-QPSK-132597-1RB#0




16:20:32 26.08.2021

Band66-15MHz-QPSK-132597-75RB#0




16:20:57 26.08.2021


Band66-15MHz-16QAM-132047-1RB#0



Band66-15MHz-16QAM-132047-75RB#0



Band66-15MHz-16QAM-132322-1RB#0




16:19:52 26.08.2021

Band66-15MHz-16QAM-132322-75RB#0



16:20:18 26.08.2021

Band66-15MHz-16QAM-132597-1RB#0




16:20:44 26.08.2021

Band66-15MHz-16QAM-132597-75RB#0




16:21:09 26.08.2021

Band66-20MHz-QPSK-132072-1RB#0




16:46:26 26.08.2021

Band66-20MHz-QPSK-132072-100RB#0




16:46:52 26.08.2021

Band66-20MHz-QPSK-132322-1RB#0




16:47:19 26.08.2021

Band66-20MHz-QPSK-132322-100RB#0




16:47:44 26.08.2021

Band66-20MHz-QPSK-132572-1RB#0




16:48:11 26.08.2021

Band66-20MHz-QPSK-132572-100RB#0




16:48:36 26.08.2021

Band66-20MHz-16QAM-132072-1RB#0




16:46:39 26.08.2021

Band66-20MHz-16QAM-132072-100RB#0



16:47:05 26.08.2021

Band66-20MHz-16QAM-132322-1RB#0




16:47:31 26.08.2021

Band66-20MHz-16QAM-132322-100RB#0




16:47:57 26.08.2021

Band66-20MHz-16QAM-132572-1RB#0



16:48:23 26.08.2021

Band66-20MHz-16QAM-132572-100RB#0



16:48:49 26.08.2021