





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix E: Band edge measurements

Test Result B1/2/3

Test Mode	Antenna	ChName	Frequency[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant1	Low	5180	-45.63	≤-27	PASS
11A	Ant2	Low	5180	-43.52	≤-27	PASS
11A	Ant1	High	5320	-44.12	≤-27	PASS
11A	Ant2	High	5320	-41.14	≤-27	PASS
11A	Ant1	Low	5500	-43.68	≤-27	PASS
11A	Ant2	Low	5500	-41.17	≤-27	PASS
11A	Ant1	High	5700	-40.73	≤-27	PASS
11A	Ant2	High	5700	-39.85	≤-27	PASS
11N20MIMO	Ant1	Low	5180	-44.37	≤-27	PASS
11N20MIMO	Ant2	Low	5180	-43.33	≤-27	PASS
11N20MIMO	Ant1	High	5320	-44.1	≤-27	PASS
11N20MIMO	Ant2	High	5320	-42.63	≤-27	PASS
11N20MIMO	Ant1	Low	5500	-43.61	≤-27	PASS
11N20MIMO	Ant2	Low	5500	-42.24	≤-27	PASS
11N20MIMO	Ant1	High	5700	-40.37	≤-27	PASS
11N20MIMO	Ant2	High	5700	-40.2	≤-27	PASS
11N40MIMO	Ant1	Low	5190	-42.03	≤-27	PASS
11N40MIMO	Ant2	Low	5190	-42.66	≤-27	PASS
11N40MIMO	Ant1	High	5310	-38.4	≤-27	PASS
11N40MIMO	Ant2	High	5310	-41.63	≤-27	PASS
11N40MIMO	Ant1	Low	5510	-43.71	≤-27	PASS
11N40MIMO	Ant2	Low	5510	-38.12	≤-27	PASS
11N40MIMO	Ant1	High	5670	-42.81	≤-27	PASS
11N40MIMO	Ant2	High	5670	-40.72	≤-27	PASS
11AC20MIMO	Ant1	Low	5180	-43.85	≤-27	PASS
11AC20MIMO	Ant2	Low	5180	-43.19	≤-27	PASS
11AC20MIMO	Ant1	High	5320	-44.73	≤-27	PASS
11AC20MIMO	Ant2	High	5320	-42.46	≤-27	PASS
11AC20MIMO	Ant1	Low	5500	-43.01	≤-27	PASS
11AC20MIMO	Ant2	Low	5500	-40.86	≤-27	PASS
11AC20MIMO	Ant1	High	5700	-40.2	≤-27	PASS
11AC20MIMO	Ant2	High	5700	-36.51	≤-27	PASS
11AC40MIMO	Ant1	Low	5190	-40.05	≤-27	PASS
11AC40MIMO	Ant2	Low	5190	-42.03	≤-27	PASS
11AC40MIMO	Ant1	High	5310	-40.52	≤-27	PASS
11AC40MIMO	Ant2	High	5310	-41.19	≤-27	PASS
11AC40MIMO	Ant1	Low	5510	-42.26	≤-27	PASS

11AC40MIMO	Ant2	Low	5510	-41.17	≤ -27	PASS
11AC40MIMO	Ant1	High	5670	-43.11	≤ -27	PASS
11AC40MIMO	Ant2	High	5670	-39.91	≤ -27	PASS
11AC80MIMO	Ant1	Low	5210	-41.86	≤ -27	PASS
11AC80MIMO	Ant2	Low	5210	-41.6	≤ -27	PASS
11AC80MIMO	Ant1	High	5290	-39.53	≤ -27	PASS
11AC80MIMO	Ant2	High	5290	-39.73	≤ -27	PASS
11AC80MIMO	Ant1	Low	5530	-41.27	≤ -27	PASS
11AC80MIMO	Ant2	Low	5530	-39.16	≤ -27	PASS
11AC80MIMO	Ant1	High	5610	-43.47	≤ -27	PASS
11AC80MIMO	Ant2	High	5610	-40.84	≤ -27	PASS
11AX20MIMO	Ant1	Low	5180	-44.67	≤ -27	PASS
11AX20MIMO	Ant2	Low	5180	-43.41	≤ -27	PASS
11AX20MIMO	Ant1	High	5320	-44.57	≤ -27	PASS
11AX20MIMO	Ant2	High	5320	-40.09	≤ -27	PASS
11AX20MIMO	Ant1	Low	5500	-36.05	≤ -27	PASS
11AX20MIMO	Ant2	Low	5500	-42.24	≤ -27	PASS
11AX20MIMO	Ant1	High	5700	-37.63	≤ -27	PASS
11AX20MIMO	Ant2	High	5700	-38.19	≤ -27	PASS
11AX40MIMO	Ant1	Low	5190	-35.56	≤ -27	PASS
11AX40MIMO	Ant2	Low	5190	-36.16	≤ -27	PASS
11AX40MIMO	Ant1	High	5310	-37.26	≤ -27	PASS
11AX40MIMO	Ant2	High	5310	-36.19	≤ -27	PASS
11AX40MIMO	Ant1	Low	5510	-38.13	≤ -27	PASS
11AX40MIMO	Ant2	Low	5510	-35.8	≤ -27	PASS
11AX40MIMO	Ant1	High	5670	-42.64	≤ -27	PASS
11AX40MIMO	Ant2	High	5670	-39.41	≤ -27	PASS
11AX80MIMO	Ant1	Low	5210	-32.81	≤ -27	PASS
11AX80MIMO	Ant2	Low	5210	-38.04	≤ -27	PASS
11AX80MIMO	Ant1	High	5290	-34.28	≤ -27	PASS
11AX80MIMO	Ant2	High	5290	-35.92	≤ -27	PASS
11AX80MIMO	Ant1	Low	5530	-35.5	≤ -27	PASS
11AX80MIMO	Ant2	Low	5530	-36.23	≤ -27	PASS
11AX80MIMO	Ant1	High	5610	-38.56	≤ -27	PASS
11AX80MIMO	Ant2	High	5610	-40.66	≤ -27	PASS

Note: 1. The margin plus the antenna gain also meets the limit.

2. ANT 1 and ANT 2 worst case result are over 3 dB margin below the limit ,so MIMO mode is also compliance with the requirement.

Test Result B4

Test Mode	Antenna	Ch. Name	Frequency[M Hz]	FreqRange [MHz]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	Low	5745	5720~5725	-35.44	≤16.08	PASS
11A	Ant1	Low	5745	5700~5720	-36.28	≤15.37	PASS
11A	Ant1	Low	5745	5650~5700	-45.44	≤-26.87	PASS
11A	Ant1	Low	5745	5760~5650	-45.86	≤-27	PASS
11A	Ant2	Low	5745	5720~5725	-42.35	≤16.08	PASS
11A	Ant2	Low	5745	5700~5720	-41.63	≤10.51	PASS
11A	Ant2	Low	5745	5650~5700	-43.61	≤-26.27	PASS
11A	Ant2	Low	5745	5760~5650	-42.73	≤-27	PASS
11A	Ant1	High	5825	5850~5855	-41.76	≤16.34	PASS
11A	Ant1	High	5825	5855~5875	-42.32	≤10.59	PASS
11A	Ant1	High	5825	5875~5925	-44.84	≤-26.01	PASS
11A	Ant1	High	5825	5925~5935	-44.75	≤-27	PASS
11A	Ant2	High	5825	5850~5855	-42.14	≤15.73	PASS
11A	Ant2	High	5825	5855~5875	-41.46	≤10.66	PASS
11A	Ant2	High	5825	5875~5925	-41.93	≤-25.51	PASS
11A	Ant2	High	5825	5925~5935	-42.65	≤-27	PASS
11N20MIMO	Ant1	Low	5745	5720~5725	-36.43	≤19.23	PASS
11N20MIMO	Ant1	Low	5745	5700~5720	-42.55	≤12.08	PASS
11N20MIMO	Ant1	Low	5745	5650~5700	-45.88	≤-26.10	PASS
11N20MIMO	Ant1	Low	5745	5760~5650	-45.37	≤-27	PASS
11N20MIMO	Ant2	Low	5745	5720~5725	-37.4	≤20.27	PASS
11N20MIMO	Ant2	Low	5745	5700~5720	-42.32	≤10.41	PASS
11N20MIMO	Ant2	Low	5745	5650~5700	-44.41	≤-26.70	PASS
11N20MIMO	Ant2	Low	5745	5760~5650	-42.37	≤-27	PASS
11N20MIMO	Ant1	High	5825	5850~5855	-44.53	≤16.03	PASS
11N20MIMO	Ant1	High	5825	5855~5875	-43.5	≤10.44	PASS
11N20MIMO	Ant1	High	5825	5875~5925	-45.68	≤-26.51	PASS
11N20MIMO	Ant1	High	5825	5925~5935	-44.73	≤-27	PASS
11N20MIMO	Ant2	High	5825	5850~5855	-42.16	≤15.73	PASS
11N20MIMO	Ant2	High	5825	5855~5875	-42.72	≤10.36	PASS
11N20MIMO	Ant2	High	5825	5875~5925	-43.96	≤-26.21	PASS
11N20MIMO	Ant2	High	5825	5925~5935	-42.47	≤-27	PASS
11N40MIMO	Ant1	Low	5755	5720~5725	-33.74	≤15.74	PASS
11N40MIMO	Ant1	Low	5755	5700~5720	-33.45	≤14.03	PASS
11N40MIMO	Ant1	Low	5755	5650~5700	-44.94	≤-26.90	PASS
11N40MIMO	Ant1	Low	5755	5780~5650	-44.61	≤-27	PASS
11N40MIMO	Ant2	Low	5755	5720~5725	-37.98	≤15.74	PASS
11N40MIMO	Ant2	Low	5755	5700~5720	-38.01	≤12.74	PASS
11N40MIMO	Ant2	Low	5755	5650~5700	-42.99	≤-26.70	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11N40MIMO	Ant2	Low	5755	5780~5650	-42.69	≤-27	PASS
11N40MIMO	Ant1	High	5795	5850~5855	-44.8	≤16.79	PASS
11N40MIMO	Ant1	High	5795	5855~5875	-45.05	≤10.34	PASS
11N40MIMO	Ant1	High	5795	5875~5925	-45.86	≤-26.95	PASS
11N40MIMO	Ant1	High	5795	5925~5935	-44.88	≤-27	PASS
11N40MIMO	Ant2	High	5795	5850~5855	-45.11	≤15.66	PASS
11N40MIMO	Ant2	High	5795	5855~5875	-42.04	≤10.85	PASS
11N40MIMO	Ant2	High	5795	5875~5925	-43.13	≤-26.59	PASS
11N40MIMO	Ant2	High	5795	5925~5935	-43.85	≤-27	PASS
11AC20MIMO	Ant1	Low	5745	5720~5725	-33.99	≤20.27	PASS
11AC20MIMO	Ant1	Low	5745	5700~5720	-37.94	≤15.37	PASS
11AC20MIMO	Ant1	Low	5745	5650~5700	-44.68	≤-26.02	PASS
11AC20MIMO	Ant1	Low	5745	5760~5650	-45.31	≤-27	PASS
11AC20MIMO	Ant2	Low	5745	5720~5725	-37.72	≤18.70	PASS
11AC20MIMO	Ant2	Low	5745	5700~5720	-42.62	≤10.54	PASS
11AC20MIMO	Ant2	Low	5745	5650~5700	-44.16	≤-26.87	PASS
11AC20MIMO	Ant2	Low	5745	5760~5650	-43.12	≤-27	PASS
11AC20MIMO	Ant1	High	5825	5850~5855	-43.89	≤16.03	PASS
11AC20MIMO	Ant1	High	5825	5855~5875	-43.12	≤10.06	PASS
11AC20MIMO	Ant1	High	5825	5875~5925	-46.08	≤-26.71	PASS
11AC20MIMO	Ant1	High	5825	5925~5935	-44.93	≤-27	PASS
11AC20MIMO	Ant2	High	5825	5850~5855	-42.04	≤15.73	PASS
11AC20MIMO	Ant2	High	5825	5855~5875	-42.45	≤10.63	PASS
11AC20MIMO	Ant2	High	5825	5875~5925	-42.48	≤-25.91	PASS
11AC20MIMO	Ant2	High	5825	5925~5935	-42.58	≤-27	PASS
11AC40MIMO	Ant1	Low	5755	5720~5725	-34.86	≤16.97	PASS
11AC40MIMO	Ant1	Low	5755	5700~5720	-36.76	≤12.93	PASS
11AC40MIMO	Ant1	Low	5755	5650~5700	-45.25	≤-26.80	PASS
11AC40MIMO	Ant1	Low	5755	5780~5650	-43.58	≤-27	PASS
11AC40MIMO	Ant2	Low	5755	5720~5725	-36.45	≤17.89	PASS
11AC40MIMO	Ant2	Low	5755	5700~5720	-33.77	≤15.24	PASS
11AC40MIMO	Ant2	Low	5755	5650~5700	-43.63	≤-26.80	PASS
11AC40MIMO	Ant2	Low	5755	5780~5650	-42.22	≤-27	PASS
11AC40MIMO	Ant1	High	5795	5850~5855	-44.68	≤17.54	PASS
11AC40MIMO	Ant1	High	5795	5855~5875	-45.33	≤10.29	PASS
11AC40MIMO	Ant1	High	5795	5875~5925	-45.61	≤-26.95	PASS
11AC40MIMO	Ant1	High	5795	5925~5935	-46.07	≤-27	PASS
11AC40MIMO	Ant2	High	5795	5850~5855	-44.09	≤15.66	PASS
11AC40MIMO	Ant2	High	5795	5855~5875	-42.51	≤10.62	PASS
11AC40MIMO	Ant2	High	5795	5875~5925	-43.18	≤-26.22	PASS
11AC40MIMO	Ant2	High	5795	5925~5935	-42.24	≤-27	PASS
11AC80MIMO	Ant1	Low	5775	5720~5725	-34.45	≤16.35	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AC80MIMO	Ant1	Low	5775	5700~5720	-35.96	≤10.35	PASS
11AC80MIMO	Ant1	Low	5775	5650~5700	-42.36	≤-24.62	PASS
11AC80MIMO	Ant1	Low	5775	5800~5650	-43.66	≤-27	PASS
11AC80MIMO	Ant1	High	5775	5850~5855	-40.55	≤15.84	PASS
11AC80MIMO	Ant1	High	5775	5855~5875	-42.23	≤10.45	PASS
11AC80MIMO	Ant1	High	5775	5875~5925	-43.26	≤-26.46	PASS
11AC80MIMO	Ant1	High	5775	5925~5935	-41.51	≤-27	PASS
11AC80MIMO	Ant2	Low	5775	5720~5725	-42.47	≤15.65	PASS
11AC80MIMO	Ant2	Low	5775	5700~5720	-42.04	≤10.66	PASS
11AC80MIMO	Ant2	Low	5775	5650~5700	-41.56	≤-25.31	PASS
11AC80MIMO	Ant2	Low	5775	5800~5650	-42.05	≤-27	PASS
11AC80MIMO	Ant2	High	5775	5850~5855	-43.93	≤16.26	PASS
11AC80MIMO	Ant2	High	5775	5855~5875	-42.61	≤10.19	PASS
11AC80MIMO	Ant2	High	5775	5875~5925	-42.8	≤-26.60	PASS
11AC80MIMO	Ant2	High	5775	5925~5935	-41.85	≤-27	PASS
11AX20MIMO	Ant1	Low	5745	5720~5725	-32.02	≤21.06	PASS
11AX20MIMO	Ant1	Low	5745	5700~5720	-36.37	≤15.43	PASS
11AX20MIMO	Ant1	Low	5745	5650~5700	-46.08	≤-26.87	PASS
11AX20MIMO	Ant1	Low	5745	5760~5650	-45.26	≤-27	PASS
11AX20MIMO	Ant2	Low	5745	5720~5725	-40.95	≤16.34	PASS
11AX20MIMO	Ant2	Low	5745	5700~5720	-43.44	≤10.57	PASS
11AX20MIMO	Ant2	Low	5745	5650~5700	-44.62	≤-26.79	PASS
11AX20MIMO	Ant2	Low	5745	5760~5650	-43.57	≤-27	PASS
11AX20MIMO	Ant1	High	5825	5850~5855	-43.89	≤15.73	PASS
11AX20MIMO	Ant1	High	5825	5855~5875	-43.7	≤10.47	PASS
11AX20MIMO	Ant1	High	5825	5875~5925	-45.45	≤-26.11	PASS
11AX20MIMO	Ant1	High	5825	5925~5935	-44.54	≤-27	PASS
11AX20MIMO	Ant2	High	5825	5850~5855	-42.64	≤15.73	PASS
11AX20MIMO	Ant2	High	5825	5855~5875	-42.39	≤10.21	PASS
11AX20MIMO	Ant2	High	5825	5875~5925	-44.18	≤-26.51	PASS
11AX20MIMO	Ant2	High	5825	5925~5935	-42.96	≤-27	PASS
11AX40MIMO	Ant1	Low	5755	5720~5725	-28.18	≤16.97	PASS
11AX40MIMO	Ant1	Low	5755	5700~5720	-33.31	≤13.24	PASS
11AX40MIMO	Ant1	Low	5755	5650~5700	-46.07	≤-26.30	PASS
11AX40MIMO	Ant1	Low	5755	5780~5650	-44.1	≤-27	PASS
11AX40MIMO	Ant2	Low	5755	5720~5725	-32.08	≤17.28	PASS
11AX40MIMO	Ant2	Low	5755	5700~5720	-37.59	≤13.20	PASS
11AX40MIMO	Ant2	Low	5755	5650~5700	-43.34	≤-26.40	PASS
11AX40MIMO	Ant2	Low	5755	5780~5650	-42.77	≤-27	PASS
11AX40MIMO	Ant1	High	5795	5850~5855	-45.83	≤15.66	PASS
11AX40MIMO	Ant1	High	5795	5855~5875	-45.73	≤10.11	PASS
11AX40MIMO	Ant1	High	5795	5875~5925	-46.06	≤-26.71	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX40MIMO	Ant1	High	5795	5925~5935	-45.93	≤-27	PASS
11AX40MIMO	Ant2	High	5795	5850~5855	-42.46	≤16.03	PASS
11AX40MIMO	Ant2	High	5795	5855~5875	-43.58	≤10.20	PASS
11AX40MIMO	Ant2	High	5795	5875~5925	-43.13	≤-25.00	PASS
11AX40MIMO	Ant2	High	5795	5925~5935	-43.46	≤-27	PASS
11AX80MIMO	Ant1	Low	5775	5720~5725	-34.56	≤16.00	PASS
11AX80MIMO	Ant1	Low	5775	5700~5720	-32.89	≤12.74	PASS
11AX80MIMO	Ant1	Low	5775	5650~5700	-38.65	≤-25.65	PASS
11AX80MIMO	Ant1	Low	5775	5800~5650	-39.95	≤-27	PASS
11AX80MIMO	Ant1	High	5775	5850~5855	-42.97	≤15.84	PASS
11AX80MIMO	Ant1	High	5775	5855~5875	-40.3	≤11.28	PASS
11AX80MIMO	Ant1	High	5775	5875~5925	-38.86	≤-24.27	PASS
11AX80MIMO	Ant1	High	5775	5925~5935	-42.38	≤-27	PASS
11AX80MIMO	Ant2	Low	5775	5720~5725	-35.27	≤16.00	PASS
11AX80MIMO	Ant2	Low	5775	5700~5720	-33.81	≤10.44	PASS
11AX80MIMO	Ant2	Low	5775	5650~5700	-42.71	≤-26.91	PASS
11AX80MIMO	Ant2	Low	5775	5800~5650	-42.01	≤-27	PASS
11AX80MIMO	Ant2	High	5775	5850~5855	-37.38	≤19.21	PASS
11AX80MIMO	Ant2	High	5775	5855~5875	-41.4	≤10.45	PASS
11AX80MIMO	Ant2	High	5775	5875~5925	-41.75	≤-26.32	PASS
11AX80MIMO	Ant2	High	5775	5925~5935	-40.89	≤-27	PASS

Note: 1. The Margin plus the antenna gain also meets the limit.

2. ANT 1 and ANT 2 worst case result are over 3 dB margin below the limit ,so MIMO mode is also compliance with the requirement.

Test Graphs B1/2/3



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com







Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com







Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

























Test Graphs B4



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com













Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com







Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com








Appendix F: DFS Detection Thresholds

Test Result

TestMode	Frequency[dbm]	Radar Type	Result	Limit[dbm]	Verdict
11A	5300	Type0	-62.15	-62.00	PASS
11A	5580	Type0	-62.23	-62.00	PASS
11AX80SISO	5290	Type0	-62.06	-62.00	PASS
11AX80SISO	5530	Type0	-62.02	-62.00	PASS

Note: The antenna gain is grater than 0dBi, the experiment employed a harsher approach.


Test Graphs



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix G: Channel Move Time and Channel Closing

Transmission Time

Test Result

TestMode	Frequency[MHz]	CCTT[ms]	Limit[ms]	CMT[ms]	Limit[ms]	Verdict
11A	5300	200+1.3	200+60	219.6	10000	PASS
11A	5580	200+1.3	200+60	211.8	10000	PASS
11AX80SISO	5290	200+3.9	200+60	233.9	10000	PASS
11AX80SISO	5530	200+1.3	200+60	207.9	10000	PASS


Test Graphs



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix H: Non-Occupancy Period

Test Result

TestMode	Frequency[MHz]	Result	Limit[s]	Verdict
11A	5300	see test graph	≥1800	PASS
11A	5580	see test graph	≥1800	PASS
11AX80SISO	5290	see test graph	≥1800	PASS
11AX80SISO	5530	see test graph	≥1800	PASS


Test Graphs



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



---END---