



Date: 07-Jun-2017

Re: § 2.933 Change in identification of equipment

To Whom It May Concern:

This change in identification of equipment request applies to the original FCC ID: ZTL-RFSC1, granted on 12/21/2012. The equipment bearing the modified identification (new FCC ID: 2ABEDU62-900M) is electrically identical to the original equipment. Therefore, the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

Stephen M. Penley
Sr. Staff Product Engineer
Panduit Corp.

(770) 889-1800 x 87308
stmp@panduit.com