

FIGURE 7
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
COVER REMOVED




FIGURE 8
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
MAIN BOARD (FRONT SIDE)




FIGURE 9
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
MAIN BOARD (BACK SIDE)




FIGURE 10
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
CHIP & CRYSTAL ON MAIN BOARD




FIGURE 11
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
RF BOARD (FRONT SIDE)




FIGURE 12
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
RF BOARD (BACK SIDE)




FIGURE 13
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
RF BOARD (SHIELDED COVER REMOVED)




FIGURE 14
LEAK GOPHER RECEIVER (M/N: C9201T-W470-D05-T)
CHIP & CRYSTAL ON RF BOARD

