






17:47:42 18.10.2023

11BE80MIMO_Ant15_6465_484+242_OFDMA_2




17:51:24 18.10.2023

11BE80MIMO_Ant15_6465_484+242_OFDMA_3




17:54:41 18.10.2023

11BE80MIMO_Ant15_6465_484+242_OFDMA_4




17:58:03 18.10.2023


11BE80MIMO_Ant9_6545_484+242_OFDMA_1



11BE80MIMO_Ant9_6545_484+242_OFDMA_2




11BE80MIMO_Ant9_6545_484+242_OFDMA_3




10:10:09 19.10.2023

11BE80MIMO_Ant9_6545_484+242_OFDMA_4




10:13:53 19.10.2023

11BE80MIMO_Ant15_6545_484+242_OFDMA_1




10:17:23 19.10.2023

11BE80MIMO_Ant15_6545_484+242_OFDMA_2




10:20:25 19.10.2023

11BE80MIMO_Ant15_6545_484+242_OFDMA_3




10:23:29 19.10.2023

11BE80MIMO_Ant15_6545_484+242_OFDMA_4




10:26:30 19.10.2023


11BE80MIMO_Ant9_6625_484+242_OFDMA_1



11BE80MIMO_Ant9_6625_484+242_OFDMA_2




11BE80MIMO_Ant9_6625_484+242_OFDMA_3




10:36:18 19.10.2023

11BE80MIMO_Ant9_6625_484+242_OFDMA_4




10:39:30 19.10.2023


11BE80MIMO_Ant15_6625_484+242_OFDMA_1



11BE80MIMO_Ant15_6625_484+242_OFDMA_2




11BE80MIMO_Ant15_6625_484+242_OFDMA_3




10:49:27 19.10.2023

11BE80MIMO_Ant15_6625_484+242_OFDMA_4




10:52:58 19.10.2023

11BE80MIMO_Ant9_6705_484+242_OFDMA_1




10:56:04 19.10.2023

11BE80MIMO_Ant9_6705_484+242_OFDMA_2




11:00:04 19.10.2023

11BE80MIMO_Ant9_6705_484+242_OFDMA_3




11:03:09 19.10.2023

11BE80MIMO_Ant9_6705_484+242_OFDMA_4




11:06:29 19.10.2023

11BE80MIMO_Ant15_6705_484+242_OFDMA_1




11:09:54 19.10.2023

11BE80MIMO_Ant15_6705_484+242_OFDMA_2




11:13:30 19.10.2023

11BE80MIMO_Ant15_6705_484+242_OFDMA_3




11:16:54 19.10.2023

11BE80MIMO_Ant15_6705_484+242_OFDMA_4




11:20:11 19.10.2023

11BE80MIMO_Ant9_6785_484+242_OFDMA_1




16:06:36 19.10.2023

11BE80MIMO_Ant9_6785_484+242_OFDMA_2




16:09:57 19.10.2023


11BE80MIMO_Ant9_6785_484+242_OFDMA_3




11BE80MIMO_Ant9_6785_484+242_OFDMA_4




11BE80MIMO_Ant15_6785_484+242_OFDMA_1



11BE80MIMO_Ant15_6785_484+242_OFDMA_2




11BE80MIMO_Ant15_6785_484+242_OFDMA_3




16:47:47 19.10.2023

11BE80MIMO_Ant15_6785_484+242_OFDMA_4




16:56:06 19.10.2023

11BE80MIMO_Ant9_6865_484+242_OFDMA_1




14:01:55 20.10.2023

11BE80MIMO_Ant9_6865_484+242_OFDMA_2




14:03:08 20.10.2023

11BE80MIMO_Ant9_6865_484+242_OFDMA_3




14:08:44 20.10.2023

11BE80MIMO_Ant9_6865_484+242_OFDMA_4




14:11:51 20.10.2023

11BE80MIMO_Ant15_6865_484+242_OFDMA_1




14:15:40 20.10.2023

11BE80MIMO_Ant15_6865_484+242_OFDMA_2




14:19:47 20.10.2023

11BE80MIMO_Ant15_6865_484+242_OFDMA_3




14:22:57 20.10.2023

11BE80MIMO_Ant15_6865_484+242_OFDMA_4




14:37:53 20.10.2023

11BE80MIMO_Ant9_6945_484+242_OFDMA_1




14:42:01 20.10.2023

11BE80MIMO_Ant9_6945_484+242_OFDMA_2




14:43:59 20.10.2023

11BE80MIMO_Ant9_6945_484+242_OFDMA_3




14:49:54 20.10.2023

11BE80MIMO_Ant9_6945_484+242_OFDMA_4




14:52:59 20.10.2023

11BE80MIMO_Ant15_6945_484+242_OFDMA_1




14:56:24 20.10.2023

11BE80MIMO_Ant15_6945_484+242_OFDMA_2




14:59:25 20.10.2023

11BE80MIMO_Ant15_6945_484+242_OFDMA_3




15:14:50 20.10.2023

11BE80MIMO_Ant15_6945_484+242_OFDMA_4




15:18:49 20.10.2023

11BE80MIMO_Ant9_7025_484+242_OFDMA_1




15:22:11 20.10.2023

11BE80MIMO_Ant9_7025_484+242_OFDMA_2




15:25:28 20.10.2023

11BE80MIMO_Ant9_7025_484+242_OFDMA_3




15:29:04 20.10.2023

11BE80MIMO_Ant9_7025_484+242_OFDMA_4




15:32:01 20.10.2023

11BE80MIMO_Ant15_7025_484+242_OFDMA_1




15:35:15 20.10.2023

11BE80MIMO_Ant15_7025_484+242_OFDMA_2




15:38:22 20.10.2023

11BE80MIMO_Ant15_7025_484+242_OFDMA_3




15:41:22 20.10.2023

11BE80MIMO_Ant15_7025_484+242_OFDMA_4




15:44:24 20.10.2023


11BE160MIMO_Ant9_6025_996+484_OFDMA_1



11BE160MIMO_Ant9_6025_996+484_OFDMA_2




11BE160MIMO_Ant9_6025_996+484_OFDMA_3




17:09:38 20.10.2023

11BE160MIMO_Ant9_6025_996+484_OFDMA_4




17:12:56 20.10.2023

11BE160MIMO_Ant9_6025_996+484+242_OFDMA_1




15:44:59 23.10.2023

11BE160MIMO_Ant9_6025_996+484+242_OFDMA_2




15:48:33 23.10.2023


11BE160MIMO_Ant9_6025_996+484+242_OFDMA_3




11BE160MIMO_Ant9_6025_996+484+242_OFDMA_4




11BE160MIMO_Ant9_6025_996+484+242_OFDMA_5



11BE160MIMO_Ant9_6025_996+484+242_OFDMA_6




11BE160MIMO_Ant9_6025_996+484+242_OFDMA_7




16:04:54 23.10.2023

11BE160MIMO_Ant9_6025_996+484+242_OFDMA_8




16:08:13 23.10.2023

11BE160MIMO_Ant15_6025_996+484_OFDMA_1




17:31:06 20.10.2023

11BE160MIMO_Ant15_6025_996+484_OFDMA_2




17:34:14 20.10.2023

11BE160MIMO_Ant15_6025_996+484_OFDMA_3




17:37:26 20.10.2023

11BE160MIMO_Ant15_6025_996+484_OFDMA_4




17:40:31 20.10.2023


11BE160MIMO_Ant15_6025_996+484+242_OFDMA_1



11BE160MIMO_Ant15_6025_996+484+242_OFDMA_2




11BE160MIMO_Ant15_6025_996+484+242_OFDMA_3




16:17:47 23.10.2023

11BE160MIMO_Ant15_6025_996+484+242_OFDMA_4




16:20:50 23.10.2023

11BE160MIMO_Ant15_6025_996+484+242_OFDMA_5




16:23:53 23.10.2023

11BE160MIMO_Ant15_6025_996+484+242_OFDMA_6




16:28:28 23.10.2023

11BE160MIMO_Ant15_6025_996+484+242_OFDMA_7




16:31:47 23.10.2023

11BE160MIMO_Ant15_6025_996+484+242_OFDMA_8




16:34:52 23.10.2023

11BE160MIMO_Ant9_6185_996+484_OFDMA_1




10:21:23 23.10.2023

11BE160MIMO_Ant9_6185_996+484_OFDMA_2




10:25:43 23.10.2023

11BE160MIMO_Ant9_6185_996+484_OFDMA_3




10:29:13 23.10.2023

11BE160MIMO_Ant9_6185_996+484_OFDMA_4




10:32:42 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_1




16:37:54 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_2




16:41:03 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_3




16:44:09 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_4




16:47:06 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_5




16:50:08 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_6




16:53:05 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_7




16:56:04 23.10.2023

11BE160MIMO_Ant9_6185_996+484+242_OFDMA_8




16:59:15 23.10.2023

11BE160MIMO_Ant15_6185_996+484_OFDMA_1




10:36:12 23.10.2023

11BE160MIMO_Ant15_6185_996+484_OFDMA_2




10:39:36 23.10.2023


11BE160MIMO_Ant15_6185_996+484_OFDMA_3



11BE160MIMO_Ant15_6185_996+484_OFDMA_4




11BE160MIMO_Ant15_6185_996+484+242_OFDMA_1




17:02:19 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_2




17:05:21 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_3




17:08:27 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_4




17:11:39 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_5




17:14:45 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_6




17:17:45 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_7




17:21:42 23.10.2023

11BE160MIMO_Ant15_6185_996+484+242_OFDMA_8




17:25:14 23.10.2023

11BE160MIMO_Ant9_6345_996+484_OFDMA_1




10:49:18 23.10.2023

11BE160MIMO_Ant9_6345_996+484_OFDMA_2




10:52:28 23.10.2023

11BE160MIMO_Ant9_6345_996+484_OFDMA_3




10:55:40 23.10.2023

11BE160MIMO_Ant9_6345_996+484_OFDMA_4




10:58:46 23.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_1




09:57:06 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_2




10:00:14 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_3




10:16:16 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_4




10:26:58 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_5




10:33:30 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_6




10:36:51 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_7




10:39:47 24.10.2023

11BE160MIMO_Ant9_6345_996+484+242_OFDMA_8




10:43:16 24.10.2023

11BE160MIMO_Ant15_6345_996+484_OFDMA_1




11:02:59 23.10.2023

11BE160MIMO_Ant15_6345_996+484_OFDMA_2




11:06:14 23.10.2023

11BE160MIMO_Ant15_6345_996+484_OFDMA_3




11:09:44 23.10.2023

11BE160MIMO_Ant15_6345_996+484_OFDMA_4




11:13:05 23.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_1




10:47:54 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_2




10:51:06 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_3




10:56:06 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_4




10:59:10 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_5




11:02:22 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_6




11:03:32 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_7




11:08:29 24.10.2023

11BE160MIMO_Ant15_6345_996+484+242_OFDMA_8




11:11:42 24.10.2023


11BE160MIMO_Ant9_6505_996+484_OFDMA_1



11BE160MIMO_Ant9_6505_996+484_OFDMA_2




11BE160MIMO_Ant9_6505_996+484_OFDMA_3




11:30:09 23.10.2023

11BE160MIMO_Ant9_6505_996+484_OFDMA_4




11:33:26 23.10.2023

11BE160MIMO_Ant9_6505_996+484+242_OFDMA_1




11:15:10 24.10.2023

11BE160MIMO_Ant9_6505_996+484+242_OFDMA_2




11:18:19 24.10.2023

11BE160MIMO_Ant9_6505_996+484+242_OFDMA_3



11:21:58 24.10.2023

11BE160MIMO_Ant9_6505_996+484+242_OFDMA_4



13:39:16 24.10.2023

11BE160MIMO_Ant9_6505_996+484+242_OFDMA_5