




11AX80MIMO_Ant1_6705




11AX80MIMO_Ant1_6945




11AX80MIMO_Ant1_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945




11AX20MIMO_Ant1_6155_Center_6155_1




11AX20MIMO_Ant1_6155_Center_6155_2


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6155_Center_6155_3




11AX20MIMO_Ant1_6155_Center_6155_4




11AX20MIMO_Ant1_6155_Center_6155_5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6155_Center_6155_6




11AX20MIMO_Ant1_6155_Center_6155_7




11AX20MIMO_Ant1_6155_Center_6155_8


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6155_Center_6155_9




11AX20MIMO_Ant1_6155_Center_6155_10




11AX20MIMO_Ant1_6455_Center_6455_1


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6455_Center_6455_2




11AX20MIMO_Ant1_6455_Center_6455_3




11AX20MIMO_Ant1_6455_Center_6455_4


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6455_Center_6455_5




11AX20MIMO_Ant1_6455_Center_6455_6




11AX20MIMO_Ant1_6455_Center_6455_7


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6455_Center_6455_8




11AX20MIMO_Ant1_6455_Center_6455_9




11AX20MIMO_Ant1_6455_Center_6455_10


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_1




11AX20MIMO_Ant1_6615_Center_6615_2




11AX20MIMO_Ant1_6615_Center_6615_3


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_4




11AX20MIMO_Ant1_6615_Center_6615_5




11AX20MIMO_Ant1_6615_Center_6615_6


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_7




11AX20MIMO_Ant1_6615_Center_6615_8




11AX20MIMO_Ant1_6615_Center_6615_9


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6615_Center_6615_10




11AX20MIMO_Ant1_7015_Center_7015_1




11AX20MIMO_Ant1_7015_Center_7015_2


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_7015_Center_7015_3




11AX20MIMO_Ant1_7015_Center_7015_4




11AX20MIMO_Ant1_7015_Center_7015_5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_7015_Center_7015_6




11AX20MIMO_Ant1_7015_Center_7015_7




11AX20MIMO_Ant1_7015_Center_7015_8

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_7015_Center_7015_9




11AX20MIMO_Ant1_7015_Center_7015_10




11AX80MIMO_Ant1_6145_High_6110_1


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_High_6110_2




11AX80MIMO_Ant1_6145_High_6110_3




11AX80MIMO_Ant1_6145_High_6110_4

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_High_6110_5




11AX80MIMO_Ant1_6145_High_6110_6




11AX80MIMO_Ant1_6145_High_6110_7


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_High_6110_8




11AX80MIMO_Ant1_6145_High_6110_9




11AX80MIMO_Ant1_6145_High_6110_10

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Center_6145_1




11AX80MIMO_Ant1_6145_Center_6145_2




11AX80MIMO_Ant1_6145_Center_6145_3


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Center_6145_4




11AX80MIMO_Ant1_6145_Center_6145_5




11AX80MIMO_Ant1_6145_Center_6145_6


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Center_6145_7




11AX80MIMO_Ant1_6145_Center_6145_8




11AX80MIMO_Ant1_6145_Center_6145_9


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Center_6145_10




11AX80MIMO_Ant1_6145_Low_6180_1




11AX80MIMO_Ant1_6145_Low_6180_2


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Low_6180_3




11AX80MIMO_Ant1_6145_Low_6180_4




11AX80MIMO_Ant1_6145_Low_6180_5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Low_6180_6




11AX80MIMO_Ant1_6145_Low_6180_7




11AX80MIMO_Ant1_6145_Low_6180_8


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6145_Low_6180_9




11AX80MIMO_Ant1_6145_Low_6180_10




11AX80MIMO_Ant1_6465_High_6430_1


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_High_6430_2



11AX80MIMO_Ant1_6465_High_6430_3



11AX80MIMO_Ant1_6465_High_6430_4

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.