




11AX80MIMO_Ant1_6465_High_6430_5




11AX80MIMO_Ant1_6465_High_6430_6




11AX80MIMO_Ant1_6465_High_6430_7


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_High_6430_8




11AX80MIMO_Ant1_6465_High_6430_9




11AX80MIMO_Ant1_6465_High_6430_10


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Center_6465_1




11AX80MIMO_Ant1_6465_Center_6465_2




11AX80MIMO_Ant1_6465_Center_6465_3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Center_6465_4




11AX80MIMO_Ant1_6465_Center_6465_5




11AX80MIMO_Ant1_6465_Center_6465_6


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Center_6465_7




11AX80MIMO_Ant1_6465_Center_6465_8




11AX80MIMO_Ant1_6465_Center_6465_9


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Center_6465_10




11AX80MIMO_Ant1_6465_Low_6500_1




11AX80MIMO_Ant1_6465_Low_6500_2


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Low_6500_3




11AX80MIMO_Ant1_6465_Low_6500_4




11AX80MIMO_Ant1_6465_Low_6500_5

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Low_6500_6




11AX80MIMO_Ant1_6465_Low_6500_7




11AX80MIMO_Ant1_6465_Low_6500_8


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465_Low_6500_9




11AX80MIMO_Ant1_6465_Low_6500_10




11AX80MIMO_Ant1_6705_High_6670_1


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_High_6670_2




11AX80MIMO_Ant1_6705_High_6670_3




11AX80MIMO_Ant1_6705_High_6670_4


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_High_6670_5




11AX80MIMO_Ant1_6705_High_6670_6




11AX80MIMO_Ant1_6705_High_6670_7


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_High_6670_8




11AX80MIMO_Ant1_6705_High_6670_9




11AX80MIMO_Ant1_6705_High_6670_10

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Center_6705_1




11AX80MIMO_Ant1_6705_Center_6705_2




11AX80MIMO_Ant1_6705_Center_6705_3


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Center_6705_4




11AX80MIMO_Ant1_6705_Center_6705_5




11AX80MIMO_Ant1_6705_Center_6705_6

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Center_6705_7




11AX80MIMO_Ant1_6705_Center_6705_8




11AX80MIMO_Ant1_6705_Center_6705_9


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Center_6705_10




11AX80MIMO_Ant1_6705_Low_6740_1




11AX80MIMO_Ant1_6705_Low_6740_2


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Low_6740_3




11AX80MIMO_Ant1_6705_Low_6740_4




11AX80MIMO_Ant1_6705_Low_6740_5


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Low_6740_6




11AX80MIMO_Ant1_6705_Low_6740_7




11AX80MIMO_Ant1_6705_Low_6740_8


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705_Low_6740_9




11AX80MIMO_Ant1_6705_Low_6740_10




11AX80MIMO_Ant1_6945_High_6910_1


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_High_6910_2




11AX80MIMO_Ant1_6945_High_6910_3




11AX80MIMO_Ant1_6945_High_6910_4

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_High_6910_5




11AX80MIMO_Ant1_6945_High_6910_6




11AX80MIMO_Ant1_6945_High_6910_7


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_High_6910_8




11AX80MIMO_Ant1_6945_High_6910_9




11AX80MIMO_Ant1_6945_High_6910_10

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_Center_6945_1




11AX80MIMO_Ant1_6945_Center_6945_2




11AX80MIMO_Ant1_6945_Center_6945_3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_Center_6945_4




11AX80MIMO_Ant1_6945_Center_6945_5




11AX80MIMO_Ant1_6945_Center_6945_6

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_Center_6945_7




11AX80MIMO_Ant1_6945_Center_6945_8




11AX80MIMO_Ant1_6945_Center_6945_9


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945_Center_6945_10



11AX80MIMO_Ant1_6945_Low_6980_1



11AX80MIMO_Ant1_6945_Low_6980_2

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.