

Londa industry limited

Dec. 19, 2014

To: FCC

From: SIEMIC, INC.

RE: Applicant: Londa industry limited, FCC ID: 2AC5CFQ-04, Request for supercede of test report 、 External/Internal Photo exhibits、 Label 、 Antenna location and Test Setup Photo.

Per customer's request, Update all photo involving EUT. They confuse the photos to other project FCC ID: 2AC5CD-320, therefore, we are asking to kindly replace the test report 、 External/Internal Photo exhibits、 Label 、 Antenna location and Test Setup Photo with revised copies which will not affect the test result.

The sample is correct when testing, but put wrong EUT photo and setup photos in reports and other documents which are from another FCC ID: 2AC5CD-320.

You can find the changes on
Part 15B report P21-P22
Part 22/24 report P72
SAR report P13 and P20-P25
of the revised test report,

Thank you,

Tory Xie

Tory Xie

Londa industry limited

ROOM636, Gongyi block, No.55 zhenhua road, Shenzhen, China

Tel: 013713558722

Fax: 0755-83214456