

SUPERSONIC INC
6555 BANDINI BOULEVARD CA 90040-3119 USA

Date: 2026-4-7

To:
Federal Communication Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern,

Original **FCC ID: 2AGFW-M01**; Model Number: M01, M02


New **FCC ID: 2AC5R-SC-601G**; Model Number: **M01, M02, SC-601G**

This is to advise and officially, that we, **SUPERSONIC INC** hereby declare that the product same and only FCC ID, product model number and trade mark difference as market requirement;

The original test results continue to be representative of and applicable to the equipment of the new FCC ID;

If you have any query, please feel free to contact me.

Sincerely,



Name / Title: David Gholiani/General manager
Company: SUPERSONIC INC
Address: 6555 BANDINI BOULEVARD CA 90040-3119 USA
Phone: (323) 201-5060
Fax: N/A
E-Mail: David@SupersonicINC.com