




Annex B

Internal Photo

Report No.: HK2404221950-1E/2E

Page 1 of 2





Coil Antenna

