




Plot 4.9
Ant 2, Tx @ 2462MHz 802.11b




Plot 4.10
Ant 3, Tx @ 2412MHz 802.11b




Plot 4.11
Ant 3, Tx @ 2437MHz 802.11b




Plot 4.12
Ant 3, Tx @ 2462MHz 802.11b




Plot 4.13
Ant 0, Tx @ 2412MHz 802.11g




Plot 4.14
Ant 0, Tx @ 2437MHz 802.11g




Plot 4.15
Ant 0, Tx @ 2462MHz 802.11g




Plot 4.16
Ant 1, Tx @ 2412MHz 802.11g




Plot 4.17
Ant 1, Tx @ 2437MHz 802.11g




Plot 4.18
Ant 1, Tx @ 2462MHz 802.11g




Plot 4.19
Ant 2, Tx @ 2412MHz 802.11g




Plot 4.20
Ant 2, Tx @ 2437MHz 802.11g




Plot 4.21
Ant 2, Tx @ 2462MHz 802.11g




Plot 4.22
Ant 3, Tx @ 2412MHz 802.11g



Plot 4.23
Ant 3, Tx @ 2437MHz 802.11g



Plot 4.24
Ant 3, Tx @ 2462MHz 802.11g



Test data continued in report number: 103224477MPK-002B (Pages: 127 to 194)