



Toronto July 15, 2014

To Whom It May Concern

Re: Tuning Procedure for the DRU-200 (FCC ID: 2ACLT-DRU200)

This is to affirm that a tuning procedure for the DRU-200 is not required as the signal outputs are at a fixed frequency and bandwidth. As such, no tuning procedure has been submitted as part of the FCC application.

Regards,

A handwritten signature in blue ink, appearing to read 'Ana Maria De Valencia', with a long horizontal line extending to the right.

Ana Maria De Valencia
Senior Manager, Government Relations
UBS Ltd.
400 Spinnaker Way
Vaughan, ON
CANADA L4K 5Y9
905 669 8533 x 141
905 669 8516 fax
416 271 7012 cell
www.uniquesys.com