


INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01


(Internal)



Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)



Report No.: 14071232HKG-002

Model : DO01




INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14071232HKG-002

Equipment Photographs

Model : DO01

(Internal)

