

## ANNEX B TEST SETUP PHOTOS

### B.1 Radiated Field Strength Measurement

Below 1 GHz




30 MHz-1 GHz (USB test mode)

Above 1 GHz



USB test mode

## B.2 Conducted Emission



USB Test Mode