



NVNT	ac20	5580	Ant2	21.54	Pass
NVNT	ac20	5700	Ant2	25.43	Pass
NVNT	ac20	5180	Ant3	26.476	Pass
NVNT	ac20	5200	Ant3	28.422	Pass
NVNT	ac20	5240	Ant3	20.287	Pass
NVNT	ac20	5260	Ant3	21.655	Pass
NVNT	ac20	5300	Ant3	25.571	Pass
NVNT	ac20	5320	Ant3	27.942	Pass
NVNT	ac20	5500	Ant3	27.009	Pass
NVNT	ac20	5580	Ant3	21.564	Pass
NVNT	ac20	5700	Ant3	25.505	Pass
NVNT	ac40	5190	Ant1	52.265	Pass
NVNT	ac40	5230	Ant1	41.284	Pass
NVNT	ac40	5270	Ant1	41.614	Pass
NVNT	ac40	5310	Ant1	53.028	Pass
NVNT	ac40	5510	Ant1	54.094	Pass
NVNT	ac40	5550	Ant1	41.124	Pass
NVNT	ac40	5670	Ant1	56.649	Pass
NVNT	ac40	5190	Ant2	54.618	Pass
NVNT	ac40	5230	Ant2	41.329	Pass
NVNT	ac40	5270	Ant2	41.037	Pass
NVNT	ac40	5310	Ant2	51.137	Pass
NVNT	ac40	5510	Ant2	53.364	Pass
NVNT	ac40	5550	Ant2	41.322	Pass
NVNT	ac40	5670	Ant2	57.473	Pass
NVNT	ac40	5190	Ant3	47.314	Pass
NVNT	ac40	5230	Ant3	40.978	Pass
NVNT	ac40	5270	Ant3	40.943	Pass
NVNT	ac40	5310	Ant3	49.741	Pass
NVNT	ac40	5510	Ant3	50.034	Pass
NVNT	ac40	5550	Ant3	41.186	Pass
NVNT	ac40	5670	Ant3	56.719	Pass
NVNT	ac80	5210	Ant1	96.084	Pass
NVNT	ac80	5290	Ant1	101.48	Pass
NVNT	ac80	5530	Ant1	100.294	Pass
NVNT	ac80	5610	Ant1	79.413	Pass
NVNT	ac80	5210	Ant2	102.72	Pass
NVNT	ac80	5290	Ant2	84.48	Pass
NVNT	ac80	5530	Ant2	85.367	Pass
NVNT	ac80	5610	Ant2	79.577	Pass
NVNT	ac80	5210	Ant3	98.812	Pass
NVNT	ac80	5290	Ant3	96.62	Pass
NVNT	ac80	5530	Ant3	88.168	Pass
NVNT	ac80	5610	Ant3	79.198	Pass
NVNT	ac160	5250	Ant1	168.725	Pass
NVNT	ac160	5570	Ant1	167.089	Pass
NVNT	ac160	5250	Ant2	165.476	Pass
NVNT	ac160	5570	Ant2	166.987	Pass
NVNT	ac160	5250	Ant3	167.415	Pass
NVNT	ac160	5570	Ant3	164.416	Pass
NVNT	ax20	5180	Ant1	26.637	Pass
NVNT	ax20	5200	Ant1	26.964	Pass
NVNT	ax20	5240	Ant1	19.938	Pass
NVNT	ax20	5260	Ant1	21.5	Pass
NVNT	ax20	5300	Ant1	27.744	Pass
NVNT	ax20	5320	Ant1	23.289	Pass
NVNT	ax20	5500	Ant1	25.77	Pass
NVNT	ax20	5580	Ant1	21.795	Pass
NVNT	ax20	5700	Ant1	25.411	Pass
NVNT	ax20	5180	Ant2	26.771	Pass
NVNT	ax20	5200	Ant2	23.98	Pass
NVNT	ax20	5240	Ant2	19.931	Pass
NVNT	ax20	5260	Ant2	21.699	Pass
NVNT	ax20	5300	Ant2	25.28	Pass
NVNT	ax20	5320	Ant2	25.32	Pass
NVNT	ax20	5500	Ant2	25.695	Pass
NVNT	ax20	5580	Ant2	21.405	Pass
NVNT	ax20	5700	Ant2	25.943	Pass
NVNT	ax20	5180	Ant3	24.89	Pass
NVNT	ax20	5200	Ant3	28.586	Pass
NVNT	ax20	5240	Ant3	19.885	Pass
NVNT	ax20	5260	Ant3	22.3	Pass
NVNT	ax20	5300	Ant3	26.849	Pass
NVNT	ax20	5320	Ant3	24.067	Pass
NVNT	ax20	5500	Ant3	26.966	Pass
NVNT	ax20	5580	Ant3	21.948	Pass
NVNT	ax20	5700	Ant3	24.2	Pass
NVNT	ax40	5190	Ant1	49.754	Pass
NVNT	ax40	5230	Ant1	40.148	Pass
NVNT	ax40	5270	Ant1	39.931	Pass
NVNT	ax40	5310	Ant1	46.656	Pass
NVNT	ax40	5510	Ant1	50.284	Pass
NVNT	ax40	5550	Ant1	40.301	Pass
NVNT	ax40	5670	Ant1	54.465	Pass
NVNT	ax40	5190	Ant2	55.662	Pass
NVNT	ax40	5230	Ant2	40.242	Pass
NVNT	ax40	5270	Ant2	40.142	Pass
NVNT	ax40	5310	Ant2	50.382	Pass
NVNT	ax40	5510	Ant2	45.892	Pass
NVNT	ax40	5550	Ant2	39.991	Pass
NVNT	ax40	5670	Ant2	53.41	Pass
NVNT	ax40	5190	Ant3	48.669	Pass
NVNT	ax40	5230	Ant3	40.11	Pass
NVNT	ax40	5270	Ant3	40.275	Pass



NVNT	ax40	5310	Ant3	48.925	Pass
NVNT	ax40	5510	Ant3	49.705	Pass
NVNT	ax40	5550	Ant3	40.249	Pass
NVNT	ax40	5670	Ant3	55.108	Pass
NVNT	ax80	5210	Ant1	91.05	Pass
NVNT	ax80	5290	Ant1	96.543	Pass
NVNT	ax80	5530	Ant1	80.037	Pass
NVNT	ax80	5610	Ant1	80.147	Pass
NVNT	ax80	5210	Ant2	86.383	Pass
NVNT	ax80	5290	Ant2	92.142	Pass
NVNT	ax80	5530	Ant2	81.63	Pass
NVNT	ax80	5610	Ant2	80.226	Pass
NVNT	ax80	5210	Ant3	82.587	Pass
NVNT	ax80	5290	Ant3	94.907	Pass
NVNT	ax80	5530	Ant3	89.066	Pass
NVNT	ax80	5610	Ant3	80.086	Pass
NVNT	ax160	5250	Ant1	162.006	Pass
NVNT	ax160	5570	Ant1	166.621	Pass
NVNT	ax160	5250	Ant2	165.541	Pass
NVNT	ax160	5570	Ant2	162.267	Pass
NVNT	ax160	5250	Ant3	161.903	Pass
NVNT	ax160	5570	Ant3	162.794	Pass















































































