

Shenzhen Wellcore Technology Co., Ltd.

Rm 700, Block B, ShenFang Building, Futian District, Shenzhen City, China

W903 Tune up Procedure

I would like to confirm this device does not have tune up information, because the tune up is fixed by the manufacturer.
Therefore, the user cannot tune up the device.

BT	0dBm $\pm$ 1.0