




3MHz_High_QPSK_1@14




3MHz_High_QPSK_15@0




3MHz_High_16QAM_1@14




3MHz_High_16QAM_15@0




5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24




5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24




5MHz_High_16QAM_25@0




10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0




10MHz_Low_16QAM_50@0




10MHz_High_QPSK_1@49




10MHz_High_QPSK_50@0




10MHz_High_16QAM_1@49




10MHz_High_16QAM_50@0




15MHz_Low_QPSK_1@0




15MHz_Low_QPSK_75@0




15MHz_Low_16QAM_1@0




15MHz_Low_16QAM_75@0




15MHz_High_QPSK_1@74




15MHz_High_QPSK_75@0




15MHz_High_16QAM_1@74




15MHz_High_16QAM_75@0




20MHz_Low_QPSK_1@0




20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0




20MHz_Low_16QAM_100@0




20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99



20MHz_High_16QAM_100@0




Spurious Emissions at Antenna Terminal

FCC Part 27


LTE Band 4 , Normal
 1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
 Date: 16.MAY.2025 15:29:46

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
 Date: 16.MAY.2025 15:30:05

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
 Date: 16.MAY.2025 15:30:26

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
 Date: 16.MAY.2025 15:31:26

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
 Date: 16.MAY.2025 15:31:46

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
 Date: 16.MAY.2025 15:32:05


5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



10MHz_High_QPSK_1@0(30MHz~18.55GHz)




15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
Date: 16.MAY.2025 15:36:01

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
Date: 16.MAY.2025 15:36:18

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
Date: 16.MAY.2025 15:36:35

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44145E-RF Tester:Loge Long
Date: 16.MAY.2025 15:37:24

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502Q44145E-RF Tester:Loge Long
Date: 16.MAY.2025 15:37:41

20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502Q44145E-RF Tester:Loge Long
Date: 16.MAY.2025 15:37:59

***** END *****