





Band4-5MHz-16QAM-19975-1RB#0-PASS




Band4-5MHz-16QAM-19975-25RB#0-PASS




Band4-5MHz-16QAM-20175-1RB#0-PASS



Band4-5MHz-16QAM-20175-25RB#0-PASS




Band4-5MHz-16QAM-20375-1RB#0-PASS




Band4-5MHz-16QAM-20375-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-QPSK-20000-1RB#0-PASS




Band4-10MHz-QPSK-20000-50RB#0-PASS




Band4-10MHz-QPSK-20175-1RB#0-PASS



Band4-10MHz-QPSK-20175-50RB#0-PASS




Band4-10MHz-QPSK-20350-1RB#0-PASS




Band4-10MHz-QPSK-20350-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-16QAM-20000-1RB#0-PASS




Band4-10MHz-16QAM-20000-50RB#0-PASS



Band4-10MHz-16QAM-20175-1RB#0-PASS



Band4-10MHz-16QAM-20175-50RB#0-PASS




Band4-10MHz-16QAM-20350-1RB#0-PASS




Band4-10MHz-16QAM-20350-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-QPSK-20025-1RB#0-PASS




Band4-15MHz-QPSK-20025-75RB#0-PASS




Band4-15MHz-QPSK-20175-1RB#0-PASS



Band4-15MHz-QPSK-20175-75RB#0-PASS




Band4-15MHz-QPSK-20325-1RB#0-PASS




Band4-15MHz-QPSK-20325-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-16QAM-20025-1RB#0-PASS




Band4-15MHz-16QAM-20025-75RB#0-PASS




Band4-15MHz-16QAM-20175-1RB#0-PASS



Band4-15MHz-16QAM-20175-75RB#0-PASS




Band4-15MHz-16QAM-20325-1RB#0-PASS




Band4-15MHz-16QAM-20325-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-QPSK-20050-1RB#0-PASS




Band4-20MHz-QPSK-20050-100RB#0-PASS




Band4-20MHz-QPSK-20175-1RB#0-PASS



Band4-20MHz-QPSK-20175-100RB#0-PASS




Band4-20MHz-QPSK-20300-1RB#0-PASS




Band4-20MHz-QPSK-20300-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-16QAM-20050-1RB#0-PASS




Band4-20MHz-16QAM-20050-100RB#0-PASS




Band4-20MHz-16QAM-20175-1RB#0-PASS



Band4-20MHz-16QAM-20175-100RB#0-PASS




Band4-20MHz-16QAM-20300-1RB#0-PASS




Band4-20MHz-16QAM-20300-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-QPSK-20407-1RB#0-PASS




Band5-1.4MHz-QPSK-20407-6RB#0-PASS




Band5-1.4MHz-QPSK-20525-1RB#0-PASS



Band5-1.4MHz-QPSK-20525-6RB#0-PASS




Band5-1.4MHz-QPSK-20643-1RB#0-PASS




Band5-1.4MHz-QPSK-20643-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-16QAM-20407-1RB#0-PASS




Band5-1.4MHz-16QAM-20407-6RB#0-PASS




Band5-1.4MHz-16QAM-20525-1RB#0-PASS



Band5-1.4MHz-16QAM-20525-6RB#0-PASS




Band5-1.4MHz-16QAM-20643-1RB#0-PASS




Band5-1.4MHz-16QAM-20643-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-QPSK-20415-1RB#0-PASS




Band5-3MHz-QPSK-20415-15RB#0-PASS




Band5-3MHz-QPSK-20525-1RB#0-PASS



Band5-3MHz-QPSK-20525-15RB#0-PASS




Band5-3MHz-QPSK-20635-1RB#0-PASS




Band5-3MHz-QPSK-20635-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-16QAM-20415-1RB#0-PASS




Band5-3MHz-16QAM-20415-15RB#0-PASS




Band5-3MHz-16QAM-20525-1RB#0-PASS



Band5-3MHz-16QAM-20525-15RB#0-PASS




Band5-3MHz-16QAM-20635-1RB#0-PASS




Band5-3MHz-16QAM-20635-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-QPSK-20425-1RB#0-PASS




Band5-5MHz-QPSK-20425-25RB#0-PASS




Band5-5MHz-QPSK-20525-1RB#0-PASS



Band5-5MHz-QPSK-20525-25RB#0-PASS




Band5-5MHz-QPSK-20625-1RB#0-PASS




Band5-5MHz-QPSK-20625-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-16QAM-20425-1RB#0-PASS




Band5-5MHz-16QAM-20425-25RB#0-PASS




Band5-5MHz-16QAM-20525-1RB#0-PASS



Band5-5MHz-16QAM-20525-25RB#0-PASS




Band5-5MHz-16QAM-20625-1RB#0-PASS




Band5-5MHz-16QAM-20625-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-QPSK-20450-1RB#0-PASS




Band5-10MHz-QPSK-20450-50RB#0-PASS




Band5-10MHz-QPSK-20525-1RB#0-PASS



Band5-10MHz-QPSK-20525-50RB#0-PASS




Band5-10MHz-QPSK-20600-1RB#0-PASS




Band5-10MHz-QPSK-20600-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-16QAM-20450-1RB#0-PASS




Band5-10MHz-16QAM-20450-50RB#0-PASS




Band5-10MHz-16QAM-20525-1RB#0-PASS



Band5-10MHz-16QAM-20525-50RB#0-PASS




Band5-10MHz-16QAM-20600-1RB#0-PASS




Band5-10MHz-16QAM-20600-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-QPSK-23017-1RB#0-PASS




Band12-1.4MHz-QPSK-23017-6RB#0-PASS




Band12-1.4MHz-QPSK-23095-1RB#0-PASS



Band12-1.4MHz-QPSK-23095-6RB#0-PASS




Band12-1.4MHz-QPSK-23173-1RB#0-PASS




Band12-1.4MHz-QPSK-23173-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-16QAM-23017-1RB#0-PASS




Band12-1.4MHz-16QAM-23017-6RB#0-PASS




Band12-1.4MHz-16QAM-23095-1RB#0-PASS



Band12-1.4MHz-16QAM-23095-6RB#0-PASS




Band12-1.4MHz-16QAM-23173-1RB#0-PASS




Band12-1.4MHz-16QAM-23173-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-3MHz-QPSK-23025-1RB#0-PASS




Band12-3MHz-QPSK-23025-15RB#0-PASS




Band12-3MHz-QPSK-23095-1RB#0-PASS



Band12-3MHz-QPSK-23095-15RB#0-PASS




Band12-3MHz-QPSK-23165-1RB#0-PASS




Band12-3MHz-QPSK-23165-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-3MHz-16QAM-23025-1RB#0-PASS




Band12-3MHz-16QAM-23025-15RB#0-PASS




Band12-3MHz-16QAM-23095-1RB#0-PASS



Band12-3MHz-16QAM-23095-15RB#0-PASS




Band12-3MHz-16QAM-23165-1RB#0-PASS




Band12-3MHz-16QAM-23165-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-5MHz-QPSK-23035-1RB#0-PASS




Band12-5MHz-QPSK-23035-25RB#0-PASS




Band12-5MHz-QPSK-23095-1RB#0-PASS



Band12-5MHz-QPSK-23095-25RB#0-PASS




Band12-5MHz-QPSK-23155-1RB#0-PASS




Band12-5MHz-QPSK-23155-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-5MHz-16QAM-23035-1RB#0-PASS




Band12-5MHz-16QAM-23035-25RB#0-PASS




Band12-5MHz-16QAM-23095-1RB#0-PASS



Band12-5MHz-16QAM-23095-25RB#0-PASS




Band12-5MHz-16QAM-23155-1RB#0-PASS




Band12-5MHz-16QAM-23155-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-10MHz-QPSK-23060-1RB#0-PASS




Band12-10MHz-QPSK-23060-50RB#0-PASS




Band12-10MHz-QPSK-23095-1RB#0-PASS



Band12-10MHz-QPSK-23095-50RB#0-PASS




Band12-10MHz-QPSK-23130-1RB#0-PASS




Band12-10MHz-QPSK-23130-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-10MHz-16QAM-23060-1RB#0-PASS




Band12-10MHz-16QAM-23060-50RB#0-PASS




Band12-10MHz-16QAM-23095-1RB#0-PASS



Band12-10MHz-16QAM-23095-50RB#0-PASS




Band12-10MHz-16QAM-23130-1RB#0-PASS




Band12-10MHz-16QAM-23130-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-5MHz-QPSK-23205-1RB#0-PASS




Band13-5MHz-QPSK-23205-25RB#0-PASS




Band13-5MHz-QPSK-23230-1RB#0-PASS



Band13-5MHz-QPSK-23230-25RB#0-PASS




Band13-5MHz-QPSK-23255-1RB#0-PASS




Band13-5MHz-QPSK-23255-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-5MHz-16QAM-23205-1RB#0-PASS




Band13-5MHz-16QAM-23205-25RB#0-PASS




Band13-5MHz-16QAM-23230-1RB#0-PASS



Band13-5MHz-16QAM-23230-25RB#0-PASS




Band13-5MHz-16QAM-23255-1RB#0-PASS




Band13-5MHz-16QAM-23255-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band13-10MHz-QPSK-23230-1RB#0-PASS




Band13-10MHz-QPSK-23230-50RB#0-PASS




Band13-10MHz-16QAM-23230-1RB#0-PASS



Band13-10MHz-16QAM-23230-50RB#0-PASS




Band25-1.4MHz-QPSK-26047-1RB#0-PASS




Band25-1.4MHz-QPSK-26047-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-1.4MHz-QPSK-26365-1RB#0-PASS




Band25-1.4MHz-QPSK-26365-6RB#0-PASS




Band25-1.4MHz-QPSK-26683-1RB#0-PASS



Band25-1.4MHz-QPSK-26683-6RB#0-PASS




Band25-1.4MHz-16QAM-26047-1RB#0-PASS




Band25-1.4MHz-16QAM-26047-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-1.4MHz-16QAM-26365-1RB#0-PASS




Band25-1.4MHz-16QAM-26365-6RB#0-PASS




Band25-1.4MHz-16QAM-26683-1RB#0-PASS



Band25-1.4MHz-16QAM-26683-6RB#0-PASS




Band25-3MHz-QPSK-26055-1RB#0-PASS




Band25-3MHz-QPSK-26055-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-3MHz-QPSK-26365-1RB#0-PASS




Band25-3MHz-QPSK-26365-15RB#0-PASS




Band25-3MHz-QPSK-26675-1RB#0-PASS



Band25-3MHz-QPSK-26675-15RB#0-PASS




Band25-3MHz-16QAM-26055-1RB#0-PASS




Band25-3MHz-16QAM-26055-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-3MHz-16QAM-26365-1RB#0-PASS




Band25-3MHz-16QAM-26365-15RB#0-PASS




Band25-3MHz-16QAM-26675-1RB#0-PASS



Band25-3MHz-16QAM-26675-15RB#0-PASS




Band25-5MHz-QPSK-26065-1RB#0-PASS




Band25-5MHz-QPSK-26065-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-5MHz-QPSK-26365-1RB#0-PASS




Band25-5MHz-QPSK-26365-25RB#0-PASS




Band25-5MHz-QPSK-26665-1RB#0-PASS



Band25-5MHz-QPSK-26665-25RB#0-PASS




Band25-5MHz-16QAM-26065-1RB#0-PASS




Band25-5MHz-16QAM-26065-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-5MHz-16QAM-26365-1RB#0-PASS




Band25-5MHz-16QAM-26365-25RB#0-PASS




Band25-5MHz-16QAM-26665-1RB#0-PASS



Band25-5MHz-16QAM-26665-25RB#0-PASS




Band25-10MHz-QPSK-26090-1RB#0-PASS




Band25-10MHz-QPSK-26090-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-10MHz-QPSK-26365-1RB#0-PASS




Band25-10MHz-QPSK-26365-50RB#0-PASS




Band25-10MHz-QPSK-26640-1RB#0-PASS



Band25-10MHz-QPSK-26640-50RB#0-PASS




Band25-10MHz-16QAM-26090-1RB#0-PASS




Band25-10MHz-16QAM-26090-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-10MHz-16QAM-26365-1RB#0-PASS




Band25-10MHz-16QAM-26365-50RB#0-PASS




Band25-10MHz-16QAM-26640-1RB#0-PASS



Band25-10MHz-16QAM-26640-50RB#0-PASS




Band25-15MHz-QPSK-26115-1RB#0-PASS




Band25-15MHz-QPSK-26115-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-15MHz-QPSK-26365-1RB#0-PASS




Band25-15MHz-QPSK-26365-75RB#0-PASS




Band25-15MHz-QPSK-26615-1RB#0-PASS



Band25-15MHz-QPSK-26615-75RB#0-PASS




Band25-15MHz-16QAM-26115-1RB#0-PASS




Band25-15MHz-16QAM-26115-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-15MHz-16QAM-26365-1RB#0-PASS




Band25-15MHz-16QAM-26365-75RB#0-PASS




Band25-15MHz-16QAM-26615-1RB#0-PASS



Band25-15MHz-16QAM-26615-75RB#0-PASS




Band25-20MHz-QPSK-26140-1RB#0-PASS




Band25-20MHz-QPSK-26140-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-20MHz-QPSK-26365-1RB#0-PASS




Band25-20MHz-QPSK-26365-100RB#0-PASS




Band25-20MHz-QPSK-26590-1RB#0-PASS



Band25-20MHz-QPSK-26590-100RB#0-PASS




Band25-20MHz-16QAM-26140-1RB#0-PASS




Band25-20MHz-16QAM-26140-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-20MHz-16QAM-26365-1RB#0-PASS




Band25-20MHz-16QAM-26365-100RB#0-PASS




Band25-20MHz-16QAM-26590-1RB#0-PASS



Band25-20MHz-16QAM-26590-100RB#0-PASS




Band41-5MHz-QPSK-39675-1RB#0-PASS




Band41-5MHz-QPSK-39675-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-5MHz-QPSK-40620-1RB#0-PASS




Band41-5MHz-QPSK-40620-25RB#0-PASS




Band41-5MHz-QPSK-41565-1RB#0-PASS



Band41-5MHz-QPSK-41565-25RB#0-PASS




Band41-5MHz-16QAM-39675-1RB#0-PASS




Band41-5MHz-16QAM-39675-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-5MHz-16QAM-40620-1RB#0-PASS




Band41-5MHz-16QAM-40620-25RB#0-PASS




Band41-5MHz-16QAM-41565-1RB#0-PASS



Band41-5MHz-16QAM-41565-25RB#0-PASS



Band41-10MHz-QPSK-39700-1RB#0-PASS



Band41-10MHz-QPSK-39700-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch