

Band26(814-824)-3MHz-QPSK-26705-15RB#0-PASS



Band26(814-824)-3MHz-QPSK-26740-15RB#0-PASS



Band26(814-824)-3MHz-QPSK-26775-15RB#0-PASS



Band26(814-824)-3MHz-16QAM-26705-15RB#0-PASS



Band26(814-824)-3MHz-16QAM-26740-15RB#0-PASS



Band26(814-824)-3MHz-16QAM-26775-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(814-824)-5MHz-QPSK-26715-25RB#0-PASS



Band26(814-824)-5MHz-QPSK-26740-25RB#0-PASS



Band26(814-824)-5MHz-QPSK-26765-25RB#0-PASS



Band26(814-824)-5MHz-16QAM-26715-25RB#0-PASS



Band26(814-824)-5MHz-16QAM-26740-25RB#0-PASS



Band26(814-824)-5MHz-16QAM-26765-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(814-824)-10MHz-QPSK-26740-50RB#0-PASS



Band26(814-824)-10MHz-16QAM-26740-50RB#0-PASS



Band26(824-849)-1.4MHz-QPSK-26797-6RB#0-PASS



Band26(824-849)-1.4MHz-QPSK-26915-6RB#0-PASS



Band26(824-849)-1.4MHz-QPSK-27033-6RB#0-PASS



Band26(824-849)-1.4MHz-16QAM-26797-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-1.4MHz-16QAM-26915-6RB#0-PASS



Band26(824-849)-1.4MHz-16QAM-27033-6RB#0-PASS



Band26(824-849)-3MHz-QPSK-26805-15RB#0-PASS



Band26(824-849)-3MHz-QPSK-26915-15RB#0-PASS



Band26(824-849)-3MHz-QPSK-27025-15RB#0-PASS



Band26(824-849)-3MHz-16QAM-26805-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-3MHz-16QAM-26915-15RB#0-PASS



Band26(824-849)-3MHz-16QAM-27025-15RB#0-PASS



Band26(824-849)-5MHz-QPSK-26815-25RB#0-PASS



Band26(824-849)-5MHz-QPSK-26915-25RB#0-PASS



Band26(824-849)-5MHz-QPSK-27015-25RB#0-PASS



Band26(824-849)-5MHz-16QAM-26815-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-5MHz-16QAM-26915-25RB#0-PASS



Band26(824-849)-5MHz-16QAM-27015-25RB#0-PASS



Band26(824-849)-10MHz-QPSK-26840-50RB#0-PASS



Band26(824-849)-10MHz-QPSK-26915-50RB#0-PASS



Band26(824-849)-10MHz-QPSK-26990-50RB#0-PASS



Band26(824-849)-10MHz-16QAM-26840-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-10MHz-16QAM-26915-50RB#0-PASS



Band26(824-849)-10MHz-16QAM-26990-50RB#0-PASS



Band26(824-849)-15MHz-QPSK-26865-75RB#0-PASS



Band26(824-849)-15MHz-QPSK-26915-75RB#0-PASS



Band26(824-849)-15MHz-QPSK-26965-75RB#0-PASS



Band26(824-849)-15MHz-16QAM-26865-75RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch





Band26(824-849)-15MHz-16QAM-26915-75RB#0-PASS

Band26(824-849)-15MHz-16QAM-26965-75RB#0-PASS





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch

8.4. Appendix D: Band Edge

8.4.1. Test Graphs

Band2-1.4MHz-QPSK-18607-1RB#0-PASS



Band2-1.4MHz-QPSK-18607-6RB#0-PASS



Band2-1.4MHz-QPSK-18607-1RB#5-PASS



Band2-1.4MHz-QPSK-19193-1RB#0-PASS

Band2-1.4MHz-QPSK-19193-6RB#0-PASS



Band2-1.4MHz-QPSK-19193-1RB#5-PASS



Band2-1.4MHz-16QAM-18607-1RB#0-PASS

Band2-1.4MHz-16QAM-18607-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-1.4MHz-16QAM-18607-1RB#5-PASS



Band2-1.4MHz-16QAM-19193-1RB#0-PASS



Band2-1.4MHz-16QAM-19193-6RB#0-PASS



Band2-1.4MHz-16QAM-19193-1RB#5-PASS



Band2-3MHz-QPSK-18615-1RB#0-PASS



Band2-3MHz-QPSK-18615-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-3MHz-QPSK-18615-1RB#14-PASS



Band2-3MHz-QPSK-19185-1RB#0-PASS



Band2-3MHz-QPSK-19185-15RB#0-PASS



Band2-3MHz-QPSK-19185-1RB#14-PASS



Band2-3MHz-16QAM-18615-1RB#0-PASS



Band2-3MHz-16QAM-18615-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-3MHz-16QAM-18615-1RB#14-PASS



Band2-3MHz-16QAM-19185-1RB#0-PASS



Band2-3MHz-16QAM-19185-15RB#0-PASS



Band2-3MHz-16QAM-19185-1RB#14-PASS



Band2-5MHz-QPSK-18625-1RB#0-PASS



Band2-5MHz-QPSK-18625-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-5MHz-QPSK-18625-1RB#24-PASS



Band2-5MHz-QPSK-19175-1RB#0-PASS



Band2-5MHz-QPSK-19175-25RB#0-PASS



Band2-5MHz-QPSK-19175-1RB#24-PASS



Band2-5MHz-16QAM-18625-1RB#0-PASS



Band2-5MHz-16QAM-18625-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-5MHz-16QAM-18625-1RB#24-PASS



Band2-5MHz-16QAM-19175-1RB#0-PASS



Band2-5MHz-16QAM-19175-25RB#0-PASS



Band2-5MHz-16QAM-19175-1RB#24-PASS



Band2-10MHz-QPSK-18650-1RB#0-PASS



Band2-10MHz-QPSK-18650-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-10MHz-QPSK-18650-1RB#49-PASS



Band2-10MHz-QPSK-19150-1RB#0-PASS



Band2-10MHz-QPSK-19150-50RB#0-PASS



Band2-10MHz-QPSK-19150-1RB#49-PASS



Band2-10MHz-16QAM-18650-1RB#0-PASS



Band2-10MHz-16QAM-18650-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-10MHz-16QAM-18650-1RB#49-PASS



Band2-10MHz-16QAM-19150-1RB#0-PASS



Band2-10MHz-16QAM-19150-50RB#0-PASS



Band2-10MHz-16QAM-19150-1RB#49-PASS



Band2-15MHz-QPSK-18675-1RB#0-PASS



Band2-15MHz-QPSK-18675-75RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-15MHz-QPSK-18675-1RB#74-PASS



Band2-15MHz-QPSK-19125-1RB#0-PASS



Band2-15MHz-QPSK-19125-75RB#0-PASS



Band2-15MHz-QPSK-19125-1RB#74-PASS



Band2-15MHz-16QAM-18675-1RB#0-PASS



Band2-15MHz-16QAM-18675-75RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-15MHz-16QAM-18675-1RB#74-PASS



Band2-15MHz-16QAM-19125-1RB#0-PASS



Band2-15MHz-16QAM-19125-75RB#0-PASS



Band2-15MHz-16QAM-19125-1RB#74-PASS



Band2-20MHz-QPSK-18700-1RB#0-PASS



Band2-20MHz-QPSK-18700-100RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-20MHz-QPSK-18700-1RB#99-PASS



Band2-20MHz-QPSK-19100-1RB#0-PASS



Band2-20MHz-QPSK-19100-100RB#0-PASS



Band2-20MHz-QPSK-19100-1RB#99-PASS



Band2-20MHz-16QAM-18700-1RB#0-PASS



Band2-20MHz-16QAM-18700-100RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-20MHz-16QAM-18700-1RB#99-PASS



Band2-20MHz-16QAM-19100-1RB#0-PASS



Band2-20MHz-16QAM-19100-100RB#0-PASS



Band2-20MHz-16QAM-19100-1RB#99-PASS



Band4-1.4MHz-QPSK-19957-1RB#0-PASS



Band4-1.4MHz-QPSK-19957-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-1.4MHz-QPSK-19957-1RB#5-PASS



Band4-1.4MHz-QPSK-20393-1RB#0-PASS



Band4-1.4MHz-QPSK-20393-6RB#0-PASS

Band4-1.4MHz-QPSK-20393-1RB#5-PASS



Band4-1.4MHz-16QAM-19957-1RB#0-PASS



Band4-1.4MHz-16QAM-19957-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-1.4MHz-16QAM-19957-1RB#5-PASS



Band4-1.4MHz-16QAM-20393-1RB#0-PASS



Band4-1.4MHz-16QAM-20393-6RB#0-PASS

Band4-1.4MHz-16QAM-20393-1RB#5-PASS



Band4-3MHz-QPSK-19965-1RB#0-PASS



Band4-3MHz-QPSK-19965-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-3MHz-QPSK-19965-1RB#14-PASS



Band4-3MHz-QPSK-20385-1RB#0-PASS



Band4-3MHz-QPSK-20385-15RB#0-PASS



Band4-3MHz-QPSK-20385-1RB#14-PASS



Band4-3MHz-16QAM-19965-1RB#0-PASS



Band4-3MHz-16QAM-19965-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-3MHz-16QAM-19965-1RB#14-PASS



Band4-3MHz-16QAM-20385-1RB#0-PASS



Band4-3MHz-16QAM-20385-15RB#0-PASS

Band4-3MHz-16QAM-20385-1RB#14-PASS



Band4-5MHz-QPSK-19975-1RB#0-PASS



Band4-5MHz-QPSK-19975-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-5MHz-QPSK-19975-1RB#24-PASS



Band4-5MHz-QPSK-20375-1RB#0-PASS



Band4-5MHz-QPSK-20375-25RB#0-PASS



Band4-5MHz-QPSK-20375-1RB#24-PASS



Band4-5MHz-16QAM-19975-1RB#0-PASS



Band4-5MHz-16QAM-19975-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-5MHz-16QAM-19975-1RB#24-PASS



Band4-5MHz-16QAM-20375-1RB#0-PASS



Band4-5MHz-16QAM-20375-25RB#0-PASS



Band4-5MHz-16QAM-20375-1RB#24-PASS



Band4-10MHz-QPSK-20000-1RB#0-PASS



Band4-10MHz-QPSK-20000-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-10MHz-QPSK-20000-1RB#49-PASS



Band4-10MHz-QPSK-20350-1RB#0-PASS



Band4-10MHz-QPSK-20350-50RB#0-PASS



Band4-10MHz-QPSK-20350-1RB#49-PASS



Band4-10MHz-16QAM-20000-1RB#0-PASS



Band4-10MHz-16QAM-20000-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-10MHz-16QAM-20000-1RB#49-PASS



Band4-10MHz-16QAM-20350-1RB#0-PASS



Band4-10MHz-16QAM-20350-50RB#0-PASS



Band4-10MHz-16QAM-20350-1RB#49-PASS



Band4-15MHz-QPSK-20025-1RB#0-PASS



Band4-15MHz-QPSK-20025-75RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-15MHz-QPSK-20025-1RB#74-PASS



Band4-15MHz-QPSK-20325-1RB#0-PASS



Band4-15MHz-QPSK-20325-75RB#0-PASS



Band4-15MHz-QPSK-20325-1RB#74-PASS



Band4-15MHz-16QAM-20025-1RB#0-PASS



Band4-15MHz-16QAM-20025-75RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-15MHz-16QAM-20025-1RB#74-PASS



Band4-15MHz-16QAM-20325-1RB#0-PASS



Band4-15MHz-16QAM-20325-75RB#0-PASS



Band4-15MHz-16QAM-20325-1RB#74-PASS



Band4-20MHz-QPSK-20050-1RB#0-PASS



Band4-20MHz-QPSK-20050-100RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-20MHz-QPSK-20050-1RB#99-PASS



Band4-20MHz-QPSK-20300-1RB#0-PASS



Band4-20MHz-QPSK-20300-100RB#0-PASS



Band4-20MHz-QPSK-20300-1RB#99-PASS



Band4-20MHz-16QAM-20050-1RB#0-PASS



Band4-20MHz-16QAM-20050-100RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-20MHz-16QAM-20050-1RB#99-PASS



Band4-20MHz-16QAM-20300-1RB#0-PASS



Band4-20MHz-16QAM-20300-100RB#0-PASS



Band4-20MHz-16QAM-20300-1RB#99-PASS



Band5-1.4MHz-QPSK-20407-1RB#0-PASS



Band5-1.4MHz-QPSK-20407-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-1.4MHz-QPSK-20407-1RB#5-PASS



Band5-1.4MHz-QPSK-20643-1RB#0-PASS



Band5-1.4MHz-QPSK-20643-6RB#0-PASS

Band5-1.4MHz-QPSK-20643-1RB#5-PASS



Band5-1.4MHz-16QAM-20407-1RB#0-PASS



Band5-1.4MHz-16QAM-20407-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-1.4MHz-16QAM-20407-1RB#5-PASS



Band5-1.4MHz-16QAM-20643-1RB#0-PASS



Band5-1.4MHz-16QAM-20643-6RB#0-PASS



Band5-1.4MHz-16QAM-20643-1RB#5-PASS



Band5-3MHz-QPSK-20415-1RB#0-PASS



Band5-3MHz-QPSK-20415-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-3MHz-QPSK-20415-1RB#14-PASS



Band5-3MHz-QPSK-20635-1RB#0-PASS



Band5-3MHz-QPSK-20635-15RB#0-PASS



Band5-3MHz-QPSK-20635-1RB#14-PASS



Band5-3MHz-16QAM-20415-1RB#0-PASS

Band5-3MHz-16QAM-20415-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-3MHz-16QAM-20415-1RB#14-PASS



Band5-3MHz-16QAM-20635-1RB#0-PASS

Band5-3MHz-16QAM-20635-15RB#0-PASS

Band5-3MHz-16QAM-20635-1RB#14-PASS



Band5-5MHz-QPSK-20425-1RB#0-PASS



Band5-5MHz-QPSK-20425-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-5MHz-QPSK-20425-1RB#24-PASS



Band5-5MHz-QPSK-20625-1RB#0-PASS



Band5-5MHz-QPSK-20625-25RB#0-PASS



Band5-5MHz-QPSK-20625-1RB#24-PASS



Band5-5MHz-16QAM-20425-1RB#0-PASS



Band5-5MHz-16QAM-20425-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-5MHz-16QAM-20425-1RB#24-PASS



Band5-5MHz-16QAM-20625-1RB#0-PASS



Band5-5MHz-16QAM-20625-25RB#0-PASS



Band5-5MHz-16QAM-20625-1RB#24-PASS



Band5-10MHz-QPSK-20450-1RB#0-PASS



Band5-10MHz-QPSK-20450-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-10MHz-QPSK-20450-1RB#49-PASS



Band5-10MHz-QPSK-20600-1RB#0-PASS



Band5-10MHz-QPSK-20600-50RB#0-PASS



Band5-10MHz-QPSK-20600-1RB#49-PASS



Band5-10MHz-16QAM-20450-1RB#0-PASS



Band5-10MHz-16QAM-20450-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-10MHz-16QAM-20450-1RB#49-PASS



Band5-10MHz-16QAM-20600-1RB#0-PASS



Band5-10MHz-16QAM-20600-50RB#0-PASS



Band5-10MHz-16QAM-20600-1RB#49-PASS



Band12-1.4MHz-QPSK-23017-1RB#0-PASS



Band12-1.4MHz-QPSK-23017-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-1.4MHz-QPSK-23017-1RB#5-PASS



Band12-1.4MHz-QPSK-23173-1RB#0-PASS



Band12-1.4MHz-QPSK-23173-6RB#0-PASS



Band12-1.4MHz-QPSK-23173-1RB#5-PASS

Band12-1.4MHz-16QAM-23017-1RB#0-PASS



Band12-1.4MHz-16QAM-23017-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-1.4MHz-16QAM-23017-1RB#5-PASS

Band12-1.4MHz-16QAM-23173-1RB#0-PASS



Band12-1.4MHz-16QAM-23173-6RB#0-PASS



Band12-1.4MHz-16QAM-23173-1RB#5-PASS

Band12-3MHz-QPSK-23025-1RB#0-PASS



Band12-3MHz-QPSK-23025-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-3MHz-QPSK-23025-1RB#14-PASS



Band12-3MHz-QPSK-23165-1RB#0-PASS

Band12-3MHz-QPSK-23165-15RB#0-PASS



Band12-3MHz-QPSK-23165-1RB#14-PASS



Band12-3MHz-16QAM-23025-1RB#0-PASS



Band12-3MHz-16QAM-23025-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-3MHz-16QAM-23025-1RB#14-PASS

Band12-3MHz-16QAM-23165-1RB#0-PASS



Band12-3MHz-16QAM-23165-15RB#0-PASS



Band12-3MHz-16QAM-23165-1RB#14-PASS



Band12-5MHz-QPSK-23035-1RB#0-PASS



Band12-5MHz-QPSK-23035-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-5MHz-QPSK-23035-1RB#24-PASS



Band12-5MHz-QPSK-23155-1RB#0-PASS



Band12-5MHz-QPSK-23155-25RB#0-PASS



Band12-5MHz-QPSK-23155-1RB#24-PASS



Band12-5MHz-16QAM-23035-1RB#0-PASS



Band12-5MHz-16QAM-23035-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-5MHz-16QAM-23035-1RB#24-PASS



Band12-5MHz-16QAM-23155-1RB#0-PASS



Band12-5MHz-16QAM-23155-25RB#0-PASS



Band12-5MHz-16QAM-23155-1RB#24-PASS



Band12-10MHz-QPSK-23060-1RB#0-PASS



Band12-10MHz-QPSK-23060-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-10MHz-QPSK-23060-1RB#49-PASS



Band12-10MHz-QPSK-23130-1RB#0-PASS



Band12-10MHz-QPSK-23130-50RB#0-PASS



Band12-10MHz-QPSK-23130-1RB#49-PASS



Band12-10MHz-16QAM-23060-1RB#0-PASS



Band12-10MHz-16QAM-23060-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band12-10MHz-16QAM-23060-1RB#49-PASS



Band12-10MHz-16QAM-23130-1RB#0-PASS



Band12-10MHz-16QAM-23130-50RB#0-PASS



Band12-10MHz-16QAM-23130-1RB#49-PASS



Band13-5MHz-QPSK-23205-1RB#0-PASS



Band13-5MHz-QPSK-23205-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band13-5MHz-QPSK-23205-1RB#24-PASS



Band13-5MHz-QPSK-23255-1RB#0-PASS



Band13-5MHz-QPSK-23255-25RB#0-PASS



Band13-5MHz-QPSK-23255-1RB#24-PASS



Band13-5MHz-16QAM-23205-1RB#0-PASS



Band13-5MHz-16QAM-23205-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band13-5MHz-16QAM-23205-1RB#24-PASS



Band13-5MHz-16QAM-23255-1RB#0-PASS



Band13-5MHz-16QAM-23255-25RB#0-PASS



Band13-5MHz-16QAM-23255-1RB#24-PASS



Band13-10MHz-QPSK-23230-1RB#0-PASS



Band13-10MHz-QPSK-23230-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band13-10MHz-QPSK-23230-1RB#49-PASS



Band13-10MHz-16QAM-23230-1RB#0-PASS



Band13-10MHz-16QAM-23230-50RB#0-PASS



Band13-10MHz-16QAM-23230-1RB#49-PASS



Band25-1.4MHz-QPSK-26047-1RB#0-PASS



Band25-1.4MHz-QPSK-26047-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band25-1.4MHz-QPSK-26047-1RB#5-PASS



Band25-1.4MHz-QPSK-26683-1RB#0-PASS



Band25-1.4MHz-QPSK-26683-6RB#0-PASS



Band25-1.4MHz-QPSK-26683-1RB#5-PASS



Band25-1.4MHz-16QAM-26047-1RB#0-PASS



Band25-1.4MHz-16QAM-26047-6RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band25-1.4MHz-16QAM-26047-1RB#5-PASS



Band25-1.4MHz-16QAM-26683-1RB#0-PASS



Band25-1.4MHz-16QAM-26683-6RB#0-PASS

Band25-1.4MHz-16QAM-26683-1RB#5-PASS



Band25-3MHz-QPSK-26055-1RB#0-PASS



Band25-3MHz-QPSK-26055-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band25-3MHz-QPSK-26055-1RB#14-PASS



Band25-3MHz-QPSK-26675-1RB#0-PASS



Band25-3MHz-QPSK-26675-15RB#0-PASS



Band25-3MHz-QPSK-26675-1RB#14-PASS



Band25-3MHz-16QAM-26055-1RB#0-PASS



Band25-3MHz-16QAM-26055-15RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band25-3MHz-16QAM-26055-1RB#14-PASS



Band25-3MHz-16QAM-26675-1RB#0-PASS



Band25-3MHz-16QAM-26675-15RB#0-PASS

Band25-3MHz-16QAM-26675-1RB#14-PASS



Band25-5MHz-QPSK-26065-1RB#0-PASS



Band25-5MHz-QPSK-26065-25RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch