





Band25-5MHz-QPSK-26065-1RB#24-PASS




Band25-5MHz-QPSK-26665-1RB#0-PASS




Band25-5MHz-QPSK-26665-25RB#0-PASS



Band25-5MHz-QPSK-26665-1RB#24-PASS




Band25-5MHz-16QAM-26065-1RB#0-PASS




Band25-5MHz-16QAM-26065-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-5MHz-16QAM-26065-1RB#24-PASS




Band25-5MHz-16QAM-26665-1RB#0-PASS




Band25-5MHz-16QAM-26665-25RB#0-PASS



Band25-5MHz-16QAM-26665-1RB#24-PASS




Band25-10MHz-QPSK-26090-1RB#0-PASS




Band25-10MHz-QPSK-26090-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-10MHz-QPSK-26090-1RB#49-PASS




Band25-10MHz-QPSK-26640-1RB#0-PASS




Band25-10MHz-QPSK-26640-50RB#0-PASS



Band25-10MHz-QPSK-26640-1RB#49-PASS




Band25-10MHz-16QAM-26090-1RB#0-PASS




Band25-10MHz-16QAM-26090-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-10MHz-16QAM-26090-1RB#49-PASS




Band25-10MHz-16QAM-26640-1RB#0-PASS




Band25-10MHz-16QAM-26640-50RB#0-PASS



Band25-10MHz-16QAM-26640-1RB#49-PASS




Band25-15MHz-QPSK-26115-1RB#0-PASS




Band25-15MHz-QPSK-26115-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-15MHz-QPSK-26115-1RB#74-PASS




Band25-15MHz-QPSK-26615-1RB#0-PASS




Band25-15MHz-QPSK-26615-75RB#0-PASS



Band25-15MHz-QPSK-26615-1RB#74-PASS




Band25-15MHz-16QAM-26115-1RB#0-PASS




Band25-15MHz-16QAM-26615-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-15MHz-16QAM-26615-75RB#0-PASS




Band25-15MHz-16QAM-26615-1RB#0-PASS




Band25-15MHz-16QAM-26615-75RB#0-PASS



Band25-15MHz-16QAM-26615-1RB#74-PASS




Band25-20MHz-QPSK-26140-1RB#0-PASS




Band25-20MHz-QPSK-26140-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-20MHz-QPSK-26140-1RB#99-PASS




Band25-20MHz-QPSK-26590-1RB#0-PASS




Band25-20MHz-QPSK-26590-100RB#0-PASS



Band25-20MHz-QPSK-26590-1RB#99-PASS




Band25-20MHz-16QAM-26140-1RB#0-PASS




Band25-20MHz-16QAM-26140-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band25-20MHz-16QAM-26140-1RB#99-PASS




Band25-20MHz-16QAM-26590-1RB#0-PASS




Band25-20MHz-16QAM-26590-100RB#0-PASS



Band25-20MHz-16QAM-26590-1RB#99-PASS




Band41-5MHz-QPSK-39675-1RB#0-PASS




Band41-5MHz-QPSK-39675-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-5MHz-QPSK-39675-1RB#24-PASS




Band41-5MHz-QPSK-41565-1RB#0-PASS




Band41-5MHz-QPSK-41565-25RB#0-PASS



Band41-5MHz-QPSK-41565-1RB#24-PASS




Band41-5MHz-16QAM-39675-1RB#0-PASS




Band41-5MHz-16QAM-39675-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-5MHz-16QAM-39675-1RB#24-PASS




Band41-5MHz-16QAM-41565-1RB#0-PASS




Band41-5MHz-16QAM-41565-25RB#0-PASS



Band41-5MHz-16QAM-41565-1RB#24-PASS




Band41-10MHz-QPSK-39700-1RB#0-PASS




Band41-10MHz-QPSK-39700-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-10MHz-QPSK-39700-1RB#49-PASS




Band41-10MHz-QPSK-41540-1RB#0-PASS




Band41-10MHz-QPSK-41540-50RB#0-PASS



Band41-10MHz-QPSK-41540-1RB#49-PASS




Band41-10MHz-16QAM-39700-1RB#0-PASS




Band41-10MHz-16QAM-39700-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band41-10MHz-16QAM-39700-1RB#49-PASS



Band41-10MHz-16QAM-41540-1RB#0-PASS




Band41-10MHz-16QAM-41540-50RB#0-PASS



Band41-10MHz-16QAM-41540-1RB#49-PASS




Band41-15MHz-QPSK-39725-1RB#0-PASS




Band41-15MHz-QPSK-39725-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-15MHz-QPSK-39725-1RB#74-PASS




Band41-15MHz-QPSK-41515-1RB#0-PASS




Band41-15MHz-QPSK-41515-75RB#0-PASS



Band41-15MHz-QPSK-41515-1RB#74-PASS




Band41-15MHz-16QAM-39725-1RB#0-PASS




Band41-15MHz-16QAM-39725-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-15MHz-16QAM-39725-1RB#74-PASS




Band41-15MHz-16QAM-41515-1RB#0-PASS




Band41-15MHz-16QAM-41515-75RB#0-PASS



Band41-15MHz-16QAM-41515-1RB#74-PASS




Band41-20MHz-QPSK-39750-1RB#0-PASS




Band41-20MHz-QPSK-39750-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-20MHz-QPSK-39750-1RB#99-PASS




Band41-20MHz-QPSK-41490-1RB#0-PASS




Band41-20MHz-QPSK-41490-100RB#0-PASS



Band41-20MHz-QPSK-41490-1RB#99-PASS




Band41-20MHz-16QAM-39750-1RB#0-PASS




Band41-20MHz-16QAM-39750-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band41-20MHz-16QAM-39750-1RB#99-PASS




Band41-20MHz-16QAM-41490-1RB#0-PASS




Band41-20MHz-16QAM-41490-100RB#0-PASS



Band41-20MHz-16QAM-41490-1RB#99-PASS




Band66-1.4MHz-QPSK-131979-1RB#0-PASS




Band66-1.4MHz-QPSK-131979-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-1.4MHz-QPSK-131979-1RB#5-PASS




Band66-1.4MHz-QPSK-132665-1RB#0-PASS




Band66-1.4MHz-QPSK-132665-6RB#0-PASS



Band66-1.4MHz-QPSK-132665-1RB#5-PASS




Band66-1.4MHz-16QAM-131979-1RB#0-PASS




Band66-1.4MHz-16QAM-131979-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-1.4MHz-16QAM-131979-1RB#5-PASS




Band66-1.4MHz-16QAM-132665-1RB#0-PASS




Band66-1.4MHz-16QAM-132665-6RB#0-PASS



Band66-1.4MHz-16QAM-132665-1RB#5-PASS




Band66-3MHz-QPSK-131987-1RB#0-PASS




Band66-3MHz-QPSK-131987-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-3MHz-QPSK-131987-1RB#14-PASS




Band66-3MHz-QPSK-132657-1RB#0-PASS




Band66-3MHz-QPSK-132657-15RB#0-PASS



Band66-3MHz-QPSK-132657-1RB#14-PASS




Band66-3MHz-16QAM-131987-1RB#0-PASS




Band66-3MHz-16QAM-131987-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-3MHz-16QAM-131987-1RB#14-PASS




Band66-3MHz-16QAM-132657-1RB#0-PASS




Band66-3MHz-16QAM-132657-15RB#0-PASS



Band66-3MHz-16QAM-132657-1RB#14-PASS




Band66-5MHz-QPSK-131997-1RB#0-PASS




Band66-5MHz-QPSK-131997-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-5MHz-QPSK-131997-1RB#24-PASS




Band66-5MHz-QPSK-132647-1RB#0-PASS




Band66-5MHz-QPSK-132647-25RB#0-PASS



Band66-5MHz-QPSK-132647-1RB#24-PASS




Band66-5MHz-16QAM-131997-1RB#0-PASS




Band66-5MHz-16QAM-131997-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-5MHz-16QAM-131997-1RB#24-PASS




Band66-5MHz-16QAM-132647-1RB#0-PASS




Band66-5MHz-16QAM-132647-25RB#0-PASS



Band66-5MHz-16QAM-132647-1RB#24-PASS




Band66-10MHz-QPSK-132022-1RB#0-PASS




Band66-10MHz-QPSK-132022-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-10MHz-QPSK-132022-1RB#49-PASS




Band66-10MHz-QPSK-132622-1RB#0-PASS




Band66-10MHz-QPSK-132622-50RB#0-PASS



Band66-10MHz-QPSK-132622-1RB#49-PASS




Band66-10MHz-16QAM-132022-1RB#0-PASS




Band66-10MHz-16QAM-132022-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-10MHz-16QAM-132022-1RB#49-PASS




Band66-10MHz-16QAM-132622-1RB#0-PASS




Band66-10MHz-16QAM-132622-50RB#0-PASS



Band66-10MHz-16QAM-132622-1RB#49-PASS




Band66-15MHz-QPSK-132047-1RB#0-PASS




Band66-15MHz-QPSK-132047-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-15MHz-QPSK-132047-1RB#74-PASS




Band66-15MHz-QPSK-132597-1RB#0-PASS




Band66-15MHz-QPSK-132597-75RB#0-PASS



Band66-15MHz-QPSK-132597-1RB#74-PASS




Band66-15MHz-16QAM-132047-1RB#0-PASS




Band66-15MHz-16QAM-132047-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-15MHz-16QAM-132047-1RB#74-PASS




Band66-15MHz-16QAM-132597-1RB#0-PASS




Band66-15MHz-16QAM-132597-75RB#0-PASS



Band66-15MHz-16QAM-132597-1RB#74-PASS




Band66-20MHz-QPSK-132072-1RB#0-PASS




Band66-20MHz-QPSK-132072-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-20MHz-QPSK-132072-1RB#99-PASS




Band66-20MHz-QPSK-132572-1RB#0-PASS




Band66-20MHz-QPSK-132572-100RB#0-PASS



Band66-20MHz-QPSK-132572-1RB#99-PASS




Band66-20MHz-16QAM-132072-1RB#0-PASS




Band66-20MHz-16QAM-132072-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band66-20MHz-16QAM-132072-1RB#99-PASS




Band66-20MHz-16QAM-132572-1RB#0-PASS




Band66-20MHz-16QAM-132572-100RB#0-PASS



Band66-20MHz-16QAM-132572-1RB#99-PASS




Band71-5MHz-QPSK-133147-1RB#0-PASS




Band71-5MHz-QPSK-133147-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-5MHz-QPSK-133147-1RB#24-PASS




Band71-5MHz-QPSK-133447-1RB#0-PASS




Band71-5MHz-QPSK-133447-25RB#0-PASS



Band71-5MHz-QPSK-133447-1RB#24-PASS




Band71-5MHz-16QAM-133147-1RB#0-PASS




Band71-5MHz-16QAM-133147-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-5MHz-16QAM-133147-1RB#24-PASS




Band71-5MHz-16QAM-133447-1RB#0-PASS




Band71-5MHz-16QAM-133447-25RB#0-PASS



Band71-5MHz-16QAM-133447-1RB#24-PASS




Band71-10MHz-QPSK-133172-1RB#0-PASS




Band71-10MHz-QPSK-133172-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-10MHz-QPSK-133172-1RB#49-PASS




Band71-10MHz-QPSK-133422-1RB#0-PASS




Band71-10MHz-QPSK-133422-50RB#0-PASS



Band71-10MHz-QPSK-133422-1RB#49-PASS




Band71-10MHz-16QAM-133172-1RB#0-PASS




Band71-10MHz-16QAM-133172-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-10MHz-16QAM-133172-1RB#49-PASS




Band71-10MHz-16QAM-133422-1RB#0-PASS




Band71-10MHz-16QAM-133422-50RB#0-PASS



Band71-10MHz-16QAM-133422-1RB#49-PASS




Band71-15MHz-QPSK-133197-1RB#0-PASS




Band71-15MHz-QPSK-133197-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-15MHz-QPSK-133197-1RB#74-PASS




Band71-15MHz-QPSK-133397-1RB#0-PASS




Band71-15MHz-QPSK-133397-75RB#0-PASS



Band71-15MHz-QPSK-133397-1RB#74-PASS




Band71-15MHz-16QAM-133197-1RB#0-PASS




Band71-15MHz-16QAM-133197-75RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-15MHz-16QAM-133197-1RB#74-PASS




Band71-15MHz-16QAM-133397-1RB#0-PASS




Band71-15MHz-16QAM-133397-75RB#0-PASS



Band71-15MHz-16QAM-133397-1RB#74-PASS




Band71-20MHz-QPSK-133222-1RB#0-PASS




Band71-20MHz-QPSK-133222-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-20MHz-QPSK-133222-1RB#99-PASS




Band71-20MHz-QPSK-133372-1RB#0-PASS




Band71-20MHz-QPSK-133372-100RB#0-PASS



Band71-20MHz-QPSK-133372-1RB#99-PASS




Band71-20MHz-16QAM-133222-1RB#0-PASS




Band71-20MHz-16QAM-133222-100RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band71-20MHz-16QAM-133222-1RB#99-PASS




Band71-20MHz-16QAM-133372-1RB#0-PASS




Band71-20MHz-16QAM-133372-100RB#0-PASS



Band71-20MHz-16QAM-133372-1RB#99-PASS




Band26(814-824)-1.4MHz-QPSK-26697-1RB#0-PASS




Band26(814-824)-1.4MHz-QPSK-26697-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-1.4MHz-QPSK-26697-1RB#5-PASS




Band26(814-824)-1.4MHz-QPSK-26783-1RB#0-PASS




Band26(814-824)-1.4MHz-QPSK-26783-6RB#0-PASS



Band26(814-824)-1.4MHz-QPSK-26783-1RB#5-PASS




Band26(814-824)-1.4MHz-16QAM-26697-1RB#0-PASS




Band26(814-824)-1.4MHz-16QAM-26697-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-1.4MHz-16QAM-26697-1RB#5-PASS




Band26(814-824)-1.4MHz-16QAM-26783-1RB#0-PASS




Band26(814-824)-1.4MHz-16QAM-26783-6RB#0-PASS



Band26(814-824)-1.4MHz-16QAM-26783-1RB#5-PASS




Band26(814-824)-3MHz-QPSK-26705-1RB#0-PASS




Band26(814-824)-3MHz-QPSK-26705-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-3MHz-QPSK-26705-1RB#14-PASS




Band26(814-824)-3MHz-QPSK-26775-1RB#0-PASS




Band26(814-824)-3MHz-QPSK-26775-15RB#0-PASS



Band26(814-824)-3MHz-QPSK-26775-1RB#14-PASS




Band26(814-824)-3MHz-16QAM-26705-1RB#0-PASS




Band26(814-824)-3MHz-16QAM-26705-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-3MHz-16QAM-26705-1RB#14-PASS




Band26(814-824)-3MHz-16QAM-26775-1RB#0-PASS




Band26(814-824)-3MHz-16QAM-26775-15RB#0-PASS



Band26(814-824)-3MHz-16QAM-26775-1RB#14-PASS




Band26(814-824)-5MHz-QPSK-26715-1RB#0-PASS




Band26(814-824)-5MHz-QPSK-26715-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-5MHz-QPSK-26715-1RB#24-PASS




Band26(814-824)-5MHz-QPSK-26765-1RB#0-PASS




Band26(814-824)-5MHz-QPSK-26765-25RB#0-PASS



Band26(814-824)-5MHz-QPSK-26765-1RB#24-PASS




Band26(814-824)-5MHz-16QAM-26715-1RB#0-PASS




Band26(814-824)-5MHz-16QAM-26715-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-5MHz-16QAM-26715-1RB#24-PASS




Band26(814-824)-5MHz-16QAM-26765-1RB#0-PASS




Band26(814-824)-5MHz-16QAM-26765-25RB#0-PASS



Band26(814-824)-5MHz-16QAM-26765-1RB#24-PASS




Band26(814-824)-10MHz-QPSK-26740-1RB#0-PASS




Band26(814-824)-10MHz-QPSK-26740-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(814-824)-10MHz-QPSK-26740-1RB#49-PASS




Band26(814-824)-10MHz-16QAM-26740-1RB#0-PASS




Band26(814-824)-10MHz-16QAM-26740-50RB#0-PASS



Band26(814-824)-10MHz-16QAM-26740-1RB#49-PASS




Band26(824-849)-1.4MHz-QPSK-26797-1RB#0-PASS




Band26(824-849)-1.4MHz-QPSK-26797-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-1.4MHz-QPSK-26797-1RB#5-PASS




Band26(824-849)-1.4MHz-QPSK-27033-1RB#0-PASS




Band26(824-849)-1.4MHz-QPSK-27033-6RB#0-PASS



Band26(824-849)-1.4MHz-QPSK-27033-1RB#5-PASS




Band26(824-849)-1.4MHz-16QAM-26797-1RB#0-PASS




Band26(824-849)-1.4MHz-16QAM-26797-6RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(824-849)-1.4MHz-16QAM-26797-1RB#5-PASS




Band26(824-849)-1.4MHz-16QAM-27033-1RB#0-PASS




Band26(824-849)-1.4MHz-16QAM-27033-6RB#0-PASS



Band26(824-849)-1.4MHz-16QAM-27033-1RB#5-PASS




Band26(824-849)-3MHz-QPSK-26805-1RB#0-PASS




Band26(824-849)-3MHz-QPSK-26805-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(824-849)-3MHz-QPSK-26805-1RB#14-PASS




Band26(824-849)-3MHz-QPSK-27025-1RB#0-PASS




Band26(824-849)-3MHz-QPSK-27025-15RB#0-PASS



Band26(824-849)-3MHz-QPSK-27025-1RB#14-PASS




Band26(824-849)-3MHz-16QAM-26805-1RB#0-PASS




Band26(824-849)-3MHz-16QAM-26805-15RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(824-849)-3MHz-16QAM-26805-1RB#14-PASS




Band26(824-849)-3MHz-16QAM-27025-1RB#0-PASS




Band26(824-849)-3MHz-16QAM-27025-15RB#0-PASS



Band26(824-849)-3MHz-16QAM-27025-1RB#14-PASS




Band26(824-849)-5MHz-QPSK-26815-1RB#0-PASS




Band26(824-849)-5MHz-QPSK-26815-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(824-849)-5MHz-QPSK-26815-1RB#24-PASS




Band26(824-849)-5MHz-QPSK-27015-1RB#0-PASS




Band26(824-849)-5MHz-QPSK-27015-25RB#0-PASS



Band26(824-849)-5MHz-QPSK-27015-1RB#24-PASS




Band26(824-849)-5MHz-16QAM-26815-1RB#0-PASS




Band26(824-849)-5MHz-16QAM-26815-25RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(824-849)-5MHz-16QAM-26815-1RB#24-PASS




Band26(824-849)-5MHz-16QAM-27015-1RB#0-PASS




Band26(824-849)-5MHz-16QAM-27015-25RB#0-PASS



Band26(824-849)-5MHz-16QAM-27015-1RB#24-PASS




Band26(824-849)-10MHz-QPSK-26840-1RB#0-PASS




Band26(824-849)-10MHz-QPSK-26840-50RB#0-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band26(824-849)-10MHz-QPSK-26840-1RB#49-PASS




Band26(824-849)-10MHz-QPSK-26990-1RB#0-PASS




Band26(824-849)-10MHz-QPSK-26990-50RB#0-PASS



Band26(824-849)-10MHz-QPSK-26990-1RB#49-PASS



Band26(824-849)-10MHz-16QAM-26840-1RB#0-PASS



Band26(824-849)-10MHz-16QAM-26840-50RB#0-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch