





Band2-20MHz-QPSK-18900-1RB#0-0.15~30-PASS




Band2-20MHz-QPSK-18900-1RB#0-30~1000-PASS




Band2-20MHz-QPSK-18900-1RB#0-1000~3000-PASS



Band2-20MHz-QPSK-18900-1RB#0-3000~20000-PASS




Band2-20MHz-QPSK-19100-1RB#0-0.009~0.15-PASS




Band2-20MHz-QPSK-19100-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band2-20MHz-QPSK-19100-1RB#0-30~1000-PASS




Band2-20MHz-QPSK-19100-1RB#0-1000~3000-PASS




Band2-20MHz-QPSK-19100-1RB#0-3000~20000-PASS



Band2-20MHz-16QAM-18700-1RB#0-0.009~0.15-PASS




Band2-20MHz-16QAM-18700-1RB#0-0.15~30-PASS




Band2-20MHz-16QAM-18700-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band2-20MHz-16QAM-18700-1RB#0-1000~3000-PASS




Band2-20MHz-16QAM-18700-1RB#0-3000~20000-PASS




Band2-20MHz-16QAM-18900-1RB#0-0.009~0.15-PASS



Band2-20MHz-16QAM-18900-1RB#0-0.15~30-PASS




Band2-20MHz-16QAM-18900-1RB#0-30~1000-PASS




Band2-20MHz-16QAM-18900-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band2-20MHz-16QAM-18900-1RB#0-3000~20000-PASS




Band2-20MHz-16QAM-19100-1RB#0-0.009~0.15-PASS




Band2-20MHz-16QAM-19100-1RB#0-0.15~30-PASS



Band2-20MHz-16QAM-19100-1RB#0-30~1000-PASS




Band2-20MHz-16QAM-19100-1RB#0-1000~3000-PASS




Band2-20MHz-16QAM-19100-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-1.4MHz-QPSK-19957-1RB#0-0.009~0.15-PASS




Band4-1.4MHz-QPSK-19957-1RB#0-0.15~30-PASS




Band4-1.4MHz-QPSK-19957-1RB#0-30~1000-PASS



Band4-1.4MHz-QPSK-19957-1RB#0-1000~3000-PASS




Band4-1.4MHz-QPSK-19957-1RB#0-3000~20000-PASS




Band4-1.4MHz-QPSK-20175-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-1.4MHz-QPSK-20175-1RB#0-0.15~30-PASS




Band4-1.4MHz-QPSK-20175-1RB#0-30~1000-PASS




Band4-1.4MHz-QPSK-20175-1RB#0-1000~3000-PASS



Band4-1.4MHz-QPSK-20175-1RB#0-3000~20000-PASS




Band4-1.4MHz-QPSK-20393-1RB#0-0.009~0.15-PASS




Band4-1.4MHz-QPSK-20393-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-1.4MHz-QPSK-20393-1RB#0-30~1000-PASS




Band4-1.4MHz-QPSK-20393-1RB#0-1000~3000-PASS




Band4-1.4MHz-QPSK-20393-1RB#0-3000~20000-PASS



Band4-1.4MHz-16QAM-19957-1RB#0-0.009~0.15-PASS




Band4-1.4MHz-16QAM-19957-1RB#0-0.15~30-PASS




Band4-1.4MHz-16QAM-19957-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-1.4MHz-16QAM-19957-1RB#0-1000~3000-PASS




Band4-1.4MHz-16QAM-19957-1RB#0-3000~20000-PASS




Band4-1.4MHz-16QAM-20175-1RB#0-0.009~0.15-PASS



Band4-1.4MHz-16QAM-20175-1RB#0-0.15~30-PASS




Band4-1.4MHz-16QAM-20175-1RB#0-30~1000-PASS




Band4-1.4MHz-16QAM-20175-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-1.4MHz-16QAM-20175-1RB#0-3000~20000-PASS




Band4-1.4MHz-16QAM-20393-1RB#0-0.009~0.15-PASS




Band4-1.4MHz-16QAM-20393-1RB#0-0.15~30-PASS



Band4-1.4MHz-16QAM-20393-1RB#0-30~1000-PASS




Band4-1.4MHz-16QAM-20393-1RB#0-1000~3000-PASS




Band4-1.4MHz-16QAM-20393-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-3MHz-QPSK-19965-1RB#0-0.009~0.15-PASS




Band4-3MHz-QPSK-19965-1RB#0-0.15~30-PASS




Band4-3MHz-QPSK-19965-1RB#0-30~1000-PASS



Band4-3MHz-QPSK-19965-1RB#0-1000~3000-PASS




Band4-3MHz-QPSK-19965-1RB#0-3000~20000-PASS




Band4-3MHz-QPSK-20175-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-3MHz-QPSK-20175-1RB#0-0.15~30-PASS




Band4-3MHz-QPSK-20175-1RB#0-30~1000-PASS




Band4-3MHz-QPSK-20175-1RB#0-1000~3000-PASS



Band4-3MHz-QPSK-20175-1RB#0-3000~20000-PASS




Band4-3MHz-QPSK-20385-1RB#0-0.009~0.15-PASS




Band4-3MHz-QPSK-20385-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-3MHz-QPSK-20385-1RB#0-30~1000-PASS




Band4-3MHz-QPSK-20385-1RB#0-1000~3000-PASS




Band4-3MHz-QPSK-20385-1RB#0-3000~20000-PASS



Band4-3MHz-16QAM-19965-1RB#0-0.009~0.15-PASS




Band4-3MHz-16QAM-19965-1RB#0-0.15~30-PASS




Band4-3MHz-16QAM-19965-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-3MHz-16QAM-19965-1RB#0-1000~3000-PASS




Band4-3MHz-16QAM-19965-1RB#0-3000~20000-PASS




Band4-3MHz-16QAM-20175-1RB#0-0.009~0.15-PASS



Band4-3MHz-16QAM-20175-1RB#0-0.15~30-PASS




Band4-3MHz-16QAM-20175-1RB#0-30~1000-PASS




Band4-3MHz-16QAM-20175-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-3MHz-16QAM-20175-1RB#0-3000~20000-PASS




Band4-3MHz-16QAM-20385-1RB#0-0.009~0.15-PASS




Band4-3MHz-16QAM-20385-1RB#0-0.15~30-PASS



Band4-3MHz-16QAM-20385-1RB#0-30~1000-PASS




Band4-3MHz-16QAM-20385-1RB#0-1000~3000-PASS




Band4-3MHz-16QAM-20385-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-5MHz-QPSK-19975-1RB#0-0.009~0.15-PASS




Band4-5MHz-QPSK-19975-1RB#0-0.15~30-PASS




Band4-5MHz-QPSK-19975-1RB#0-30~1000-PASS



Band4-5MHz-QPSK-19975-1RB#0-1000~3000-PASS




Band4-5MHz-QPSK-19975-1RB#0-3000~20000-PASS




Band4-5MHz-QPSK-20175-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-5MHz-QPSK-20175-1RB#0-0.15~30-PASS




Band4-5MHz-QPSK-20175-1RB#0-30~1000-PASS




Band4-5MHz-QPSK-20175-1RB#0-1000~3000-PASS



Band4-5MHz-QPSK-20175-1RB#0-3000~20000-PASS




Band4-5MHz-QPSK-20375-1RB#0-0.009~0.15-PASS




Band4-5MHz-QPSK-20375-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-5MHz-QPSK-20375-1RB#0-30~1000-PASS




Band4-5MHz-QPSK-20375-1RB#0-1000~3000-PASS




Band4-5MHz-QPSK-20375-1RB#0-3000~20000-PASS



Band4-5MHz-16QAM-19975-1RB#0-0.009~0.15-PASS




Band4-5MHz-16QAM-19975-1RB#0-0.15~30-PASS




Band4-5MHz-16QAM-19975-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-5MHz-16QAM-19975-1RB#0-1000~3000-PASS




Band4-5MHz-16QAM-19975-1RB#0-3000~20000-PASS




Band4-5MHz-16QAM-20175-1RB#0-0.009~0.15-PASS



Band4-5MHz-16QAM-20175-1RB#0-0.15~30-PASS




Band4-5MHz-16QAM-20175-1RB#0-30~1000-PASS




Band4-5MHz-16QAM-20175-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-5MHz-16QAM-20175-1RB#0-3000~20000-PASS




Band4-5MHz-16QAM-20375-1RB#0-0.009~0.15-PASS




Band4-5MHz-16QAM-20375-1RB#0-0.15~30-PASS



Band4-5MHz-16QAM-20375-1RB#0-30~1000-PASS




Band4-5MHz-16QAM-20375-1RB#0-1000~3000-PASS




Band4-5MHz-16QAM-20375-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-QPSK-20000-1RB#0-0.009~0.15-PASS




Band4-10MHz-QPSK-20000-1RB#0-0.15~30-PASS




Band4-10MHz-QPSK-20000-1RB#0-30~1000-PASS



Band4-10MHz-QPSK-20000-1RB#0-1000~3000-PASS




Band4-10MHz-QPSK-20000-1RB#0-3000~20000-PASS




Band4-10MHz-QPSK-20175-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-QPSK-20175-1RB#0-0.15~30-PASS




Band4-10MHz-QPSK-20175-1RB#0-30~1000-PASS




Band4-10MHz-QPSK-20175-1RB#0-1000~3000-PASS



Band4-10MHz-QPSK-20175-1RB#0-3000~20000-PASS




Band4-10MHz-QPSK-20350-1RB#0-0.009~0.15-PASS




Band4-10MHz-QPSK-20350-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-QPSK-20350-1RB#0-30~1000-PASS




Band4-10MHz-QPSK-20350-1RB#0-1000~3000-PASS




Band4-10MHz-QPSK-20350-1RB#0-3000~20000-PASS



Band4-10MHz-16QAM-20000-1RB#0-0.009~0.15-PASS




Band4-10MHz-16QAM-20000-1RB#0-0.15~30-PASS




Band4-10MHz-16QAM-20000-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-16QAM-20000-1RB#0-1000~3000-PASS




Band4-10MHz-16QAM-20000-1RB#0-3000~20000-PASS




Band4-10MHz-16QAM-20175-1RB#0-0.009~0.15-PASS



Band4-10MHz-16QAM-20175-1RB#0-0.15~30-PASS




Band4-10MHz-16QAM-20175-1RB#0-30~1000-PASS




Band4-10MHz-16QAM-20175-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-10MHz-16QAM-20175-1RB#0-3000~20000-PASS




Band4-10MHz-16QAM-20350-1RB#0-0.009~0.15-PASS




Band4-10MHz-16QAM-20350-1RB#0-0.15~30-PASS



Band4-10MHz-16QAM-20350-1RB#0-30~1000-PASS




Band4-10MHz-16QAM-20350-1RB#0-1000~3000-PASS




Band4-10MHz-16QAM-20350-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-QPSK-20025-1RB#0-0.009~0.15-PASS




Band4-15MHz-QPSK-20025-1RB#0-0.15~30-PASS




Band4-15MHz-QPSK-20025-1RB#0-30~1000-PASS



Band4-15MHz-QPSK-20025-1RB#0-1000~3000-PASS




Band4-15MHz-QPSK-20025-1RB#0-3000~20000-PASS




Band4-15MHz-QPSK-20175-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-QPSK-20175-1RB#0-0.15~30-PASS




Band4-15MHz-QPSK-20175-1RB#0-30~1000-PASS




Band4-15MHz-QPSK-20175-1RB#0-1000~3000-PASS



Band4-15MHz-QPSK-20175-1RB#0-3000~20000-PASS




Band4-15MHz-QPSK-20325-1RB#0-0.009~0.15-PASS




Band4-15MHz-QPSK-20325-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-QPSK-20325-1RB#0-30~1000-PASS




Band4-15MHz-QPSK-20325-1RB#0-1000~3000-PASS




Band4-15MHz-QPSK-20325-1RB#0-3000~20000-PASS



Band4-15MHz-16QAM-20025-1RB#0-0.009~0.15-PASS




Band4-15MHz-16QAM-20025-1RB#0-0.15~30-PASS




Band4-15MHz-16QAM-20025-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-16QAM-20025-1RB#0-1000~3000-PASS




Band4-15MHz-16QAM-20025-1RB#0-3000~20000-PASS




Band4-15MHz-16QAM-20175-1RB#0-0.009~0.15-PASS



Band4-15MHz-16QAM-20175-1RB#0-0.15~30-PASS




Band4-15MHz-16QAM-20175-1RB#0-30~1000-PASS




Band4-15MHz-16QAM-20175-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-15MHz-16QAM-20175-1RB#0-3000~20000-PASS




Band4-15MHz-16QAM-20325-1RB#0-0.009~0.15-PASS




Band4-15MHz-16QAM-20325-1RB#0-0.15~30-PASS



Band4-15MHz-16QAM-20325-1RB#0-30~1000-PASS




Band4-15MHz-16QAM-20325-1RB#0-1000~3000-PASS




Band4-15MHz-16QAM-20325-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-QPSK-20050-1RB#0-0.009~0.15-PASS




Band4-20MHz-QPSK-20050-1RB#0-0.15~30-PASS




Band4-20MHz-QPSK-20050-1RB#0-30~1000-PASS



Band4-20MHz-QPSK-20050-1RB#0-1000~3000-PASS




Band4-20MHz-QPSK-20050-1RB#0-3000~20000-PASS




Band4-20MHz-QPSK-20175-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-QPSK-20175-1RB#0-0.15~30-PASS




Band4-20MHz-QPSK-20175-1RB#0-30~1000-PASS




Band4-20MHz-QPSK-20175-1RB#0-1000~3000-PASS



Band4-20MHz-QPSK-20175-1RB#0-3000~20000-PASS




Band4-20MHz-QPSK-20300-1RB#0-0.009~0.15-PASS




Band4-20MHz-QPSK-20300-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-QPSK-20300-1RB#0-30~1000-PASS




Band4-20MHz-QPSK-20300-1RB#0-1000~3000-PASS




Band4-20MHz-QPSK-20300-1RB#0-3000~20000-PASS



Band4-20MHz-16QAM-20050-1RB#0-0.009~0.15-PASS




Band4-20MHz-16QAM-20050-1RB#0-0.15~30-PASS




Band4-20MHz-16QAM-20050-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-16QAM-20050-1RB#0-1000~3000-PASS




Band4-20MHz-16QAM-20050-1RB#0-3000~20000-PASS




Band4-20MHz-16QAM-20175-1RB#0-0.009~0.15-PASS



Band4-20MHz-16QAM-20175-1RB#0-0.15~30-PASS




Band4-20MHz-16QAM-20175-1RB#0-30~1000-PASS




Band4-20MHz-16QAM-20175-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band4-20MHz-16QAM-20175-1RB#0-3000~20000-PASS




Band4-20MHz-16QAM-20300-1RB#0-0.009~0.15-PASS




Band4-20MHz-16QAM-20300-1RB#0-0.15~30-PASS



Band4-20MHz-16QAM-20300-1RB#0-30~1000-PASS




Band4-20MHz-16QAM-20300-1RB#0-1000~3000-PASS




Band4-20MHz-16QAM-20300-1RB#0-3000~20000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-QPSK-20407-1RB#0-0.009~0.15-PASS




Band5-1.4MHz-QPSK-20407-1RB#0-0.15~30-PASS




Band5-1.4MHz-QPSK-20407-1RB#0-30~1000-PASS



Band5-1.4MHz-QPSK-20407-1RB#0-1000~3000-PASS




Band5-1.4MHz-QPSK-20407-1RB#0-3000~10000-PASS




Band5-1.4MHz-QPSK-20525-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-QPSK-20525-1RB#0-0.15~30-PASS




Band5-1.4MHz-QPSK-20525-1RB#0-30~1000-PASS




Band5-1.4MHz-QPSK-20525-1RB#0-1000~3000-PASS



Band5-1.4MHz-QPSK-20525-1RB#0-3000~10000-PASS




Band5-1.4MHz-QPSK-20643-1RB#0-0.009~0.15-PASS




Band5-1.4MHz-QPSK-20643-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-QPSK-20643-1RB#0-30~1000-PASS




Band5-1.4MHz-QPSK-20643-1RB#0-1000~3000-PASS




Band5-1.4MHz-QPSK-20643-1RB#0-3000~10000-PASS



Band5-1.4MHz-16QAM-20407-1RB#0-0.009~0.15-PASS




Band5-1.4MHz-16QAM-20407-1RB#0-0.15~30-PASS




Band5-1.4MHz-16QAM-20407-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-16QAM-20407-1RB#0-1000~3000-PASS




Band5-1.4MHz-16QAM-20407-1RB#0-3000~10000-PASS




Band5-1.4MHz-16QAM-20525-1RB#0-0.009~0.15-PASS



Band5-1.4MHz-16QAM-20525-1RB#0-0.15~30-PASS




Band5-1.4MHz-16QAM-20525-1RB#0-30~1000-PASS




Band5-1.4MHz-16QAM-20525-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-1.4MHz-16QAM-20525-1RB#0-3000~10000-PASS




Band5-1.4MHz-16QAM-20643-1RB#0-0.009~0.15-PASS




Band5-1.4MHz-16QAM-20643-1RB#0-0.15~30-PASS



Band5-1.4MHz-16QAM-20643-1RB#0-30~1000-PASS




Band5-1.4MHz-16QAM-20643-1RB#0-1000~3000-PASS




Band5-1.4MHz-16QAM-20643-1RB#0-3000~10000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-QPSK-20415-1RB#0-0.009~0.15-PASS




Band5-3MHz-QPSK-20415-1RB#0-0.15~30-PASS




Band5-3MHz-QPSK-20415-1RB#0-30~1000-PASS



Band5-3MHz-QPSK-20415-1RB#0-1000~3000-PASS




Band5-3MHz-QPSK-20415-1RB#0-3000~10000-PASS




Band5-3MHz-QPSK-20525-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-QPSK-20525-1RB#0-0.15~30-PASS




Band5-3MHz-QPSK-20525-1RB#0-30~1000-PASS




Band5-3MHz-QPSK-20525-1RB#0-1000~3000-PASS



Band5-3MHz-QPSK-20525-1RB#0-3000~10000-PASS




Band5-3MHz-QPSK-20635-1RB#0-0.009~0.15-PASS




Band5-3MHz-QPSK-20635-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-QPSK-20635-1RB#0-30~1000-PASS




Band5-3MHz-QPSK-20635-1RB#0-1000~3000-PASS




Band5-3MHz-QPSK-20635-1RB#0-3000~10000-PASS



Band5-3MHz-16QAM-20415-1RB#0-0.009~0.15-PASS




Band5-3MHz-16QAM-20415-1RB#0-0.15~30-PASS




Band5-3MHz-16QAM-20415-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-16QAM-20415-1RB#0-1000~3000-PASS




Band5-3MHz-16QAM-20415-1RB#0-3000~10000-PASS




Band5-3MHz-16QAM-20525-1RB#0-0.009~0.15-PASS



Band5-3MHz-16QAM-20525-1RB#0-0.15~30-PASS




Band5-3MHz-16QAM-20525-1RB#0-30~1000-PASS




Band5-3MHz-16QAM-20525-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-3MHz-16QAM-20525-1RB#0-3000~10000-PASS




Band5-3MHz-16QAM-20635-1RB#0-0.009~0.15-PASS




Band5-3MHz-16QAM-20635-1RB#0-0.15~30-PASS



Band5-3MHz-16QAM-20635-1RB#0-30~1000-PASS




Band5-3MHz-16QAM-20635-1RB#0-1000~3000-PASS




Band5-3MHz-16QAM-20635-1RB#0-3000~10000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-QPSK-20425-1RB#0-0.009~0.15-PASS




Band5-5MHz-QPSK-20425-1RB#0-0.15~30-PASS




Band5-5MHz-QPSK-20425-1RB#0-30~1000-PASS



Band5-5MHz-QPSK-20425-1RB#0-1000~3000-PASS




Band5-5MHz-QPSK-20425-1RB#0-3000~10000-PASS




Band5-5MHz-QPSK-20525-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-QPSK-20525-1RB#0-0.15~30-PASS




Band5-5MHz-QPSK-20525-1RB#0-30~1000-PASS




Band5-5MHz-QPSK-20525-1RB#0-1000~3000-PASS



Band5-5MHz-QPSK-20525-1RB#0-3000~10000-PASS




Band5-5MHz-QPSK-20625-1RB#0-0.009~0.15-PASS




Band5-5MHz-QPSK-20625-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-QPSK-20625-1RB#0-30~1000-PASS




Band5-5MHz-QPSK-20625-1RB#0-1000~3000-PASS




Band5-5MHz-QPSK-20625-1RB#0-3000~10000-PASS



Band5-5MHz-16QAM-20425-1RB#0-0.009~0.15-PASS




Band5-5MHz-16QAM-20425-1RB#0-0.15~30-PASS




Band5-5MHz-16QAM-20425-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-16QAM-20425-1RB#0-1000~3000-PASS




Band5-5MHz-16QAM-20425-1RB#0-3000~10000-PASS




Band5-5MHz-16QAM-20525-1RB#0-0.009~0.15-PASS



Band5-5MHz-16QAM-20525-1RB#0-0.15~30-PASS




Band5-5MHz-16QAM-20525-1RB#0-30~1000-PASS




Band5-5MHz-16QAM-20525-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-5MHz-16QAM-20525-1RB#0-3000~10000-PASS




Band5-5MHz-16QAM-20625-1RB#0-0.009~0.15-PASS




Band5-5MHz-16QAM-20625-1RB#0-0.15~30-PASS



Band5-5MHz-16QAM-20625-1RB#0-30~1000-PASS




Band5-5MHz-16QAM-20625-1RB#0-1000~3000-PASS




Band5-5MHz-16QAM-20625-1RB#0-3000~10000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-QPSK-20450-1RB#0-0.009~0.15-PASS




Band5-10MHz-QPSK-20450-1RB#0-0.15~30-PASS




Band5-10MHz-QPSK-20450-1RB#0-30~1000-PASS



Band5-10MHz-QPSK-20450-1RB#0-1000~3000-PASS




Band5-10MHz-QPSK-20450-1RB#0-3000~10000-PASS




Band5-10MHz-QPSK-20525-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-QPSK-20525-1RB#0-0.15~30-PASS




Band5-10MHz-QPSK-20525-1RB#0-30~1000-PASS




Band5-10MHz-QPSK-20525-1RB#0-1000~3000-PASS



Band5-10MHz-QPSK-20525-1RB#0-3000~10000-PASS




Band5-10MHz-QPSK-20600-1RB#0-0.009~0.15-PASS




Band5-10MHz-QPSK-20600-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-QPSK-20600-1RB#0-30~1000-PASS




Band5-10MHz-QPSK-20600-1RB#0-1000~3000-PASS




Band5-10MHz-QPSK-20600-1RB#0-3000~10000-PASS



Band5-10MHz-16QAM-20450-1RB#0-0.009~0.15-PASS




Band5-10MHz-16QAM-20450-1RB#0-0.15~30-PASS




Band5-10MHz-16QAM-20450-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-16QAM-20450-1RB#0-1000~3000-PASS




Band5-10MHz-16QAM-20450-1RB#0-3000~10000-PASS




Band5-10MHz-16QAM-20525-1RB#0-0.009~0.15-PASS



Band5-10MHz-16QAM-20525-1RB#0-0.15~30-PASS




Band5-10MHz-16QAM-20525-1RB#0-30~1000-PASS




Band5-10MHz-16QAM-20525-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band5-10MHz-16QAM-20525-1RB#0-3000~10000-PASS




Band5-10MHz-16QAM-20600-1RB#0-0.009~0.15-PASS




Band5-10MHz-16QAM-20600-1RB#0-0.15~30-PASS



Band5-10MHz-16QAM-20600-1RB#0-30~1000-PASS




Band5-10MHz-16QAM-20600-1RB#0-1000~3000-PASS




Band5-10MHz-16QAM-20600-1RB#0-3000~10000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-QPSK-23017-1RB#0-0.009~0.15-PASS




Band12-1.4MHz-QPSK-23017-1RB#0-0.15~30-PASS




Band12-1.4MHz-QPSK-23017-1RB#0-30~1000-PASS



Band12-1.4MHz-QPSK-23017-1RB#0-1000~3000-PASS




Band12-1.4MHz-QPSK-23017-1RB#0-3000~10000-PASS




Band12-1.4MHz-QPSK-23095-1RB#0-0.009~0.15-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-QPSK-23095-1RB#0-0.15~30-PASS




Band12-1.4MHz-QPSK-23095-1RB#0-30~1000-PASS




Band12-1.4MHz-QPSK-23095-1RB#0-1000~3000-PASS



Band12-1.4MHz-QPSK-23095-1RB#0-3000~10000-PASS




Band12-1.4MHz-QPSK-23173-1RB#0-0.009~0.15-PASS




Band12-1.4MHz-QPSK-23173-1RB#0-0.15~30-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-QPSK-23173-1RB#0-30~1000-PASS




Band12-1.4MHz-QPSK-23173-1RB#0-1000~3000-PASS




Band12-1.4MHz-QPSK-23173-1RB#0-3000~10000-PASS



Band12-1.4MHz-16QAM-23017-1RB#0-0.009~0.15-PASS




Band12-1.4MHz-16QAM-23017-1RB#0-0.15~30-PASS




Band12-1.4MHz-16QAM-23017-1RB#0-30~1000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-16QAM-23017-1RB#0-1000~3000-PASS




Band12-1.4MHz-16QAM-23017-1RB#0-3000~10000-PASS




Band12-1.4MHz-16QAM-23095-1RB#0-0.009~0.15-PASS



Band12-1.4MHz-16QAM-23095-1RB#0-0.15~30-PASS




Band12-1.4MHz-16QAM-23095-1RB#0-30~1000-PASS




Band12-1.4MHz-16QAM-23095-1RB#0-1000~3000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-1.4MHz-16QAM-23095-1RB#0-3000~10000-PASS




Band12-1.4MHz-16QAM-23173-1RB#0-0.009~0.15-PASS




Band12-1.4MHz-16QAM-23173-1RB#0-0.15~30-PASS



Band12-1.4MHz-16QAM-23173-1RB#0-30~1000-PASS




Band12-1.4MHz-16QAM-23173-1RB#0-1000~3000-PASS




Band12-1.4MHz-16QAM-23173-1RB#0-3000~10000-PASS


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch




Band12-3MHz-QPSK-23025-1RB#0-0.009~0.15-PASS




Band12-3MHz-QPSK-23025-1RB#0-0.15~30-PASS




Band12-3MHz-QPSK-23025-1RB#0-30~1000-PASS



Band12-3MHz-QPSK-23025-1RB#0-1000~3000-PASS



Band12-3MHz-QPSK-23025-1RB#0-3000~10000-PASS



Band12-3MHz-QPSK-23095-1RB#0-0.009~0.15-PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch