

Band2-3MHz-16QAM-19185-1RB#0-Range1:30~1000MHz



Band2-3MHz-16QAM-19185-1RB#0-Range2:1000~20000MHz



Band2-5MHz-QPSK-18625-1RB#0-Range1:30~1000MHz



Band2-5MHz-QPSK-18625-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-5MHz-QPSK-18900-1RB#0-Range1:30~1000MHz



Band2-5MHz-QPSK-18900-1RB#0-Range2:1000~20000MHz



Band2-5MHz-QPSK-19175-1RB#0-Range1:30~1000MHz



Band2-5MHz-QPSK-19175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-5MHz-16QAM-18625-1RB#0-Range1:30~1000MHz



Band2-5MHz-16QAM-18625-1RB#0-Range2:1000~20000MHz



Band2-5MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-5MHz-16QAM-18900-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-5MHz-16QAM-19175-1RB#0-Range1:30~1000MHz



Band2-5MHz-16QAM-19175-1RB#0-Range2:1000~20000MHz



Band2-10MHz-QPSK-18650-1RB#0-Range1:30~1000MHz



Band2-10MHz-QPSK-18650-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-10MHz-QPSK-18900-1RB#0-Range1:30~1000MHz



Band2-10MHz-QPSK-18900-1RB#0-Range2:1000~20000MHz



Band2-10MHz-QPSK-19150-1RB#0-Range1:30~1000MHz



Band2-10MHz-QPSK-19150-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-10MHz-16QAM-18650-1RB#0-Range1:30~1000MHz



Band2-10MHz-16QAM-18650-1RB#0-Range2:1000~20000MHz



Band2-10MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-10MHz-16QAM-18900-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-10MHz-16QAM-19150-1RB#0-Range1:30~1000MHz



Band2-10MHz-16QAM-19150-1RB#0-Range2:1000~20000MHz



Band2-15MHz-QPSK-18675-1RB#0-Range1:30~1000MHz



Band2-15MHz-QPSK-18675-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-15MHz-QPSK-18900-1RB#0-Range1:30~1000MHz



Band2-15MHz-QPSK-18900-1RB#0-Range2:1000~20000MHz



Band2-15MHz-QPSK-19125-1RB#0-Range1:30~1000MHz



Band2-15MHz-QPSK-19125-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-15MHz-16QAM-18675-1RB#0-Range1:30~1000MHz



Band2-15MHz-16QAM-18675-1RB#0-Range2:1000~20000MHz



Band2-15MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-15MHz-16QAM-18900-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-15MHz-16QAM-19125-1RB#0-Range1:30~1000MHz



Band2-15MHz-16QAM-19125-1RB#0-Range2:1000~20000MHz



Band2-20MHz-QPSK-18700-1RB#0-Range1:30~1000MHz



Band2-20MHz-QPSK-18700-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-20MHz-QPSK-18900-1RB#0-Range1:30~1000MHz



Band2-20MHz-QPSK-18900-1RB#0-Range2:1000~20000MHz



Band2-20MHz-QPSK-19100-1RB#0-Range1:30~1000MHz



Band2-20MHz-QPSK-19100-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-20MHz-16QAM-18700-1RB#0-Range1:30~1000MHz



Band2-20MHz-16QAM-18700-1RB#0-Range2:1000~20000MHz



Band2-20MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-20MHz-16QAM-18900-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band2-20MHz-16QAM-19100-1RB#0-Range1:30~1000MHz



Band2-20MHz-16QAM-19100-1RB#0-Range2:1000~20000MHz



Band4-1.4MHz-QPSK-19957-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-QPSK-19957-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-1.4MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-QPSK-20175-1RB#0-Range2:1000~20000MHz



Band4-1.4MHz-QPSK-20393-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-QPSK-20393-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-1.4MHz-16QAM-19957-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-16QAM-19957-1RB#0-Range2:1000~20000MHz



Band4-1.4MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-16QAM-20175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-1.4MHz-16QAM-20393-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-16QAM-20393-1RB#0-Range2:1000~20000MHz



Band4-3MHz-QPSK-19965-1RB#0-Range1:30~1000MHz



Band4-3MHz-QPSK-19965-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-3MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



Band4-3MHz-QPSK-20175-1RB#0-Range2:1000~20000MHz



Band4-3MHz-QPSK-20385-1RB#0-Range1:30~1000MHz



Band4-3MHz-QPSK-20385-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-3MHz-16QAM-19965-1RB#0-Range1:30~1000MHz



Band4-3MHz-16QAM-19965-1RB#0-Range2:1000~20000MHz



Band4-3MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-3MHz-16QAM-20175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-3MHz-16QAM-20385-1RB#0-Range1:30~1000MHz



Band4-3MHz-16QAM-20385-1RB#0-Range2:1000~20000MHz



Band4-5MHz-QPSK-19975-1RB#0-Range1:30~1000MHz



Band4-5MHz-QPSK-19975-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-5MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



Band4-5MHz-QPSK-20175-1RB#0-Range2:1000~20000MHz



Band4-5MHz-QPSK-20375-1RB#0-Range1:30~1000MHz



Band4-5MHz-QPSK-20375-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-5MHz-16QAM-19975-1RB#0-Range1:30~1000MHz



Band4-5MHz-16QAM-19975-1RB#0-Range2:1000~20000MHz



Band4-5MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-5MHz-16QAM-20175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-5MHz-16QAM-20375-1RB#0-Range1:30~1000MHz



Band4-5MHz-16QAM-20375-1RB#0-Range2:1000~20000MHz



Band4-10MHz-QPSK-20000-1RB#0-Range1:30~1000MHz



Band4-10MHz-QPSK-20000-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-10MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



Band4-10MHz-QPSK-20175-1RB#0-Range2:1000~20000MHz



Band4-10MHz-QPSK-20350-1RB#0-Range1:30~1000MHz



Band4-10MHz-QPSK-20350-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-10MHz-16QAM-20000-1RB#0-Range1:30~1000MHz



Band4-10MHz-16QAM-20000-1RB#0-Range2:1000~20000MHz



Band4-10MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-10MHz-16QAM-20175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-10MHz-16QAM-20350-1RB#0-Range1:30~1000MHz



Band4-10MHz-16QAM-20350-1RB#0-Range2:1000~20000MHz



Band4-15MHz-QPSK-20025-1RB#0-Range1:30~1000MHz



Band4-15MHz-QPSK-20025-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-15MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



Band4-15MHz-QPSK-20175-1RB#0-Range2:1000~20000MHz



Band4-15MHz-QPSK-20325-1RB#0-Range1:30~1000MHz



Band4-15MHz-QPSK-20325-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-15MHz-16QAM-20025-1RB#0-Range1:30~1000MHz



Band4-15MHz-16QAM-20025-1RB#0-Range2:1000~20000MHz



Band4-15MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-15MHz-16QAM-20175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch