

Band4-15MHz-16QAM-20325-1RB#0-Range1:30~1000MHz



Band4-15MHz-16QAM-20325-1RB#0-Range2:1000~20000MHz



Band4-20MHz-QPSK-20050-1RB#0-Range1:30~1000MHz



Band4-20MHz-QPSK-20050-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-20MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



Band4-20MHz-QPSK-20175-1RB#0-Range2:1000~20000MHz



Band4-20MHz-QPSK-20300-1RB#0-Range1:30~1000MHz



Band4-20MHz-QPSK-20300-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-20MHz-16QAM-20050-1RB#0-Range1:30~1000MHz



Band4-20MHz-16QAM-20050-1RB#0-Range2:1000~20000MHz



Band4-20MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-20MHz-16QAM-20175-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band4-20MHz-16QAM-20300-1RB#0-Range1:30~1000MHz



Band4-20MHz-16QAM-20300-1RB#0-Range2:1000~20000MHz



Band5-1.4MHz-QPSK-20407-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-QPSK-20407-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-1.4MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



Band5-1.4MHz-QPSK-20643-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-QPSK-20643-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-1.4MHz-16QAM-20407-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-16QAM-20407-1RB#0-Range2:1000~10000MHz



Band5-1.4MHz-16QAM-20525-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-1.4MHz-16QAM-20643-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-16QAM-20643-1RB#0-Range2:1000~10000MHz



Band5-3MHz-QPSK-20415-1RB#0-Range1:30~1000MHz



Band5-3MHz-QPSK-20415-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-3MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



Band5-3MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



Band5-3MHz-QPSK-20635-1RB#0-Range1:30~1000MHz



Band5-3MHz-QPSK-20635-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-3MHz-16QAM-20415-1RB#0-Range1:30~1000MHz



Band5-3MHz-16QAM-20415-1RB#0-Range2:1000~10000MHz



Band5-3MHz-16QAM-20525-1RB#0-Range1:30~1000MHz



Band5-3MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-3MHz-16QAM-20635-1RB#0-Range1:30~1000MHz



Band5-3MHz-16QAM-20635-1RB#0-Range2:1000~10000MHz



Band5-5MHz-QPSK-20425-1RB#0-Range1:30~1000MHz



Band5-5MHz-QPSK-20425-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-5MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



Band5-5MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



Band5-5MHz-QPSK-20625-1RB#0-Range1:30~1000MHz



Band5-5MHz-QPSK-20625-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-5MHz-16QAM-20425-1RB#0-Range1:30~1000MHz



Band5-5MHz-16QAM-20425-1RB#0-Range2:1000~10000MHz



Band5-5MHz-16QAM-20525-1RB#0-Range1:30~1000MHz



Band5-5MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-5MHz-16QAM-20625-1RB#0-Range1:30~1000MHz



Band5-5MHz-16QAM-20625-1RB#0-Range2:1000~10000MHz



Band5-10MHz-QPSK-20450-1RB#0-Range1:30~1000MHz



Band5-10MHz-QPSK-20450-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-10MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



Band5-10MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



Band5-10MHz-QPSK-20600-1RB#0-Range1:30~1000MHz



Band5-10MHz-QPSK-20600-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-10MHz-16QAM-20450-1RB#0-Range1:30~1000MHz



Band5-10MHz-16QAM-20450-1RB#0-Range2:1000~10000MHz



Band5-10MHz-16QAM-20525-1RB#0-Range1:30~1000MHz



Band5-10MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band5-10MHz-16QAM-20600-1RB#0-Range1:30~1000MHz



Band5-10MHz-16QAM-20600-1RB#0-Range2:1000~10000MHz



Band7-5MHz-QPSK-20775-1RB#0-Range1:30~1000MHz



Band7-5MHz-QPSK-20775-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-5MHz-QPSK-21100-1RB#0-Range1:30~1000MHz



Band7-5MHz-QPSK-21100-1RB#0-Range2:1000~26500MHz



Band7-5MHz-QPSK-21425-1RB#0-Range1:30~1000MHz



Band7-5MHz-QPSK-21425-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-5MHz-16QAM-20775-1RB#0-Range1:30~1000MHz



Band7-5MHz-16QAM-20775-1RB#0-Range2:1000~26500MHz



Band7-5MHz-16QAM-21100-1RB#0-Range1:30~1000MHz



Band7-5MHz-16QAM-21100-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-5MHz-16QAM-21425-1RB#0-Range1:30~1000MHz



Band7-5MHz-16QAM-21425-1RB#0-Range2:1000~26500MHz



Band7-10MHz-QPSK-20800-1RB#0-Range1:30~1000MHz



Band7-10MHz-QPSK-20800-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-10MHz-QPSK-21100-1RB#0-Range1:30~1000MHz



Band7-10MHz-QPSK-21100-1RB#0-Range2:1000~26500MHz



Band7-10MHz-QPSK-21400-1RB#0-Range1:30~1000MHz



Band7-10MHz-QPSK-21400-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-10MHz-16QAM-20800-1RB#0-Range1:30~1000MHz



Band7-10MHz-16QAM-20800-1RB#0-Range2:1000~26500MHz



Band7-10MHz-16QAM-21100-1RB#0-Range1:30~1000MHz



Band7-10MHz-16QAM-21100-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-10MHz-16QAM-21400-1RB#0-Range1:30~1000MHz



Band7-10MHz-16QAM-21400-1RB#0-Range2:1000~26500MHz



Band7-15MHz-QPSK-20825-1RB#0-Range1:30~1000MHz



Band7-15MHz-QPSK-20825-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-15MHz-QPSK-21100-1RB#0-Range1:30~1000MHz



Band7-15MHz-QPSK-21100-1RB#0-Range2:1000~26500MHz



Band7-15MHz-QPSK-21375-1RB#0-Range1:30~1000MHz



Band7-15MHz-QPSK-21375-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-15MHz-16QAM-20825-1RB#0-Range1:30~1000MHz



Band7-15MHz-16QAM-20825-1RB#0-Range2:1000~26500MHz



Band7-15MHz-16QAM-21100-1RB#0-Range1:30~1000MHz



Band7-15MHz-16QAM-21100-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-15MHz-16QAM-21375-1RB#0-Range1:30~1000MHz



Band7-15MHz-16QAM-21375-1RB#0-Range2:1000~26500MHz



Band7-20MHz-QPSK-20850-1RB#0-Range1:30~1000MHz



Band7-20MHz-QPSK-20850-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band7-20MHz-QPSK-21100-1RB#0-Range1:30~1000MHz



Band7-20MHz-QPSK-21100-1RB#0-Range2:1000~26500MHz



Band7-20MHz-QPSK-21350-1RB#0-Range1:30~1000MHz



Band7-20MHz-QPSK-21350-1RB#0-Range2:1000~26500MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch