

Band41-20MHz-16QAM-41490-1RB#0-Range1:30~1000MHz



Band41-20MHz-16QAM-41490-1RB#0-Range2:1000~26500MHz



Band66-1.4MHz-QPSK-131979-1RB#0-Range1:30~1000MHz



Band66-1.4MHz-QPSK-131979-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-1.4MHz-QPSK-132322-1RB#0-Range1:30~1000MHz



Band66-1.4MHz-QPSK-132322-1RB#0-Range2:1000~20000MHz



Band66-1.4MHz-QPSK-132665-1RB#0-Range1:30~1000MHz



Band66-1.4MHz-QPSK-132665-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-1.4MHz-16QAM-131979-1RB#0-Range1:30~1000MHz



Band66-1.4MHz-16QAM-131979-1RB#0-Range2:1000~20000MHz



Band66-1.4MHz-16QAM-132322-1RB#0-Range1:30~1000MHz



Band66-1.4MHz-16QAM-132322-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-1.4MHz-16QAM-132665-1RB#0-Range1:30~1000MHz



Band66-1.4MHz-16QAM-132665-1RB#0-Range2:1000~20000MHz



Band66-3MHz-QPSK-131987-1RB#0-Range1:30~1000MHz



Band66-3MHz-QPSK-131987-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-3MHz-QPSK-132322-1RB#0-Range1:30~1000MHz



Band66-3MHz-QPSK-132322-1RB#0-Range2:1000~20000MHz



Band66-3MHz-QPSK-132657-1RB#0-Range1:30~1000MHz



Band66-3MHz-QPSK-132657-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-3MHz-16QAM-131987-1RB#0-Range1:30~1000MHz



Band66-3MHz-16QAM-131987-1RB#0-Range2:1000~20000MHz



Band66-3MHz-16QAM-132322-1RB#0-Range1:30~1000MHz



Band66-3MHz-16QAM-132322-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-3MHz-16QAM-132657-1RB#0-Range1:30~1000MHz



Band66-3MHz-16QAM-132657-1RB#0-Range2:1000~20000MHz



Band66-5MHz-QPSK-131997-1RB#0-Range1:30~1000MHz



Band66-5MHz-QPSK-131997-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-5MHz-QPSK-132322-1RB#0-Range1:30~1000MHz



Band66-5MHz-QPSK-132322-1RB#0-Range2:1000~20000MHz



Band66-5MHz-QPSK-132647-1RB#0-Range1:30~1000MHz



Band66-5MHz-QPSK-132647-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-5MHz-16QAM-131997-1RB#0-Range1:30~1000MHz



Band66-5MHz-16QAM-131997-1RB#0-Range2:1000~20000MHz



Band66-5MHz-16QAM-132322-1RB#0-Range1:30~1000MHz



Band66-5MHz-16QAM-132322-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-5MHz-16QAM-132647-1RB#0-Range1:30~1000MHz



Band66-5MHz-16QAM-132647-1RB#0-Range2:1000~20000MHz



Band66-10MHz-QPSK-132022-1RB#0-Range1:30~1000MHz



Band66-10MHz-QPSK-132022-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-10MHz-QPSK-132322-1RB#0-Range1:30~1000MHz



Band66-10MHz-QPSK-132322-1RB#0-Range2:1000~20000MHz



Band66-10MHz-QPSK-132622-1RB#0-Range1:30~1000MHz



Band66-10MHz-QPSK-132622-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-10MHz-16QAM-132022-1RB#0-Range1:30~1000MHz



Band66-10MHz-16QAM-132022-1RB#0-Range2:1000~20000MHz



Band66-10MHz-16QAM-132322-1RB#0-Range1:30~1000MHz



Band66-10MHz-16QAM-132322-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-10MHz-16QAM-132622-1RB#0-Range1:30~1000MHz



Band66-10MHz-16QAM-132622-1RB#0-Range2:1000~20000MHz



Band66-15MHz-QPSK-132047-1RB#0-Range1:30~1000MHz



Band66-15MHz-QPSK-132047-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-15MHz-QPSK-132322-1RB#0-Range1:30~1000MHz



Band66-15MHz-QPSK-132322-1RB#0-Range2:1000~20000MHz



Band66-15MHz-QPSK-132597-1RB#0-Range1:30~1000MHz



Band66-15MHz-QPSK-132597-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-15MHz-16QAM-132047-1RB#0-Range1:30~1000MHz



Band66-15MHz-16QAM-132047-1RB#0-Range2:1000~20000MHz



Band66-15MHz-16QAM-132322-1RB#0-Range1:30~1000MHz



Band66-15MHz-16QAM-132322-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-15MHz-16QAM-132597-1RB#0-Range1:30~1000MHz



Band66-15MHz-16QAM-132597-1RB#0-Range2:1000~20000MHz



Band66-20MHz-QPSK-132072-1RB#0-Range1:30~1000MHz



Band66-20MHz-QPSK-132072-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-20MHz-QPSK-132322-1RB#0-Range1:30~1000MHz



Band66-20MHz-QPSK-132322-1RB#0-Range2:1000~20000MHz



Band66-20MHz-QPSK-132572-1RB#0-Range1:30~1000MHz



Band66-20MHz-QPSK-132572-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-20MHz-16QAM-132072-1RB#0-Range1:30~1000MHz



Band66-20MHz-16QAM-132072-1RB#0-Range2:1000~20000MHz



Band66-20MHz-16QAM-132322-1RB#0-Range1:30~1000MHz



Band66-20MHz-16QAM-132322-1RB#0-Range2:1000~20000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-20MHz-16QAM-132572-1RB#0-Range1:30~1000MHz



Band66-20MHz-16QAM-132572-1RB#0-Range2:1000~20000MHz



Band71-5MHz-QPSK-133147-1RB#0-Range1:30~1000MHz



Band71-5MHz-QPSK-133147-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band71-5MHz-QPSK-133297-1RB#0-Range1:30~1000MHz



Band71-5MHz-QPSK-133297-1RB#0-Range2:1000~10000MHz



Band71-5MHz-QPSK-133447-1RB#0-Range1:30~1000MHz



Band71-5MHz-QPSK-133447-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band71-5MHz-16QAM-133147-1RB#0-Range1:30~1000MHz



Band71-5MHz-16QAM-133147-1RB#0-Range2:1000~10000MHz



Band71-5MHz-16QAM-133297-1RB#0-Range1:30~1000MHz



Band71-5MHz-16QAM-133297-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band71-5MHz-16QAM-133447-1RB#0-Range1:30~1000MHz



Band71-5MHz-16QAM-133447-1RB#0-Range2:1000~10000MHz



Band71-10MHz-QPSK-133172-1RB#0-Range1:30~1000MHz



Band71-10MHz-QPSK-133172-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band71-10MHz-QPSK-133297-1RB#0-Range1:30~1000MHz



Band71-10MHz-QPSK-133297-1RB#0-Range2:1000~10000MHz



Band71-10MHz-QPSK-133422-1RB#0-Range1:30~1000MHz



Band71-10MHz-QPSK-133422-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band71-10MHz-16QAM-133172-1RB#0-Range1:30~1000MHz



Band71-10MHz-16QAM-133172-1RB#0-Range2:1000~10000MHz



Band71-10MHz-16QAM-133297-1RB#0-Range1:30~1000MHz



Band71-10MHz-16QAM-133297-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band71-10MHz-16QAM-133422-1RB#0-Range1:30~1000MHz



Band71-10MHz-16QAM-133422-1RB#0-Range2:1000~10000MHz



Band71-15MHz-QPSK-133197-1RB#0-Range1:30~1000MHz



Band71-15MHz-QPSK-133197-1RB#0-Range2:1000~10000MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch