


Band7-15MHz-QPSK-21100-75RB#0




Band7-15MHz-16QAM-21100-75RB#0




Band7-20MHz-QPSK-21100-100RB#0




Band7-20MHz-16QAM-21100-100RB#0




Band12-1.4MHz-QPSK-23095-6RB#0




Band12-1.4MHz-16QAM-23095-6RB#0


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*




Band12-3MHz-QPSK-23095-15RB#0




Band12-3MHz-16QAM-23095-15RB#0




Band12-5MHz-QPSK-23095-25RB#0




Band12-5MHz-16QAM-23095-25RB#0




Band12-10MHz-QPSK-23095-50RB#0




Band12-10MHz-16QAM-23095-50RB#0


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*




Band13-5MHz-QPSK-23230-25RB#0




Band13-5MHz-16QAM-23230-25RB#0




Band13-10MHz-QPSK-23230-50RB#0




Band13-10MHz-16QAM-23230-50RB#0




Band25-1.4MHz-QPSK-26365-6RB#0




Band25-1.4MHz-16QAM-26365-6RB#0


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*




Band25-3MHz-QPSK-26365-15RB#0




Band25-3MHz-16QAM-26365-15RB#0




Band25-5MHz-QPSK-26365-25RB#0




Band25-5MHz-16QAM-26365-25RB#0




Band25-10MHz-QPSK-26365-50RB#0




Band25-10MHz-16QAM-26365-50RB#0


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*




Band25-15MHz-QPSK-26365-75RB#0




Band25-15MHz-16QAM-26365-75RB#0




Band25-20MHz-QPSK-26365-100RB#0




Band25-20MHz-16QAM-26365-100RB#0








*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*

| Band26(814-824)-1.4MHz-QPSK-26740-6RB#0 | Band26(814-824)-1.4MHz-16QAM-26740-6RB#0 |
|---|---|
|   |   |
| Band26(814-824)-3MHz-QPSK-26740-15RB#0 | Band26(814-824)-3MHz-16QAM-26740-15RB#0 |
|   |   |
| Band26(814-824)-5MHz-QPSK-26740-25RB#0 | Band26(814-824)-5MHz-16QAM-26740-25RB#0 |


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*




Band26(814-824)-10MHz-QPSK-26740-50RB#0




Band26(814-824)-10MHz-16QAM-26740-50RB#0




Band26(824-849)-1.4MHz-QPSK-26915-6RB#0




Band26(824-849)-1.4MHz-16QAM-26915-6RB#0








*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*

| Band26(824-849)-3MHz-QPSK-26915-15RB#0 | Band26(824-849)-3MHz-16QAM-26915-15RB#0 |
|---|---|
|   |   |
| Band26(824-849)-5MHz-QPSK-26915-25RB#0 | Band26(824-849)-5MHz-16QAM-26915-25RB#0 |
|   |   |
| Band26(824-849)-10MHz-QPSK-26915-50RB#0 | Band26(824-849)-10MHz-16QAM-26915-50RB#0 |


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*




Band26(824-849)-15MHz-QPSK-26915-75RB#0




Band26(824-849)-15MHz-16QAM-26915-75RB#0




Band41-5MHz-QPSK-40620-25RB#0




Band41-5MHz-16QAM-40620-25RB#0








*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*

| Band41-10MHz-QPSK-40620-50RB#0 | Band41-10MHz-16QAM-40620-50RB#0 |
|---|---|
|  | |
| Band41-15MHz-QPSK-40620-75RB#0 | Band41-15MHz-16QAM-40620-75RB#0 |
|  |  |
| Band41-20MHz-QPSK-40620-100RB#0 | Band41-20MHz-16QAM-40620-100RB#0 |
|  |  |


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*

| Band66-1.4MHz-QPSK-132322-6RB#0 | Band66-1.4MHz-16QAM-132322-6RB#0 |
|---|---|
|  |  |
| Band66-3MHz-QPSK-132322-15RB#0 | Band66-3MHz-16QAM-132322-15RB#0 |
|  |  |
| Band66-5MHz-QPSK-132322-1RB#0 | Band66-5MHz-QPSK-132322-25RB#0 |
|  |  |


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch*