

Band26(824-849)-1.4MHz-QPSK-26797-1RB#0



Band26(824-849)-1.4MHz-QPSK-26797-6RB#0



Band26(824-849)-1.4MHz-QPSK-27033-1RB#5

Band26(824-849)-1.4MHz-QPSK-27033-6RB#0



Band26(824-849)-1.4MHz-16QAM-26797-1RB#0

Band26(824-849)-1.4MHz-16QAM-26797-6RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-1.4MHz-16QAM-27033-1RB#5



Band26(824-849)-1.4MHz-16QAM-27033-6RB#0



Band26(824-849)-3MHz-QPSK-26805-1RB#0

Band26(824-849)-3MHz-QPSK-26805-15RB#0

Band26(824-849)-3MHz-QPSK-27025-1RB#14

Band26(824-849)-3MHz-QPSK-27025-15RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-3MHz-16QAM-26805-1RB#0

Band26(824-849)-3MHz-16QAM-26805-15RB#0

Band26(824-849)-3MHz-16QAM-27025-1RB#14



Band26(824-849)-3MHz-16QAM-27025-15RB#0

Band26(824-849)-5MHz-QPSK-26815-1RB#0

Band26(824-849)-5MHz-QPSK-26815-25RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-5MHz-QPSK-27015-1RB#24



Band26(824-849)-5MHz-QPSK-27015-25RB#0

Band26(824-849)-5MHz-16QAM-26815-1RB#0

Band26(824-849)-5MHz-16QAM-26815-25RB#0

Band26(824-849)-5MHz-16QAM-27015-1RB#24

Band26(824-849)-5MHz-16QAM-27015-25RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch

Band26(824-849)-10MHz-QPSK-26840-1RB#0



Band26(824-849)-10MHz-QPSK-26840-50RB#0



Band26(824-849)-10MHz-16QAM-26840-1RB#0



Band26(824-849)-10MHz-16QAM-26840-50RB#0



Band26(824-849)-15MHz-QPSK-26865-1RB#0

Band26(824-849)-15MHz-QPSK-26865-75RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band26(824-849)-15MHz-16QAM-26865-1RB#0



Band26(824-849)-15MHz-16QAM-26865-75RB#0



Band41-5MHz-QPSK-39675-1RB#0



Band41-5MHz-QPSK-39675-25RB#0



Band41-5MHz-16QAM-39675-1RB#0



Band41-5MHz-16QAM-39675-25RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band41-10MHz-QPSK-39700-1RB#0



Band41-10MHz-QPSK-39700-50RB#0



Band41-10MHz-QPSK-41540-1RB#49



Band41-10MHz-QPSK-41540-50RB#0



Band41-10MHz-16QAM-39700-1RB#0

Band41-10MHz-16QAM-39700-50RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band41-10MHz-16QAM-41540-1RB#49



Band41-10MHz-16QAM-41540-50RB#0



Band41-15MHz-QPSK-39725-1RB#0

Band41-15MHz-16QAM-39725-1RB#0



Band41-20MHz-QPSK-39750-1RB#99

Band41-20MHz-QPSK-39750-100RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band41-20MHz-QPSK-41490-1RB#99

Band41-20MHz-QPSK-41490-100RB#0



Band41-20MHz-16QAM-39750-1RB#99

Band41-20MHz-16QAM-39750-100RB#0



Band41-20MHz-16QAM-41490-1RB#99

Band41-20MHz-16QAM-41490-100RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-1.4MHz-QPSK-131979-1RB#0



Band66-1.4MHz-QPSK-131979-6RB#0

Band66-1.4MHz-QPSK-132665-1RB#5



Band66-1.4MHz-QPSK-132665-6RB#0

Band66-1.4MHz-16QAM-131979-1RB#0

Band66-1.4MHz-16QAM-131979-6RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-1.4MHz-16QAM-132665-1RB#5



Band66-1.4MHz-16QAM-132665-6RB#0

Band66-3MHz-QPSK-131987-1RB#0

Band66-3MHz-QPSK-131987-15RB#0

Band66-3MHz-QPSK-132657-1RB#14

Band66-3MHz-QPSK-132657-15RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-3MHz-16QAM-131987-1RB#0

Band66-3MHz-16QAM-131987-15RB#0

Band66-3MHz-16QAM-132657-1RB#14



Band66-3MHz-16QAM-132657-15RB#0

Band66-5MHz-QPSK-131997-1RB#0

Band66-5MHz-QPSK-131997-25RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-5MHz-QPSK-132647-1RB#24



Band66-5MHz-QPSK-132647-25RB#0



Band66-5MHz-16QAM-131997-1RB#0

Band66-5MHz-16QAM-131997-25RB#0



Band66-5MHz-16QAM-132647-1RB#24



Band66-5MHz-16QAM-132647-25RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch



Band66-10MHz-QPSK-132022-1RB#0

Band66-10MHz-QPSK-132022-50RB#0

Band66-10MHz-QPSK-132622-1RB#49

Band66-10MHz-QPSK-132622-50RB#0

Band66-10MHz-16QAM-132022-1RB#0

Band66-10MHz-16QAM-132022-50RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch

Band66-10MHz-16QAM-132622-1RB#49

Band66-10MHz-16QAM-132622-50RB#0

Band66-15MHz-QPSK-132047-1RB#0

Band66-15MHz-QPSK-132047-75RB#0



Band66-15MHz-QPSK-132597-1RB#74



Band66-15MHz-QPSK-132597-75RB#0

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch