





































NTNV_N77-3450-
3550_PC2_30_10_H_TID14_NS_01_0.009_0.15_
#1




NTNV_N77-3450-
3550_PC2_30_10_H_TID14_NS_01_0.15_30_#1





NTNV_N77-3450-
3550_PC2_30_10_H_TID14_NS_01_30_1000_#1





NTNV_N77-3450-
3550_PC2_30_10_H_TID14_NS_01_1000_3000_
#1












































NTNV_N77-3450-
3550_PC2_30_15_L_TID7_NS_01_3000_6000_#
1



NTNV_N77-3450-
3550_PC2_30_15_L_TID7_NS_01_6000_26000_#
1



NTNV_N77-3450-
3550_PC2_30_15_L_TID7_NS_01_26000_40000_#
1



NTNV_N77-3450-
3550_PC2_30_15_L_TID8_NS_01_0.009_0.15_#
1

