

















NTNV_N77-3450-
3550_PC2_30_50_L_TID10_NS_01_0.009_0.15_
#1


NTNV_N77-3450-
3550_PC2_30_50_L_TID10_NS_01_0.15_30_#1





NTNV_N77-3450-
3550_PC2_30_50_L_TID10_NS_01_30_1000_#1


NTNV_N77-3450-
3550_PC2_30_50_L_TID10_NS_01_1000_3000_
#1























NTNV_N77-3450-
3550_PC2_30_50_L_TID15_NS_01_3000_6000_
_#1



NTNV_N77-3450-
3550_PC2_30_50_L_TID15_NS_01_6000_26000
_#1



NTNV_N77-3450-
3550_PC2_30_50_L_TID15_NS_01_26000_4000
0_#1



NTNV_N77-3450-
3550_PC2_30_50_M_TID1_NS_01_0.009_0.15_#
1

