








































NTNV_N77-3450-
3550_PC2_30_50_H_TID10_NS_01_3000_6000_
#1




NTNV_N77-3450-
3550_PC2_30_50_H_TID10_NS_01_6000_26000
_#1





NTNV_N77-3450-
3550_PC2_30_50_H_TID10_NS_01_26000_4000
0_#1





NTNV_N77-3450-
3550_PC2_30_50_H_TID11_NS_01_0.009_0.15_
#1

















NTNV_N77-3450-
3550_PC2_30_50_H_TID14_NS_01_0.009_0.15_
#1



NTNV_N77-3450-
3550_PC2_30_50_H_TID14_NS_01_0.15_30_#1



NTNV_N77-3450-
3550_PC2_30_50_H_TID14_NS_01_30_1000_#1



NTNV_N77-3450-
3550_PC2_30_50_H_TID14_NS_01_1000_3000_
#1

