










NTNV\_N77-3700-  
3980\_PC2\_30\_30\_M\_TID9\_NS\_01\_30\_1000\_#1




NTNV\_N77-3700-  
3980\_PC2\_30\_30\_M\_TID9\_NS\_01\_1000\_6000\_#  
1





NTNV\_N77-3700-  
3980\_PC2\_30\_30\_M\_TID9\_NS\_01\_6000\_26000\_  
#1





NTNV\_N77-3700-  
3980\_PC2\_30\_30\_M\_TID9\_NS\_01\_26000\_40000  
#1





























NTNV\_N77-3700-  
3980\_PC2\_30\_30\_H\_TID1\_NS\_01\_0.009\_0.15\_#  
1



NTNV\_N77-3700-  
3980\_PC2\_30\_30\_H\_TID1\_NS\_01\_0.15\_30\_#1



NTNV\_N77-3700-  
3980\_PC2\_30\_30\_H\_TID1\_NS\_01\_30\_1000\_#1



NTNV\_N77-3700-  
3980\_PC2\_30\_30\_H\_TID1\_NS\_01\_1000\_6000\_#  
1

