




10MHz_Middle_QPSK_50@0(30MHz~1GHz)




10MHz_Middle_QPSK_50@0(1GHz~20.1GHz)




10MHz_High_QPSK_1@0(30MHz~1GHz)




10MHz_High_QPSK_1@0(1GHz~20.1GHz)




10MHz_High_QPSK_50@0(30MHz~1GHz)



10MHz_High_QPSK_50@0(1GHz~20.1GHz)




15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:06:38

15MHz_Low_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:06:51

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:07:17

15MHz_Low_QPSK_75@0(1GHz~20.1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:07:30

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:07:56

15MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:08:08


15MHz_Middle_QPSK_75@0(30MHz~1GHz)




15MHz_Middle_QPSK_75@0(1GHz~20.1GHz)




15MHz_High_QPSK_1@0(30MHz~1GHz)




15MHz_High_QPSK_1@0(1GHz~20.1GHz)




15MHz_High_QPSK_75@0(30MHz~1GHz)




15MHz_High_QPSK_75@0(1GHz~20.1GHz)




20MHz_Low_QPSK_1@0(30MHz~1GHz)




20MHz_Low_QPSK_1@0(1GHz~20.1GHz)




20MHz_Low_QPSK_100@0(30MHz~1GHz)




20MHz_Low_QPSK_100@0(1GHz~20.1GHz)




20MHz_Middle_QPSK_1@0(30MHz~1GHz)




20MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




20MHz_Middle_QPSK_100@0(30MHz~1GHz)




20MHz_Middle_QPSK_100@0(1GHz~20.1GHz)




20MHz_High_QPSK_1@0(30MHz~1GHz)




20MHz_High_QPSK_1@0(1GHz~20.1GHz)



20MHz_High_QPSK_100@0(30MHz~1GHz)




20MHz_High_QPSK_100@0(1GHz~20.1GHz)




FCC Part 27

LTE Band 4, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




1.4MHz_Low_QPSK_1@0(1GHz~18.55GHz)




1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




1.4MHz_Low_QPSK_6@0(1GHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)



1.4MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:20:32

1.4MHz_Middle_QPSK_6@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:20:46

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:21:17

1.4MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:21:33

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:22:03

1.4MHz_High_QPSK_6@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:22:16

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:22:49

3MHz_Low_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:23:02

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:23:32

3MHz_Low_QPSK_15@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:23:45

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:24:16

3MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:24:30


3MHz_Middle_QPSK_15@0(30MHz~1GHz)




3MHz_Middle_QPSK_15@0(1GHz~18.55GHz)




3MHz_High_QPSK_1@0(30MHz~1GHz)




3MHz_High_QPSK_1@0(1GHz~18.55GHz)




3MHz_High_QPSK_15@0(30MHz~1GHz)




3MHz_High_QPSK_15@0(1GHz~18.55GHz)




5MHz_Low_QPSK_1@0(30MHz~1GHz)




5MHz_Low_QPSK_1@0(1GHz~18.55GHz)




5MHz_Low_QPSK_25@0(30MHz~1GHz)




5MHz_Low_QPSK_25@0(1GHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~1GHz)




5MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




5MHz_Middle_QPSK_25@0(30MHz~1GHz)




5MHz_Middle_QPSK_25@0(1GHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




5MHz_High_QPSK_1@0(1GHz~18.55GHz)




5MHz_High_QPSK_25@0(30MHz~1GHz)




5MHz_High_QPSK_25@0(1GHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~1GHz)




10MHz_Low_QPSK_1@0(1GHz~18.55GHz)




10MHz_Low_QPSK_50@0(30MHz~1GHz)




10MHz_Low_QPSK_50@0(1GHz~18.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~1GHz)




10MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




10MHz_Middle_QPSK_50@0(30MHz~1GHz)




10MHz_Middle_QPSK_50@0(1GHz~18.55GHz)




10MHz_High_QPSK_1@0(30MHz~1GHz)




10MHz_High_QPSK_1@0(1GHz~18.55GHz)




10MHz_High_QPSK_50@0(30MHz~1GHz)




10MHz_High_QPSK_50@0(1GHz~18.55GHz)




15MHz_Low_QPSK_1@0(30MHz~1GHz)




15MHz_Low_QPSK_1@0(1GHz~18.55GHz)




15MHz_Low_QPSK_75@0(30MHz~1GHz)




15MHz_Low_QPSK_75@0(1GHz~18.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~1GHz)




15MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




15MHz_Middle_QPSK_75@0(30MHz~1GHz)




15MHz_Middle_QPSK_75@0(1GHz~18.55GHz)




15MHz_High_QPSK_1@0(30MHz~1GHz)




15MHz_High_QPSK_1@0(1GHz~18.55GHz)




15MHz_High_QPSK_75@0(30MHz~1GHz)




15MHz_High_QPSK_75@0(1GHz~18.55GHz)




20MHz_Low_QPSK_1@0(30MHz~1GHz)




20MHz_Low_QPSK_1@0(1GHz~18.55GHz)




20MHz_Low_QPSK_100@0(30MHz~1GHz)




20MHz_Low_QPSK_100@0(1GHz~18.55GHz)




20MHz_Middle_QPSK_1@0(30MHz~1GHz)



20MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




20MHz_Middle_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:45:31

20MHz_Middle_QPSK_100@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:45:46

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:46:21

20MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:46:36

20MHz_High_QPSK_100@0(30MHz~1GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:47:12

20MHz_High_QPSK_100@0(1GHz~18.55GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 11:47:27

LTE Band 12, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:16:15

1.4MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:16:28

1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:17:10

1.4MHz_Low_QPSK_6@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:17:24

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:18:06

1.4MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:18:20

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:19:01

1.4MHz_Middle_QPSK_6@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:19:15

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:19:56

1.4MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:20:11

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:20:53

1.4MHz_High_QPSK_6@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:21:07

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:21:53

3MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:22:09

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:22:59

3MHz_Low_QPSK_15@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:23:15

3MHz_Middle_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:23:58

3MHz_Middle_QPSK_1@0(1GHz~8.16GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:24:14