



3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:25:00

3MHz_Middle_QPSK_15@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:25:14

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:26:01

3MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:26:15

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:26:57

3MHz_High_QPSK_15@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:27:11

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:28:42

5MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:28:56

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:29:40

5MHz_Low_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:29:54

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:30:39

5MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:30:53

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:31:39

5MHz_Middle_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:31:54

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:32:38

5MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:32:52

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:33:37

5MHz_High_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:33:52

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:35:32

10MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:35:46

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:36:30

10MHz_Low_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:36:45

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:37:31

10MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:37:45

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:38:31

10MHz_Middle_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:38:46

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:39:34

10MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:39:49

10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:40:36

10MHz_High_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 13:40:52

LTE Band 13, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:18:27

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:18:40

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:18:47

5MHz_Low_QPSK_1@0(1GHz~8.87GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:18:34

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:18:52

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:19:13


5MHz_Low_QPSK_25@0(763MHz~775MHz)




5MHz_Low_QPSK_25@0(793MHz~806MHz)




5MHz_Low_QPSK_25@0(1GHz~8.87GHz)




5MHz_Low_QPSK_25@0(1559MHz~1610MHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)



5MHz_High_QPSK_1@0(763MHz~775MHz)




5MHz_High_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:20:20

5MHz_High_QPSK_1@0(1GHz~8.87GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:20:09

5MHz_High_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 11.JUN.2025 16:35:47

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:20:47

5MHz_High_QPSK_25@0(763MHz~775MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:21:02

5MHz_High_QPSK_25@0(793MHz~806MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:21:08


5MHz_High_QPSK_25@0(1GHz~8.87GHz)




5MHz_High_QPSK_25@0(1559MHz~1610MHz)




10MHz_Middle_QPSK_1@0(30MHz~1GHz)




10MHz_Middle_QPSK_1@0(763MHz~775MHz)




10MHz_Middle_QPSK_1@0(793MHz~806MHz)



10MHz_Middle_QPSK_1@0(1GHz~8.87GHz)




10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:23:02

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:23:23

10MHz_Middle_QPSK_50@0(763MHz~775MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:23:38

10MHz_Middle_QPSK_50@0(793MHz~806MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:23:44

10MHz_Middle_QPSK_50@0(1GHz~8.87GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:23:31

10MHz_Middle_QPSK_50@0(1559MHz~1610MHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:23:50

LTE Band 17, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:24:28

5MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:24:37

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:24:58

5MHz_Low_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:25:05

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:25:26

5MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:25:33

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:25:53

5MHz_Middle_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:26:00

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:26:21

5MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:26:28

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:26:49

5MHz_High_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:26:56

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:27:19

10MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:27:26

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:46:12

10MHz_Low_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:46:19

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:46:43

10MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 17:46:50


10MHz_Middle_QPSK_50@0(30MHz~1GHz)




10MHz_Middle_QPSK_50@0(1GHz~8.16GHz)




10MHz_High_QPSK_1@0(30MHz~1GHz)




10MHz_High_QPSK_1@0(1GHz~8.16GHz)



10MHz_High_QPSK_50@0(30MHz~1GHz)




10MHz_High_QPSK_50@0(1GHz~8.16GHz)



LTE Band 66, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 16:36:27

1.4MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 16:36:38

1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 18:58:04

1.4MHz_Low_QPSK_6@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 18:58:14

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 18:59:42

1.4MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 18:59:52

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:00:13

1.4MHz_Middle_QPSK_6@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:00:23

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:00:44

1.4MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:00:54

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:01:17

1.4MHz_High_QPSK_6@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:01:48

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:02:13

3MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:02:25

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:02:48

3MHz_Low_QPSK_15@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:02:58

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:03:21

3MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:03:31


3MHz_Middle_QPSK_15@0(30MHz~1GHz)




3MHz_Middle_QPSK_15@0(1GHz~18.8GHz)




3MHz_High_QPSK_1@0(30MHz~1GHz)




3MHz_High_QPSK_1@0(1GHz~18.8GHz)




3MHz_High_QPSK_15@0(30MHz~1GHz)



3MHz_High_QPSK_15@0(1GHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:05:37

5MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:05:48

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:07:01

5MHz_Low_QPSK_25@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:07:24

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:08:50

5MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:09:54

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:10:19

5MHz_Middle_QPSK_25@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:10:29

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:10:53

5MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:11:04

5MHz_High_QPSK_25@0(30MHz~1GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:11:28

5MHz_High_QPSK_25@0(1GHz~18.8GHz)



ProjectNo.:2504S54165E-RF Tester:Len Lin
Date: 8.MAY.2025 19:11:39