

Date: 2022-04-24

Declaration Letter about Limited Use

To whom it may concern,
WE (Hangzhou Hikvision Digital Technology Co., Ltd.) HEREBY DECLARED THAT

Our product

Product Description:	Interactive Tablets
----------------------	---------------------


Model No:	DS-D5B86RB/A ; DS-D5B86RB/B ; DS-D5B86RB/C ; DS-D5B86RD/A ; DS-D5B86RD/B ; DS-D5B86RD/C ; DS-D5B86RO/A ; DS-D5B86RO/B ; DS-D5B86RO/C ; DS-D5B86RG/A ; DS-D5B86RG/B ; DS-D5B86RG/C ; DS-D5B86RM/A ; DS-D5B86RM/B ; DS-D5B86RM/C ; DS-D5B86JRX ; DS-D5B86JRY ; DS-D5B86JRZ ; DS-D5B86NYX ; DS-D5B86NYY ; DS-D5B86NYZ ; DS-D5B86ZFX ; DS-D5B86ZFY ; DS-D5B86ZFZ ; DS-D5B86GAX ; DS-D5B86GAY ; DS-D5B86GAZ ; DS-D5B86DCX ; DS-D5B86DCY ; DS-D5B86DCZ ; DS-D5B86RB/ZC;DS-D5B86RD/ZC;DS-D5B86XX/ZC;DS-D5B86RD/AO ; DS-D5B86RD/AP ; DS-D5B86RB/AO ; DS-D5B86RB/AP ; DS-D5B86RD/BO ; DS-D5B86RD/BP ; DS-D5B86RB/BO ; DS-D5B86RB/BP ; DS-D5B86MD/AO ; DS-D5B86MD/AP ; DS-D5B86MB/AO ; DS-D5B86MB/AP ; DS-D5B86MD/BO ; DS-D5B86MD/BP ; DS-D5B86MB/BO ; DS-D5B86MB/BP ; DS-D5B86CD/AO ; DS-D5B86CD/AP ; DS-D5B86CB/AO ; DS-D5B86CB/AP ; DS-D5B86CD/BO ; DS-D5B86CD/BP ; DS-D5B86CB/BO ; DS-D5B86CB/BP ; DS-D5B86FD/AO ; DS-D5B86FD/AP ; DS-D5B86FB/AO ; DS-D5B86FB/AP ; DS-D5B86FD/A ; DS-D5B86FB/A ; DS-D5B86FD/BO ; DS-D5B86FD/BP ; DS-D5B86FB/BO ; DS-D5B86FB/BP ; DS-D5B86FD/B ; DS-D5B86FB/B ; DS-D5C86RB/A ; DS-D5C86RB/B ; DS-D5C86RB/C ; DS-D5C86RD/A ; DS-D5C86RD/B ; DS-D5C86RD/C ; DS-D5C86RO/A ; DS-D5C86RO/B ; DS-D5C86RO/C ; DS-D5C86RG/A ; DS-D5C86RG/B ; DS-D5C86RG/C ; DS-D5C86RM/A ; DS-D5C86RM/B ; DS-D5C86RM/C ; DS-D5C86JRX ; DS-D5C86JRY ; DS-D5C86JRZ ; DS-D5C86NYX ; DS-D5C86NYY ; DS-D5C86NYZ ; DS-D5C86ZFX ; DS-D5C86ZFY ; DS-D5C86ZFZ ; DS-D5C86GAX ; DS-D5C86GAY ; DS-D5C86GAZ ; DS-D5C86DCX ; DS-D5C86DCY ; DS-D5C86DCZ ; DS-D5C86RB/ZC;DS-D5C86RD/ZC;DS-D5C86XX/ZC;DS-D5C86RD/AO ; DS-D5C86RD/AP ; DS-D5C86RB/AO ; DS-D5C86RB/AP ; DS-D5C86RD/BO ; DS-D5C86RD/BP ; DS-D5C86RB/BO ; DS-D5C86RB/BP ; DS-D5C86MD/AO ; DS-D5C86MD/AP ; DS-D5C86MB/AO ; DS-D5C86MB/AP ; DS-D5C86MD/BO ; DS-D5C86MD/BP ; DS-D5C86MB/BO ; DS-D5C86MB/BP ; DS-D5C86CD/AO ; DS-D5C86CD/AP ; DS-D5C86CB/AO ; DS-D5C86CB/AP ; DS-D5C86CD/BO ; DS-D5C86CD/BP ; DS-D5C86CB/BO ; DS-D5C86CB/BP ; DS-D5C86FD/AO ; DS-D5C86FD/AP ; DS-D5C86FB/AO ; DS-D5C86FB/AP ; DS-D5C86FD/A ; DS-D5C86FB/A ; DS-D5C86FD/BO ; DS-D5C86FD/BP ; DS-D5C86FB/BO ; DS-
-----------	--

	D5C86FB/BP ; DS-D5C86FD/B ; DS-D5C86FB/B ; DS-D5D86RB/A ; DS-D5D86RB/B ; DS-D5D86RB/C ; DS-D5D86RD/A ; DS- D5D86RD/B ; DS-D5D86RD/C ; DS-D5D86RO/A ; DS-D5D86RO/B ; DS-D5D86RO/C ; DS-D5D86RG/A ; DS-D5D86RG/B ; DS- D5D86RG/C ; DS-D5D86RM/A ; DS-D5D86RM/B ; DS- D5D86RM/C ; DS-D5D86JRX ; DS-D5D86JRY ; DS-D5D86JRZ ; DS- D5D86NYX ; DS-D5D86NYY ; DS-D5D86NYZ ; DS-D5D86ZFX ; DS- D5D86ZFY ; DS-D5D86ZFZ ; DS-D5D86GAX ; DS-D5D86GAY ; DS- D5D86GAZ ; DS-D5D86DCX ; DS-D5D86DCY ; DS-D5D86DCZ ; DS-D5D86RB/ZC;DS-D5D86RD/ZC;DS-D5D86XX/ZC;DS- D5D86RD/AO ; DS-D5D86RD/AP ; DS-D5D86RB/AO ; DS- D5D86RB/AP ; DS-D5D86RD/BO ; DS-D5D86RD/BP ; DS- D5D86RB/BO ; DS-D5D86RB/BP ; DS-D5D86MD/AO ; DS- D5D86MD/AP ; DS-D5D86MB/AO ; DS-D5D86MB/AP ; DS- D5D86MD/BO ; DS-D5D86MD/BP ; DS-D5D86MB/BO ; DS- D5D86MB/BP ; DS-D5D86CD/AO ; DS-D5D86CD/AP ; DS- D5D86CB/AO ; DS-D5D86CB/AP ; DS-D5D86CD/BO ; DS- D5D86CD/BP ; DS-D5D86CB/BO ; DS-D5D86CB/BP ; DS- D5D86FD/AO ; DS-D5D86FD/AP ; DS-D5D86FB/AO ; DS- D5D86FB/AP ; DS-D5D86FD/A ; DS-D5D86FB/A ; DS- D5D86FD/BO ; DS-D5D86FD/BP ; DS-D5D86FB/BO ; DS- D5D86FB/BP ; DS-D5D86FD/B ; DS-D5D86FB/B ; DS-D5F86RB/A ; DS-D5F86RB/B ; DS-D5F86RB/C ; DS-D5F86RD/A ; DS- D5F86RD/B ; DS-D5F86RD/C ; DS-D5F86RO/A ; DS-D5F86RO/B ; DS-D5F86RO/C ; DS-D5F86RG/A ; DS-D5F86RG/B ; DS- D5F86RG/C ; DS-D5F86RM/A ; DS-D5F86RM/B ; DS-D5F86RM/C ; DS-D5F86JRX ; DS-D5F86JRY ; DS-D5F86JRZ ; DS-D5F86NYX ; DS-D5F86NYY ; DS-D5F86NYZ ; DS-D5F86ZFX ; DS-D5F86ZFY ; DS-D5F86ZFZ ; DS-D5F86GAX ; DS-D5F86GAY ; DS-D5F86GAZ ; DS-D5F86DCX ; DS-D5F86DCY ; DS-D5F86DCZ ; DS- D5F86RB/ZC;DS-D5F86RD/ZC;DS-D5F86XX/ZC;DS-D5F86RD/AO ; DS-D5F86RD/AP ; DS-D5F86RB/AO ; DS-D5F86RB/AP ; DS- D5F86RD/BO ; DS-D5F86RD/BP ; DS-D5F86RB/BO ; DS- D5F86RB/BP ; DS-D5F86MD/AO ; DS-D5F86MD/AP ; DS- D5F86MB/AO ; DS-D5F86MB/AP ; DS-D5F86MD/BO ; DS- D5F86MD/BP ; DS-D5F86MB/BO ; DS-D5F86MB/BP ; DS- D5F86CD/AO ; DS-D5F86CD/AP ; DS-D5F86CB/AO ; DS- D5F86CB/AP ; DS-D5F86CD/BO ; DS-D5F86CD/BP ; DS- D5F86CB/BO ; DS-D5F86CB/BP ; DS-D5F86FD/AO ; DS- D5F86FD/AP ; DS-D5F86FB/AO ; DS-D5F86FB/AP ; DS- D5F86FD/A ; DS-D5F86FB/A ; DS-D5F86FD/BO ; DS-
--	---

	D5F86FD/BP ; DS-D5F86FB/BO ; DS-D5F86FB/BP ; DS-D5F86FD/B ; DS-D5F86FB/B ; DS-D5A86RB/A ; DS-D5A86RB/B ; DS-D5A86RB/C ; DS-D5A86RD/A ; DS-D5A86RD/B ; DS-D5A86RD/C ; DS-D5A86RO/A ; DS-D5A86RO/B ; DS-D5A86RO/C ; DS-D5A86RG/A ; DS-D5A86RG/B ; DS-D5A86RG/C ; DS-D5A86RM/A ; DS-D5A86RM/B ; DS-D5A86RM/C ; DS-D5A86JRX ; DS-D5A86JRY ; DS-D5A86JRZ ; DS-D5A86NYX ; DS-D5A86NYY ; DS-D5A86NYZ ; DS-D5A86ZFX ; DS-D5A86ZFY ; DS-D5A86ZFZ ; DS-D5A86GAX ; DS-D5A86GAY ; DS-D5A86GAZ ; DS-D5A86DCX ; DS-D5A86DCY ; DS-D5A86DCZ ; DS-D5A86RB/ZC;DS-D5A86RD/ZC;DS-D5A86XX/ZC;DS-D5A86RD/AO ; DS-D5A86RD/AP ; DS-D5A86RB/AO ; DS-D5A86RB/AP ; DS-D5A86RD/BO ; DS-D5A86RD/BP ; DS-D5A86RB/BO ; DS-D5A86RB/BP ; DS-D5A86MD/AO ; DS-D5A86MD/AP ; DS-D5A86MB/AO ; DS-D5A86MB/AP ; DS-D5A86MD/BO ; DS-D5A86MD/BP ; DS-D5A86MB/BO ; DS-D5A86MB/BP ; DS-D5A86CD/AO ; DS-D5A86CD/AP ; DS-D5A86CB/AO ; DS-D5A86CB/AP ; DS-D5A86CD/BO ; DS-D5A86CD/BP ; DS-D5A86CB/BO ; DS-D5A86CB/BP ; DS-D5A86FD/AO ; DS-D5A86FD/AP ; DS-D5A86FB/AO ; DS-D5A86FB/AP ; DS-D5A86FD/A ; DS-D5A86FB/A ; DS-D5A86FD/BO ; DS-D5A86FD/BP ; DS-D5A86FB/BO ; DS-D5A86FB/BP ; DS-D5A86FD/B ; DS-D5A86FB/B ; DS-D5X86XX/X ; DS-D5X86XX/XX ; DS-D5XXXXXX/XXX ; DS-D5XXXXXX/XXXX("X" stands for A-Z, 0-9 or blank)
HVIN:	DS-D5B65RB/A DS-D5B65RB/B
FCC ID:	2ADTD-DS-D5B86
IC:	20199-DSD5B86

The product contains the one RTL8812CU module , it can support BT,2.4G WiFi and 5G WiFi function, However, the export to the U.S. and Canada market , the BT function is disabled. Any problems caused by such restrictions shall be borne by our company.

Printed Name : Long Cheng

Signature: 

Title: Testing & Certification Engineer

On behalf of Company : Hangzhou Hikvision Digital Technology Co., Ltd.

Telephone: +8618969187825