

AcSiP Technology Corporation
3F,-1 No.207, Fusing Rd., Taoyuan City, Taoyuan County 33066,
Taiwan

Date: December 30, 2014

Subject: Ad Hoc Mode Function Declaration

To Whom it may concern,

We, **AcSiP Technology Corporation** declare that the device does not support any non-US channels and country code selection in all the operational mode(s) for the following product.

FCC ID: **2ADWC-AI7681H**

Regards,

A handwritten signature in black ink, appearing to read 'Sam Hus', is written over a horizontal dashed line.

Sam Hus / Director

AcSiP Technology Corporation

TEL.: +886 3 286 8388

FAX: +886 3 347 5000

E-mail: samhsu@acsip.com.tw